

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21012684/DEA3Q2**Date:** 07/07/2022**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MCV0007360
Claimant Vehicle No : FBN9351E **Insured Vehicle No :** GBD3416U
 Date of Loss: 05/12/2021 Nature of Claim: TP Claim No: MCV2021D0005460

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBN9351E**
 Make & Model: HONDA FS150F, 149cc Engine No: KC27E2208037
 Reg. Date: 03/01/2019 (Man. Year: 2018) Chassis No: PMKKC27A0KB203159
 Colour: Orange/Black Odometer: 0 km
 Engine Capacity: 149 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 90/80 R17 Rear Tyre Size: 120/70 R17
 Front Left Side: Pirelli 2 mm Rear Left Side: Pirelli 2 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,504.20	1,972.20	1,532.00	43.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	680.00	230.00	450.00	66.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,184.20	2,202.20	1,982.00	47.37
Approved Total (Overridden) (S\$)		1,750.00		
Nett Amount (S\$)	4,184.20	1,750.00	2,434.20	58.18
+ Loss of Use (4.0 x S\$25.00/day) (S\$)		100.00		
Nett Liability (S\$)		1,850.00		

INSPECTION

Date of Assignment: 13/12/2021
 Date Inspected: 14/12/2021 Inspected At: Sg 98 Motor Pte Ltd (HQ)
 BLK 4001 ANG MO KIO INDUSTRIAL PARK 1
 #01-21
 Singapore 569622
 Estimated Period of Repair: 4.0 days

Adjuster: BRYAN TANI**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 22 Jun 2022)	
Parts:	N/A	HONDA FS150F 149cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBN9351E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Serviceable	130.00 FL	*- FL
2	1		*HEAD LAMP	Cut	180.00 FL	*180.00 FL
3	1		*HEAD LAMP COVER	Cut	80.00 FL	*80.00 FL
4	1		*METER COVER	Cut	70.00 FL	*70.00 FL
5	1		*SET MIRROR	Ns Distorted/Broken/Os Cut	120.00 FL	*120.00 FL
6	1		*CENTRE HEAD PANEL	Cut	135.00 FL	*135.00 FL
7	1		*CENTRE INNER PANEL	Cut	135.00 FL	*135.00 FL
8	1		*FRONT RH SIGNAL	Cut	80.00 FL	*80.00 FL
9	1		*FRONT MUDGUARD	Cut/Broken	150.00 FL	*150.00 FL
10	1		*SET FORK TUBE	Repair	580.00 FL	*- FL
11	1		*FORK UNDER BRACKET	Not Necessary	380.00 FL	*- FL
12	1		*FRONT RH SIDE PANEL	Cut	160.00 FL	*160.00 FL
13	1		*BRAKE LEVER	Cut	70.00 FL	*70.00 FL
14	1		*BRAKE DISC	Not Necessary	290.00 FL	*- FL
15	1		*FRONT FOOT REST RH	Bent/Cut	58.00 FL	*58.00 FL
16	1		*FOOT REST BRACKET RH	Bent	125.00 FL	*125.00 FL
17	1		*EXHAUST GUARD-BLACK	Cut	180.00 FL	*180.00 FL
18	1		*EXHAUST NOZZLE	Cut	130.00 FL	*130.00 FL
19	1		*REAR RH TAIL SIDE PANEL	Cut/Mounting Broken	220.00 FL	*220.00 FL
20	1		*CLUTCH LEVER LH	Broken	65.00 FL	*65.00 FL
21	1		*REAR BOX	Cut	320.00 FS	*150.00 FS
22	1		*BODY STICKER	Necessary	180.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,838.00	2,168.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	333.80	195.80
Total Parts (\$\$)	3,504.20	1,972.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REPLACE PARTS,ALIGN & ETC	New	280.00	150.00
2	REMOVE & REPLACE FORK TUBE,OIL SEAL & TOP UP FORK OIL	New	120.00	80.00
3	REPRESS FRONT RIM	New	280.00	0.00
Gross Labour Cost (\$)			680.00	230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >