

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

NOTE (Usum)

Date: 13.12.2021 Juman
Time: 15:30:52
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305497815
REGN NO : SHC7442B
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 15.12.2017
DATE/TIME IN : 11.12.2021 19:00
ACCIDENT DATE : 11.12.2021

LKK Auto Centre will notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-2322-A	BUMPER FRT COVER+	1	1,052.20	20.00	841.76	de
0002 04-01-0103-0782-A	LAMP ASSY-HEAD RH#	1	1,388.00	20.00	1,110.40	one
0003 04-01-0103-0573-A	PANEL-FENDER RH+	1	663.00	20.00	530.40	de
0004 04-01-0103-0640-G	BRACKET-FR BUMPER SIDE RH	1	44.80	20.00	35.84	de
0005 04-01-0103-0641-G	CARRIER ASSY-FR END MODUL	1	907.40	20.00	725.92	one
0006 04-01-0103-0572-G	PANEL ASSY-HOOD#	1	2,265.90	20.00	1,812.72	km
0007 04-01-0101-0111-G	BUMPER COVER CLIP	10	22.00	20.00	17.60	one

4077-40
3261.92

SUB-TOTAL : 5,074.64

JOB NATURE

0000 PB	PANEL BEATING	900.00	560
0001 SP	SPRAYPAINT CHARGE	800.00	500
0002 17-01	CHECK ALL LIGHTING	50.00	30
0003 20-00	TUFF COAT ON AFFECTED PARTS.	50.00	30 1120

3261.92
1120
4381.92
4381.92
03 days

Tanpin 97495747
UP 13/12/21 430pm
LBS Runy after repair
Tanpin 13/12/21 430pm
03 days