

NTM(-LL/Sum)

COMFORTDELGRO ENGINEERING PTE LTD

Date: 13.12.2021

Juman

REPAIR ESTIMATE

Time: 08:34:27

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305497564
REGN NO : SH 8612P
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 24.11.2016
DATE/TIME IN : 10.12.2021 17:00
ACCIDENT DATE : 10.12.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0574-G	PANEL-FENDER LH#	1	663.00	20.00	530.40	bt	
0002 04-01-0103-0593-G	PANEL ASSY-FR DR LH#	1	2,256.40	20.00	1,805.12	bb	3136.62
0003 04-01-0103-0658-G	CAP ASSY-WHEEL HUB	1	217.20	20.00	173.76	de	201-2509.28
0004 28-01-0103-0003-A	FRT DOOR LOGO CTPL	1 N	75.00	10.00	67.50	nei	75 16 07.50

SUB-TOTAL : 2,576.78

JOB NATURE

2576.78

0000 PB	PANEL BEATING	600.00	525
0001 SP	SPRAYPAINT CHARGE	600.00	500
0002 20-00	TUFF COAT ON AFFECTED PARTS.	50.00	30
0003 L	TRANSFER DOOR PART	120.00	60
0004 20-05	RENEW ADVERTISMENT STICKER-FENDER	100.00	nei
0005 20-05	RENEW ADVERTISMENT STICKER-DOOR	100.00	nei 1315

SUB-TOTAL : 1,570.00

3891.78

4/5 \$3100

* 3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is of a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Tanphui 27495719
WP' 13/12/21 @ 3:45
4/5 Resurvey after repair
Tanphui @ 1st time
2 (Sobys)