

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way  
#09-16  
Singapore 079120

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Hor, Yinrul

Date: 16 Dec 2021

**Preliminary Advice**

Vehicle No	: SLV3579U	Accident Date	: 14/12/2021
Make	: KIA CARENS	Policy No.	: 1700091333
Assignment Date	: 15/12/2021	Excess	: S\$0.00
Date of Inspection	: 16/12/2021	Est. Duration of Repair	: 6
Inspection At	: CYCLE & CARRIAGE KIA PTE LTD		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,655.60
Revised Amount	:S\$	5,446.40
Check Items (Estimated)	:S\$	950.40
Total	:S\$	6,396.80

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	70,000.00
COE / PARF Rebate	:S\$	43,539.00
Salvage Value	:S\$	
Margin for Repair	:S\$	26,461.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .