

CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X


Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/Seem Kok Seng
	Reg No/Reg Date	SLV3579U / 28/12/201
	Date In/Mileage	16/12/2021/ 0
	Chassis No	KNAHU815VJ7193822
	Engine No	D4FDHH546890
	Make/Model	KIA/CARENS 1.7 A D EX FL DY7
	Colour/Trim	IM TITANIUM SILVER/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	15/12/2021/ 11:42	BLK	282 / Kevin Leong	43990			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000		REPLACE REAR BUMPER, TAILGATE, END PANEL & AFFECTED AREA		2-5 X 400				1000 2000.00
		REPAIR ON REAR RH FENDER						
E PNT98000		PAINT WORK ON REAR BUMPER, TAILGATE, END PANEL & REAR RH FENDER		3 X 350				1050 1400.00
E PNT88000		REMOVE & RELACE REAR PARKING ASSITS FOR FACILITIES REPAIR						80.00
E PNT88000		REMOVE & INSTALL REAR WINDSCREEN GLASS FOR FACILITATE REPAIR						240.00
M SUNDRY		TO APPLY WINDSCREE SEALANT						80.00
E PNT88000		TO TRANSFER REAR BOOT ATTACHEMENTS TO NEW PANEL						120 192.00
E PNT88000		TO REMOVE & INSTALL REAR COMPARTMENT FOR FACILITATE REPAIR						120.00
M SUNDRY		TO PERFORM RUST PREVENTION						40 120.00
M SUNDRY		TO APPLY SEALANT ON AFFECTED AREA						80.00
A 54900099		TO CHECK WIRING & CHASSIS ELECTRICAL SYSTEM						30.00
A 10028901		TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM						120 192.00
M SUNDRY		TO SUPPLY C&C EMBLEM						40.00
M SUNDRY		SUNDRIES						70 40.00
M LAMP ASSY-REAR COMBINATION, RH					1.00	357.00	20.00	285.60
M PANEL ASSY-TAIL GATE					1.00	1218.00	20.00	974.40
M TRIM-TRANSVERSE RR					1.00	71.00	20.00	56.80
M W/STRIP-TAIL GATE OPNG					1.00	131.00	20.00	104.80
M LATCH ASSY-TAIL GATE					1.00	109.00	20.00	87.20
M EMBLEM-CARENS					1.00	36.00	20.00	28.80

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	<table> <tr> <td>Cust No/Name</td><td>/Seem Kok Seng</td></tr> <tr> <td>Reg No/Reg Date</td><td>SLV3579U / 28/12/201</td></tr> <tr> <td>Date In/Mileage</td><td>16/12/2021/ 0</td></tr> <tr> <td>Chassis No</td><td>KNAHU815VJ7193822</td></tr> <tr> <td>Engine No</td><td>D4FDHH546890</td></tr> <tr> <td>Make/Model</td><td>KIA/CARENS 1.7 A D EX FL DY7</td></tr> <tr> <td>Colour/Trim</td><td>IM TITANIUM SILVER/ WK SATURN BLACK</td></tr> </table>	Cust No/Name	/Seem Kok Seng	Reg No/Reg Date	SLV3579U / 28/12/201	Date In/Mileage	16/12/2021/ 0	Chassis No	KNAHU815VJ7193822	Engine No	D4FDHH546890	Make/Model	KIA/CARENS 1.7 A D EX FL DY7	Colour/Trim	IM TITANIUM SILVER/ WK SATURN BLACK
Cust No/Name	/Seem Kok Seng														
Reg No/Reg Date	SLV3579U / 28/12/201														
Date In/Mileage	16/12/2021/ 0														
Chassis No	KNAHU815VJ7193822														
Engine No	D4FDHH546890														
Make/Model	KIA/CARENS 1.7 A D EX FL DY7														
Colour/Trim	IM TITANIUM SILVER/ WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	15/12/2021/ 11:42	BLK	282 / Kevin Leong	43990			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	EMBLEM-CRDI	✓ NC			1.00	29.00	20.00	23.20
M	GLASS ASSY-TAIL GATE	X			1.00	490.00	20.00	392.00
M	STOPPER-RR WINDOW GLASS	✓ NC			2.00	15.00	20.00	24.00
M	PAD-WINDSHIELD GLASS	✓ NC			6.00	2.00	20.00	9.60
M	GROMMET-REAR WIPER	✓ NC			1.00	5.00	20.00	4.00
M	ORNAMENT-KIA	✓ NC			1.00	76.00	20.00	60.80
M	GARNISH-TAIL GATE,UPR	X			1.00	135.00	20.00	108.00
M	COVER-RR BUMPER,UPR	✓ BR			1.00	576.00	20.00	460.80
M	COVER-RR BUMPER LWR	✓ BR			1.00	211.00	20.00	168.80
M	BRACKET-RR BUMPER SIDE LWR,RH	?			1.00	21.00	20.00	16.80
M	LAMP ASSY-REAR FOG,RH	✓ BR			1.00	116.00	20.00	92.80
M	BRACKET-FR BUMPER SIDE,RH	?			1.00	4.00	20.00	3.20
M	WIRING HARNESS-R.P.A.S	?			1.00	251.00	20.00	200.80
M	BRACKET-RR BUMPER RAIL,UPR	?			1.00	5.00	20.00	4.00
M	BRACKET-RR BUMPER RAIL,LWR	?			1.00	5.00	20.00	4.00
M	BRACKET-RR BUMPER LWR,CTR	?			1.00	5.00	20.00	4.00
M	BRACKET-RR BUMPER RAIL,LWR	?			1.00	5.00	20.00	4.00
M	BEAM-RR BUMPER	✓ BR			1.00	367.00	20.00	293.60
M	ANTENNA ASSY-SMARTKEY	?			1.00	79.00	20.00	63.20
M	STAY-RR BUMPER LH	?			1.00	159.00	20.00	127.20
M	STAY-RR BUMPER RH	?			1.00	159.00	20.00	127.20
M	BRACKET ASSY-RR BUMPER SIDE,LH	?			1.00	25.00	20.00	20.00
M	BRACKET ASSY-RR BUMPER SIDE,RH	?			1.00	25.00	20.00	20.00
M	HOLDER-BACK WARING SYSTEM OTR	?			2.00	4.00	20.00	6.40
M	HOLDER-BACK WARING SYSTEM INR	?			2.00	4.00	20.00	6.40
M	ULTRASONIC SENSOR ASSY-P.A.S	?			1.00	162.00	20.00	129.60
M	ULTRASONIC SENSOR ASSY-P.A.S	?			1.00	162.00	20.00	129.60

Estimate

Steve (LKK)
16/12/21, 12:30pm

00-MAL
Express-?
PIP, M B C Sy

6 days

Nett	8,655.60
7% GST on	605.89
Total Payable	9,261.49

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "What I See is What I Get" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be intimated and is subject to final approval from Insurance Company

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.