



CYCLE & CARRIAGE

AG- OD CLAIM  
SURVEY: 16/12/22  
LKK- STEVE

VEHICLE NO : SLV 3579 U

MODEL : KIA/CARENS 1.7 A D EX

WIP : 43990

Material	:	\$	<u>3,052.80</u>
Labour	:	\$	<u>3,420.00</u>
Sub-Total	:	\$	<u>6,472.80</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>—</u>
Total	:	\$	<u>6,472.80</u>
GST 7%	:	\$	<u>453.10</u>
Grand Total	:	\$	<u>6,925.90</u>
Finalise By/Date	:	<u>Umyy ON 07/01/22</u>	

REVERT BACK WITHIN 7 DAYS,  
OTHERWISE WILL PROCEED WITH INVOICING

SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 08 WORKING DAYS + 4 days (2 wk-ends)

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

**THIS IS NOT AN OFFICIAL TAX INVOICE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000  17/12/2021	<b>Cust No/Name</b> LCV18066/Seem Kok Seng
	<b>Reg No/Reg Date</b> SLV3579U / 28/12/2017
	<b>Date In/Mileage</b> 16/12/2021/ 115302
	<b>Chassis/Package</b> KNAHU815VJ7193822 /@3
	<b>Engine No</b> D4FDHH546890
	<b>Make/Model</b> KIA/CARENS 1.7 A D EX FL DY7
	<b>Colour/Trim</b> IM TITANIUM SILVER/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	07/01/2022/ 08:47	BLK	884 / Lauro Songcuan	43990			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000		REPLACE REAR BUMPER, TAILGATE & AFFECTED AREAS						1000.00 ✓
E PNT98000		SPRAY PAINT ON REAR BUMPER, TAILGATE & END PANEL						1050.00 ✓
E PNT88000		REMOVE & RELACE REAR PARKING ASSIT TO FACILITATE REPAIR						80.00 ✓
E PNT88000		REMOVE & INSTALL REAR WINDSCREEN GLASS TO FACILITATE REPAIR						240.00 ✓
M SUNDRY		APPLY REAR WINDSCREEN SEALANT						80.00 ✓
E PNT88000		TRANSFER REAR BOOT ATTACHEMENT TO NEW PANEL						120.00 ✓
E PNT88000		REMOVE & INSTALL REAR COMPARTMENT TO FACILITATE REPAIR						120.00 ✓
M SUNDRY		PERFORM RUST PREVENTION ON AFFECTED PORTIONS						40.00 ✓
M SUNDRY		APPLY SEALANT ON AFFECTED AREAS						80.00 ✓
A 54900099		CHECK WIRING & CHASSIS ELECTRICAL SYSTEM						30.00 ✓
A 10028901		TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM						120.00 ✓
M SUNDRY		SUPPLY C&C EMBLEM						40.00 ✓
M SUNDRY		SUNDRIES						20.00 ✓
E PNT88000		REPLACE REAR END PANEL → <i>Supp.</i>						400.00 ✗
X		LAMP ASSY-REAR COMBINATION,RH ✓			1.00	357.00	20.00	285.60 ✓
X		PANEL ASSY-TAIL GATE ✓			1.00	1218.00	20.00	974.40 ✓
X		EMBLEM-CARENS ✓			1.00	36.00	20.00	28.80 ✓
X		EMBLEM-CRDI ✓			1.00	29.00	20.00	23.20 ✓
X		STOPPER-RR WINDOW GLASS ✓			1.00	15.00	20.00	12.00 ✓

This is not an official tax invoice.  
 This is a computer generated document, no signature is required.

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

**THIS IS NOT AN OFFICIAL TAX INVOICE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000  17/12/2021	<b>Cust No/Name</b>	LCV18066/Seem Kok Seng
	<b>Reg No/Reg Date</b>	SLV3579U / 28/12/2017
	<b>Date In/Mileage</b>	16/12/2021/ 115302
	<b>Chassis/Package</b>	KNAHU815VJ7193822 /@3
	<b>Engine No</b>	D4FDHH546890
	<b>Make/Model</b>	KIA/CARENS 1.7 A D EX FL DY7
	<b>Colour/Trim</b>	IM TITANIUM SILVER/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	07/01/2022/ 08:47	BLK	884 / Lauro Songcuan	43990

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X GROMMET-REAR WIPER ✓	1.00	5.00	20.00	4.00
X ORNAMENT-KIA ✓	1.00	76.00	20.00	60.80
X COVER-RR BUMPER,UPR ✓	1.00	576.00	20.00	460.80
X COVER-RR BUMPER LWR ✓	1.00	211.00	20.00	168.80
X LAMP ASSY-REAR FOG,RH ✓	1.00	116.00	20.00	92.80
X BEAM-RR BUMPER ✓	1.00	367.00	20.00	293.60
X STAY-RR BUMPER RH ?	1.00	159.00	20.00	127.20
X CROSSMEMBER ASSY-RR END	1.00	453.00	20.00	362.40
X CLIP	10.00	1.00	20.00	8.00
X SKID PLATE-RR BUMPER	1.00	179.00	20.00	143.20
X CAP-RR HOOK	1.00	4.00	20.00	3.20
X BRACKET-RR BUMPER RAIL,UPR ?	1.00	5.00	20.00	4.00

Z TEXT  
 AIG OD CLAIM - REVERT  
 DOA: 14/12/2021  
 SURVEY: STEVE (LKK) 16/12/2021  
 08 DAYS

*Guarantee Your Warranty, Maintain with Cycle & Carriage!*

Parts	3,052.80		Nett	6,472.80
Labour	3,160.00	7% GST on	6472.80	453.10
Standard Menu	0.00			
Specialist Job	0.00			
Diagnostics Job	0.00		Total Payable	6,925.90
Sundry/Others	260.00			
Total(w/o GST)	6,472.80			

This is not an official tax invoice.  
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : **AIG**

Supplementary For Registration No.: **SLV 3579 U**

	<b><u>Materials</u></b>	<b><u>Cost (\$)</u></b>
1	Crossmember Assy- RR End	453.00 ✓ <i>DD</i>
2	Clip (10 pcs)	10.00 ✓ <i>rec</i>
3	Skid Plate- RR Bumper	179.00 ✓ <i>BK</i>
4	Cap- RR Hook	4.00 ✓ <i>mis</i>
		<hr/> <hr/> 646.00
	20% Discount	<hr/> <hr/> 129.20
		<hr/> <hr/> 516.80
	<b><u>Labour</u></b>	
1	Replace Rear End Panel	400.00 ✓
		<hr/> <hr/> 916.80
	7% Gst	<hr/> <hr/> 64.18
	<b>Total</b>	<hr/> <hr/> <b>980.98</b>

Thank You.

Yours faithfully  
CYCLE & CARRIAGE KIA PTE LTD

LARRY SONGCUAN  
CUSTOMER SERVICE  
TEL: 6568 4658  
FAX : 6567 5258

CAR NO: SLV 3579U

WIP: 43990 (ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	RR panel ✓	? / SUPP		✓ OD	
2	STRAY-RR Bumper RH ✓	? / SUPP		✓ RR	
3	BRACKET-RR Bumper RH L WR (1)?	? / SUPP		✓ RT	
4	Bumpers clip X10 ✓	? / SUPP		✓ MC	
5		? / SUPP			Steve
6		? / SUPP			21/12/21
7	✓ Renew RR panel <del>A 1800</del> 400	? / SUPP			
8	<del>TO APPLY RR panel</del> <del>STARTING</del>	? / SUPP			
9	✓ repair working Day = 2 hrs	? / SUPP			
10		? / SUPP			
11	86665-A 4800 (skid plate 5hr)	? / SUPP			
12	Tow Cover	? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

	DATE	TAKEN BY
PHOTO BEFORE PAINT		
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBOARD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: Carrens  
 SURVEYOR: Steve-LKK



# e-Report [Pilot Ver : 1.064]\_20211209



KNAHU815VJ7193822 CARENS/RONDO(RP)/2018/D 1.7 TCI-U2



## e-Report

## e-Report Case Statistics

eReport Case View

Vehicle Diagnosis Number : 2112280511

List

Prev Page

Date	12/28/2021	Distributor	A22VA	Dealer Code	D0001
ServerDate	12/28/2021	Model	CARENS/RONDO(RP)	Engine Type	D 1.7 TCI-U2
GDS Version	Source : Content :	Selected Symptom		VIN	KNAHU815VJ7193822

Vehicle Information	Unchecked	Warranty History	Unchecked
---------------------	-----------	------------------	-----------

odometer - Information	
odometer	Unit
	VCI
	VCI2_BT

Total Count : 1

Diagnosis - DTC Codes							
Type	System	Code	Description	FreezeFrame	Status	VCI	
Fault Code Searching	Engine		No DTC present at this time	-	-	VCI2_WFD	
Fault Code Searching	Transmission		No DTC present at this time	-	-	VCI2_WFD	
Fault Code Searching	Brake		No DTC present at this time	-	-	VCI2_WFD	
Fault Code Searching	Airbag		No DTC present at this time	-	-	VCI2_WFD	
Fault Code Searching	Air Conditioner		No DTC present at this time	-	-	VCI2_WFD	
Fault Code Searching	Smart Key		No DTC present at this time	-	-	VCI2_WFD	
Fault Code Searching	Body Control		No DTC present at this time	-	-	VCI2_WFD	
Fault Code Searching	Cluster Module		No DTC present at this time	-	-	VCI2_WFD	
Fault Code Searching	Smart Junction Block		No DTC present at this time	-	-	VCI2_WFD	

Total Count : 9

S/W Ver.

NEK-00-0009

VCI Ver.

02.63

Res Ver.

NEK-00-0009

OS Ver.

Android 11



# e-Report [Pilot Ver : 1.064]\_20211209



KNAHU815VJ7193822 CARENS/RONDO(RP)/2018/D 1.7 TCI-U2



## e-Report

## e-Report Case Statistics

eReport Case View

Vehicle Diagnosis Number 2112280511

List

Prev Page

Date	12/28/2021	Distributor	A22VA	Dealer Code	00001
ServerDate	12/28/2021	Model	CARENS/RONDO(RP)	Engine Type	D 1.7 TCI-U2
GDS Version	Source : Content :	Selected Symptom		VIN	KNAHU815VJ7193822

Vehicle Information	Unchecked	Warranty History	Unchecked
---------------------	-----------	------------------	-----------

odometer - Information	
odometer	Unit
	VCI
	VCI2_BT

Total Count : 1

Diagnosis - DTC Codes							
Type	System	Code	Description	Freezeframe	Status	VCI	
Fault Code Searching	Engine		No DTC present at this time		-	VCI2_WFD	
Fault Code Searching	Transmission		No DTC present at this time		-	VCI2_WFD	
Fault Code Searching	Brake		No DTC present at this time		-	VCI2_WFD	
Fault Code Searching	Airbag		No DTC present at this time		-	VCI2_WFD	
Fault Code Searching	Air Conditioner		No DTC present at this time		-	VCI2_WFD	
Fault Code Searching	Smart Key		No DTC present at this time		-	VCI2_WFD	
Fault Code Searching	Body Control		No DTC present at this time		-	VCI2_WFD	
Fault Code Searching	Cluster Module		No DTC present at this time		-	VCI2_WFD	
Fault Code Searching	Smart Junction Block		No DTC present at this time		-	VCI2_WFD	

Total Count : 9

S/W Ver.

NEK-00-0009

VCI Ver.

02.63

Res Ver.

NEK-00-0009

OS Ver.

Android 11