

# N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2  
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
E-Mail : sales@n51.com.sg  
Company Reg. No. : 200616038C  
GST Registration No. : 200616038C

HITACHI CAPITAL ASIA PACIFIC PTE. LTD.  
111 SOMERSET ROAD #14-05 TRIPLEONE  
SOMERSET  
SINGAPORE 238164

Contact : 68336152 98331744

## TAX INVOICE

Repair Code : CLM17030  
Date in : 13/12/2021  
Vehicle Num. : SLH7723S  
Model : MINI COOPER S HATCHBACK 1.6 HID D/AB DS SR  
Chassis/Eng# : WMWSV32050T672110/A742J519N18B16A

### Parts and Labour Assesment

Description of part	Qty	Unit Price		Amount
AIRBAG ECU	1	950.00	act ✓	950.00
AIRCON CONDENSER	1	895.00	bt ✓	895.00
FRONT BONNET	1	1250.00	bt ✓	1,250.00
FRONT BONNET 'LOGO' EMBLEM	1	65.00	nei ✓	65.00
FRONT BONNET AIR DUCT	1	45.00	Xun	45.00
FRONT BONNET HINGES L/R	2	66.00	Ry	132.00
FRONT BONNET LOCK STRIKER L/R	2	27.00	bt ✓	54.00
FRONT BONNET MECHANISM LOCK L/R	2	88.00	bt ✓	176.00
FRONT BONNET MOULDING	1	165.00	dis ✓	165.00
FRONT BUMPER (JCW)	1	820.00	de ✓	820.00
FRONT BUMPER FOGLAMP GARNISH L/R	2	450.00	de ✓	900.00
FRONT BUMPER FOGLAMP L/R	2	310.00	ane ✓	620.00
FRONT BUMPER LOWER GRILLE	1	160.00	de ✓	160.00
FRONT BUMPER LOWER GRILLE 'JOHN COOPER' EMBLEM	1	90.00	nei ✓	90.00
FRONT BUMPER LOWER LID L/R	2	305.00	de ✓	610.00
FRONT BUMPER REINFORCEMENT	1	470.00	bt ✓	470.00
FRONT BUMPER SIDE RETAINER L/R	2	47.00	nei ✓	94.00
FRONT BUMPER TOW HOOK COVER	1	45.00	mis ✓	45.00

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

HITACHI CAPITAL ASIA PACIFIC PTE. LTD.  
 111 SOMERSET ROAD #14-05 TRIPLEONE  
 SOMERSET  
 SINGAPORE 238164

Contact : 68336152 98331744

**TAX INVOICE**

Repair Code : CLM17030

Date in : 13/12/2021

Vehicle Num. : SLH7723S

Model : MINI COOPER S HATCHBACK 1.6 HID D/AB DS SR

Chassis/Eng# : WMWSV32050T672110/A742J519N18B16A

FRONT FENDER ARCH GARNISH L/R	2	205.00	de ✓	410.00
FRONT GRILLE	1	125.00	cur ✓	125.00
FRONT GRILLE OUTER MOULDING	1	148.00	di's ✓	148.00
FRONT HEADLAMP L/R	2	1450.00	cur ✓	2,900.00
FRONT INTERCOOLER	1	650.00	bt ✓	650.00
FRONT INTERCOOLER HOSE	1	465.00	Xun ✓	465.00
FRONT SEAT BUCKIE LH	1	330.00	qet ✓	330.00
FRONT SEAT BUCKIE RH	1	330.00	act ✓	330.00
OIL PRESSURE SWITCH	1	105.00	cur ✓	105.00
OIL TEMPERATURE SWITCH	1	105.00	cur ✓	105.00
RADIATOR	1	640.00	bt ✓	640.00
RADIATOR FAN COWLING ASSY	1	790.00	cur ✓	790.00
RADIATOR SIDE GUIDE L/R	2	180.00	fn ✓	360.00
RADIATOR SUPPORT PANEL	1	630.00	bt ✓	630.00
REAR BUMPER (JCW)	1	850.00	de ✓	850.00
REAR BUMPER CENTER BRACKET	1	29.00	de ✓	29.00
REAR BUMPER CENTER GRILLE	1	40.00	de ✓	40.00
REAR BUMPER LOWER DIFFUSER	1	425.00	cur ✓	425.00

\*\*\* This is a computer-generated document which requires no signature. \*\*\*

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

HITACHI CAPITAL ASIA PACIFIC PTE. LTD.  
 111 SOMERSET ROAD #14-05 TRIPLEONE  
 SOMERSET  
 SINGAPORE 238164

Contact : 68336152 98331744

**TAX INVOICE**

Repair Code : CLM17030  
 Date in : 13/12/2021  
 Vehicle Num. : SLH7723S  
 Model : MINI COOPER S HATCHBACK 1.6 HID D/AB DS SR  
 Chassis/Eng# : WMWSV32050T672110/A742J519N18B16A

REAR BUMPER LOWER SIDE SPOILER L/R	2	90.00	de ✓	180.00
REAR BUMPER REFLECTOR GARNISH L/R	2	80.00	cu ✓	160.00
REAR BUMPER REFLECTOR L/R	2	150.00	cu ✓	300.00
REAR BUMPER REINFORCEMENT	1	550.00	bt ✓	550.00
REAR BUMPER REVERSE SENSOR	4	240.00	ru ✓	960.00
REAR BUMPER REVERSE SENSOR 'O' RING	4	5.50	re ✓	22.00
REAR BUMPER REVERSE SENSOR HOLDER	2	47.00	re ✓	94.00
REAR BUMPER REVERSE SENSOR WIRE HARNESS	1	180.00	xu ✓	180.00
REAR BUMPER SIDE RETAINER L/R	2	42.00	re ✓	84.00
REAR BUMPER SPONGE	1	55.00	de ✓	55.00
REAR BUMPER TOW HOOK COVER L/R	2	45.00	de ✓	90.00
REAR END PANEL (INNER)	1	500.00	bt ✓	500.00
REAR END PANEL (OUTER)	1	500.00	bt ✓	500.00
REAR END PANEL AIR VENT COVER L/R	2	60.00	de ✓	120.00
REAR END PANEL AIR VENT L/R	2	39.00	de ✓	78.00
REAR END PANEL ANTENNA SENSOR	1	240.00	cu ✓	240.00
REAR END PANEL INNER TOP GARNISH	1	360.00	de ✓	360.00
REAR EXHAUST GASKET	1	27.00	re ✓	27.00

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

HITACHI CAPITAL ASIA PACIFIC PTE. LTD.  
 111 SOMERSET ROAD #14-05 TRIPLEONE  
 SOMERSET  
 SINGAPORE 238164

Contact : 68336152 98331744

**TAX INVOICE**

Repair Code : CLM17030  
 Date in : 13/12/2021  
 Vehicle Num. : SLH7723S  
 Model : MINI COOPER S HATCHBACK 1.6 HID D/AB DS SR  
 Chassis/Eng# : WMWSV32050T672110/A742J519N18B16A

REAR EXHAUST HEAT SEAL COVER	1	95.00	bt ✓	95.00
REAR EXHAUST SILENCER BOX	1	890.00	bt ✓	890.00
REAR FENDER ARCH GARNISH L/R	2	205.00	aw ✓	410.00
REAR FENDER INNER SHIELD L/R	2	120.00	Xun ✓	240.00
REAR FENDER INNER TRIM BOARD L/R	2	1300.00	tn ✓	2,600.00
REAR FLOOR PANEL TOP BOARD COVER	1	125.00	de ✓	125.00
REAR LH FENDER	1	880.00	R ✓	880.00
REAR TAILGATE	1	960.00	bt ✓	960.00
REAR TAILGATE 'LOGO' EMBLEM	1	65.00	ney ✓	65.00
REAR TAILGATE DAMPER L/R	1	93.00	Xun ✓	93.00
REAR TAILGATE HINGES L/R	2	51.00	XR ✓	102.00
REAR TAILGATE INNER TRIM BOARD	1	250.00	aw ✓	250.00
REAR TAILGATE LOCK STRIKER	1	65.00	bt ✓	65.00
REAR TAILGATE MECHANISM LOCK	1	150.00	bt ✓	150.00
REAR TAILGATE NUMBER PLATE LAMP L/R	2	340.00	Xun ✓	680.00
REAR TAILGATE OUTER HANDLE	1	620.00	aw ✓	620.00
REAR TAILGATE WEATHER STRIP	1	180.00	cut ✓	180.00
REAR TAILGATE WINDSCREEN LOWER MOULDING	1	168.00	de ✓	168.00

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

HITACHI CAPITAL ASIA PACIFIC PTE. LTD.  
 111 SOMERSET ROAD #14-05 TRIPLEONE  
 SOMERSET  
 SINGAPORE 238164

Contact : 68336152 98331744

**TAX INVOICE**

Repair Code : CLM17030  
 Date in : 13/12/2021  
 Vehicle Num. : SLH7723S  
 Model : MINI COOPER S HATCHBACK 1.6 HID D/AB DS SR  
 Chassis/Eng# : WMWSV32050T672110/A742J519N18B16A

REAR TAILLAMP L/R	2	LH <i>ana</i>	340.00	RH <i>Xun</i>	680.00
REAR TAILLAMP OUTER MOULDING L/R	2	LH <i>ana</i>	105.00	RH <i>Xun</i>	210.00
SUPPORT TOP PANEL	1		270.00	<i>bt</i>	270.00
WATER PUMP	1		320.00	<i>ana</i>	320.00
Subtotal before discount					31,426.00
Percentage discount 10%					3,142.60
<b>Sub-total 1</b>					<b>28,283.40</b>
FRONT BONNET MOULDING CLIPS - SET	1		60.00	<i>neu</i>	60.00 30
FRONT BONNET STICKER - SET	1		500.00	<i>neu</i>	500.00 250
FRONT BUMPER CLIPS - SET	1		60.00	<i>neu</i>	60.00 30
FRONT BUMPER NUMBER PLATE	1		25.00		25.00
FRONT BUMPER NUMBER PLATE HOLDER	1		50.00	<i>45 mis</i>	50.00
FRONT FENDER ARCH GARNISH CLIPS L/R - SET	2		50.00	<i>neu</i>	100.00 50
FRONT GRILLE CLIPS - SET	1		60.00	<i>neu</i>	60.00 30
FRONT GRILLE TOP FOGLAMP L/R	2		300.00	<i>mis</i>	600.00 400
OIL COOLER	1		500.00	<i>bt</i>	500.00 300
RADIATOR COOLANT	1		80.00	<i>neu</i>	80.00 50
REAR BUMPER CLIPS - SET	1		60.00	<i>neu</i>	60.00 30

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

HITACHI CAPITAL ASIA PACIFIC PTE. LTD.  
 111 SOMERSET ROAD #14-05 TRIPLEONE  
 SOMERSET  
 SINGAPORE 238164

Contact : 68336152 98331744

**TAX INVOICE**

Repair Code : CLM17030  
 Date in : 13/12/2021  
 Vehicle Num. : SLH7723S  
 Model : MINI COOPER S HATCHBACK 1.6 HID D/AB DS SR  
 Chassis/Eng# : WMWSV32050T672110/A742J519N18B16A

REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	50.00	net 20	50.00
REAR EXHAUST TAIL PIPE - SET	2	400.00	net 600	800.00
REAR FENDER ARCH GARNISH CLIPS L/R - SET	2	40.00	net 50	80.00
REAR FENDER INNER SHIELD CLIPS L/R - SET	2	50.00	net 30	100.00
REAR FENDER INNER TRIM BOARD CLIPS L/R - SET	2	50.00	net 30	100.00
REAR LH FENDER GLASS SEAL	1	80.00	net 80	80.00
REAR LH FENDER GLASS SEALANT	1	80.00	net 30	80.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET	1	50.00	net 30	50.00
REAR TAILGATE NUMBER PLATE	1	25.00	net 25	25.00
REAR TAILGATE NUMBER PLATE HOLDER	1	50.00	net 45	50.00
REAR TAILGATE OUTER HANDLE CLIPS - SET	1	40.00	net 20	40.00
REAR TAILGATE WINDSCREEN SEAL	1	80.00	net 40	80.00
REAR TAILGATE WINDSCREEN SEALANT	1	80.00	net 40	80.00
REAR TAILLAMP CLIPS L/R - SET	2	30.00	net 30	60.00
		Subtotal before discount	2120	3,770.00
Percentage discount 0%				0.00
		Sub-total 2		3,770.00
		Parts-total		32,053.40

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

HITACHI CAPITAL ASIA PACIFIC PTE. LTD.  
 111 SOMERSET ROAD #14-05 TRIPLEONE  
 SOMERSET  
 SINGAPORE 238164

Contact : 68336152 98331744

**L.K Auto Consultants** hence notify  
**the Repairer** of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

**TAX INVOICE**

Repair Code : CLM17030  
 Date in : 13/12/2021  
 Vehicle Num. : SLH7723S  
 Model : MINI COOPER S HATCHBACK 1.6 HID D/AB DS SR  
 Chassis/Eng# : WMWSV32050T672110/A742J519N18B16A

**LABOUR**

To remove, change air con parts, vacuums, refill air con gas.	140.00 100
To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)	80.00 30
To reset system after repair works	500.00 200
To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	80.00 30
To remove, reinstall tailgate windscreen	150.00 120
To remove, reinstall fender glass	150.00 100
To remove, reinstall petrol tank. (to FR)	80.00 100
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	140.00 60
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.	1,400.00 1100
To re-spray painting on the front bonnet, front support panel, front fender (L/R) and front bumper.	1,000.00 600
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	100.00 60
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	2,500.00 1600
To apply anti-rust chemical on repaired and replaced panel.	140.00 80
To transfer rear bootlid mechanism lock outer handle reflector	80.00 60

Labour Total	4040	6,540.00
Parts & Labour Total	<u>38,593.40</u>	

Taufik 97445749  
 WP' 1/5 Novy after repair  
 Repair limit  
 taufik@lkkauto.com 12 days

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

25348.50  
 2120  
 4040  


---

 31508.50  
 20% 25206.80  
 Repair limit \$16,000  
 1/5 \$16000, 12 days #