



# Borneo Motors



Inchcape

Co. Reg No. : 19670086Z  
GST Reg No. : MR-850000-9  
No 2 Pandan Crescent  
Singapore 128462, Tel no. : 6631 1388

## ESTIMATE

Account Details			Account No.		Customer Details			
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			S1000003 / ICCI1		Mr Richard Chris Chia Chee Weng			
			Document No. 0		233 Paya Lebar Road #06-03 Le Crescendo Singapore 409044			
			Document Date 15/12/2021		Mobile: 97925566			
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2016	ASV60R	BETGK S3	25/01/2017	SLK7401E	0	20421	61TP/SLK7401E/141221	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTHBJ1GG802095621		2ARF260095	60	Carine Yeo C L	--/--/----		0.00	--/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount		
1	Z	BP-SUNDRY SUNDRIES T/P INS: CHINA TAIPING ACC DATE: 14.12.2021 T/P VEH: XE4522Z DATE IN: DATE SURVEY: DATE AUTHORZE:				50	100.00	
2	B	BP-LAB3 TO REMOVE ALL NECESSARY PARTS TO ENABLE REPAIRING AND STRAIGHTEN ON RHS REAR DOOR, RHS REAR FENDER AND FIX NEW PARTS	866 X5			4330	5196.00	
3	B	BP-RES3 TO SPRAY PAINT ON RHS REAR DOOR, RHS REAR FENDER AND REAR PANEL	742 X2			2726	2968.00	
4	B	BP-LAB3 TO REMOVE AND TRANSFER RHS REAR DOOR'S COMPONENT AND MECHANISM TO NEW DOOR					866.00	
5	Z	BP-SLANT SUPPLY RHS REAR DOOR SEALANT (NETT)					100.00	
6	B	BP-LAB3 TO REMOVE AND RE-INSTALL REAR SEAT, SIDE TRIM, GARNISH ETC TO ENABLE REPAIR (NETT) (parts)					866.00	
For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature	Charge Summary			Total		
		Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others			Less		
						Amount Due		

Customer Copy



**Borneo Motors**

Inchcape

Co. Reg No. : 196700086Z  
 GST Reg No. : MR-8500000-9  
 No 2 Pandan Crescent  
 Singapore 128462. Tel no.: 6631 1388



**ESTIMATE**

Account Details		Account No.	Customer Details					
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICC1	Mr Richard Chris Chia Chee Weng					
		Document No. 0	233 Paya Lebar Road #06-03 Le Crescendo Singapore 409044					
		Document Date 15/12/2021	Mobile: 97925566					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2016	ASV60R	BETGK S3	25/01/2017	SLK7401E	0	20421	61TP/SLK7401E/141221	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTHBJ1GG802095621		2ARF260095	60	Carine Yeo C L	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
7	B	BP-LAB3 TO REMOVE AND REPLACE REAR WINDSCREEN GLASS (NETT)						X 866.00
8	S	BP-SUBLET REPLACE REAR WINDSCREEN SOLAR FILM (NETT)						X 420.00
9	B	BP-LAB3 TO REMOVE AND RE-INSTALL REAR SENSOR TO ENABLE REPAIR (NETT)						216.50 /
10	B	BP-LAB3 TO CHECK WIRING AND LIGHTS FUNCTIONING AND CARRY OUT WATER LEAK TEST (NETT)						216.50 /
11	B	BP-ECU3 TO RESET ECU & REPROGRAMME (NETT)						216.50 /
12	T	BP-MISC1 SHOULD THE ABOVE VEHICLE BE SUBJECT TO TOTAL LOSS OR TOW OUT BY INSURANCE COMPANY OR BY THE OWNER PRIOR TO THE REPAIR A 6% OF THE QUOTATION PRICE WILL BE IMPOSED AS ADMIN CHARGES TO A MAX OF \$1000 + TOWING CHARGES IF APPLICABLE.						
For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature		Charge Summary		Total		
		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less		
						Amount Due		

Customer Copy



Borneo Motors



Inchcape

Co. Reg No. : 196700086Z  
GST Reg No. : MR-8500000-9  
No.2 Pandan Crescent  
Singapore 128462, Tel no : 6631 1388

### ESTIMATE

Account Details			Account No.		Customer Details			
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			S1000003 / ICCI1		Mr Richard Chris Chia Chee Weng			
			Document No. 0		233 Paya Lebar Road #06-03 Le Crescendo Singapore 409044			
			Document Date 15/12/2021		Mobile: 97925566			
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2016	ASV60R	BETGK S3	25/01/2017	SLK7401E	0	20421	61TP/SLK7401E/141221	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTHBJ1GG802095621		2ARF260095	60	Carine Yeo C L	--/--/----	0.00	--/--/----	0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount		
13	Z	BP-MISC2 A DAILY STORAGE CHARGE AT THE RATE OF S\$25/- PER DAY WILL COMMENCE 7 DAYS AFTER ESTIMATE DATE. THESE CHGS WILL NOT APPLY IF REPAIRS ARE UNDERTAKEN BY BORNEO MOTORS.						
14	1	L67003-33220 PANEL SUB-ASSY RR <i>DD</i>	1.00	1212.90			1212.90	
15	2	L68188-33070 WEATHERSTRIP, RR <i>DD</i>	1.00	60.70			60.70	
16	3	L75977-33030 STRIPE RR DOOR <i>DD</i>	1.00	38.60			38.60	
17	4	L75987-33060 STRIPE RR DOOR <i>DD</i>	1.00	70.00			70.00	
18	5	L67857-33040 PROTECTOR, RR DOOR <i>DD</i>	1.00	11.30			11.30	
19	6	L67871-33110 WEATHERSTRIP RR <i>DD</i>	1.00	285.60			285.60	
20	7	T67867-12150 RETAINER, DOOR <i>DD</i>	17.00	5.40			91.80	
21	8	L67895-33030 WEATHERSTRIP RR <i>DD</i>	1.00	62.40			62.40	
22	9	L67887-33040 WEATHERSTRIP RR <i>DD</i>	1.00	62.40			62.40	
23	0	L69210-48040 B7 HANDLE ASSY, DOOR <i>DD</i>	1.00	492.90			492.90	
24	1	L69227-48010 B7 COVER, RR DOOR <i>DD</i>	1.00	49.50			49.50	
25	2	L69241-48030 PAD, FR DOOR OUTSIDE <i>DD</i>	1.00	21.00			21.00	
26	3	L69241-48050 PAD FR DOOR OUTSIDE <i>DD</i>	1.00	20.70			20.70	
27	4	L58747-33071 PROTECTOR, QUART <i>DD</i>	1.00	28.80			28.80	
28	5	L61611-33250 PANEL, QUARTER RH <i>DD</i>	1.00	1532.20			1532.20	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total	
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less	
							Amount Due	

Customer Copy

Co. Reg No. : 196700086Z  
 GST Reg No. : MR-8500000-9  
 No 2 Pandan Crescent  
 Singapore 128462, Tel no.: 6631 1388

## ESTIMATE

Account Details			Account No.		Customer Details			
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			S1000003 / ICC11		Mr Richard Chris Chia Chee Weng			
			Document No.		233 Paya Lebar Road			
			0		#06-03 Le Crescendo Singapore 409044			
			Document Date		Mobile: 97925566			
			15/12/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2016	ASV60R	BETGK S3	25/01/2017	SLK7401E	0	20421	61TP/SLK7401E/141221	
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On			
JTHBJ1GG802095621	2ARF260095	60	Carine Yeo C L	--/--/----	0.00	--/--/----	0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
29	6	L65637-33060	PANEL SUB-ASSY RR	X nn	1.00	214.00		214.00
30	7	L64801-33905	GLASS, BACK WINDOW	X nn	1.00	1671.10		1671.10
31	8	L56117-50140	DAM, WINDOW GLASS	X nn	1.00	29.20		29.20
32	9	L75573-33080	MOULDING, BACK WINDOW	X nn	1.00	60.70		60.70
33	0	L75761-33070	MOULDING RR DOOR	/ n/c	1.00	98.50		98.50
34	1	L90269-04051	RIVET	/ n/c	19.00	1.50		28.50
35	2	T21000-20	SIKA 182010 SIKATACK GO! (BLA	X nn	2.00	108.00		216.00
36	3	T21000-22	SIKA 207. G+P ADHESIVE PRIMER	X nn	1.00	200.00		200.00
37	4	T08826-08115	PANEL BONDING AD	/ n/c	1.00	267.20		267.20

Steve CLKK)  
 20/12/21, 11:30am  
 ml ml  
 PIP  
 by Bil by  
 8 to days

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			18,857.50
	Please acknowledge receipt of vehicle 	Parts	6,826.00
		Labour	11,611.50
		Sublet	420.00
		Lubrication/Fluid	0.00
		Others	0.00
GST 7.00%			1,320.03
Less			0.00
Amount Due			20,177.53

LKK Auto Consultants hence notify the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Customer Copy

