

# Vin's

**Vin's Motor Pte Ltd**  
160 Sin Ming Drive  
#03-03 Sin Ming Autocity  
Singapore 575722  
Tel : 6453 2121 Fax : 6459 9795  
GST Registration No. 199906067G

## Estimated Cost of Repair

**Attention To :** China Taiping Insurance  
(Singapore) Pte Ltd  
3 Anson Road  
#15-00 Springleaf Tower  
Singapore 079909

### Claim Details

**Case Ref. No. :** TP/122021/5129  
**Date :** 14-12-2021  
**Accident Date :** 13-12-2021

### Vehicle Details

**Make & Model :** HONDA SHUTTLE HYBRID 1.5  
AUTO  
**Chassis No :** GP72203332  
**Registration No :** SNC4703Y

### Third Party Vehicle Details

**Registration No :** SKX4439K

S/N	Description	Qty	Amount (\$S)
1	REAR TAILGATE / <i>Ruc</i>	1.00	\$1,293.50 ✓
2	REAR TAILGATE GLASS MOULDING / <i>Yac</i>	1.00	\$153.20 118.2
3	REAR TAILGATE "SHUTTLE" EMBLEM / <i>Yac</i>	1.00	\$55.20 ✓
4	REAR TAILGATE "HYBRID" EMBLEM / <i>Yac</i>	1.00	\$80.10 ✓
5	REAR BUMPER CHROME MOULDING / <i>X MV</i>	1.00	\$220.20
			\$1,802.20 1547
<b>Discount: -20%</b>			(\$360.44)
			\$1,441.76 1237.6
6	REAR WINDSCREEN GUM / <i>MCL</i>	1.00	\$60.00 40
7	TO REMOVE AND REFIX REAR WINDSCREEN	1.00	\$150.00 120
8	TO REPAIR DAMAGES	1.00	\$380.00 200
9	TO SPRAY PAINTING	1.00	\$380.00 ✓
<b>Subtotal w/o GST:</b>			\$2,411.76 740
			1977.6

4 Days.  
P/P  
before paint photos  
GMO QIP  
29/12/21

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Acknowledged by Repairer**  
Signature:  
Date:

Issued by Raymond Teo

This is a computer-generated document. No signature is required.