

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD9970A***Not Authorised  
Patching B4 paint*

AAD2112- 054.

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

**14 DEC 2021****SHD9970A**

JTDKB3FU003091526

TOYOTA

PRIUS GEN 4

10/12/21

Torela

24/09/2020

**PART****LIST**

1 COVER, REAR BUMPER	\$	By	485.60	✓
1 REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	By	332.70	✓
1 COVER, REAR BUMPER, LOWER	\$	By	22.00	✓
1 GUARD, REAR BUMPER, CENTER	\$	By	374.50	✓
1 RETAINER, REAR BUMPER SIDE, LH	\$	NJP	132.60	X
1 RETAINER, REAR BUMPER SIDE, RH	\$	NJP	132.60	X
1 REFLECTOR ASSY, REFLEX, LH	\$	By	39.00	X
1 REFLECTOR ASSY, REFLEX, RH	\$	CM	39.00	✓
1 LENS & BODY, REAR COMBINATION LAMP, RH	\$	By	339.60	✓
1 LENS & BODY, REAR COMBINATION LAMP, NO.2 RH	\$	CM	261.00	✓
1 PANEL SUB-ASSY, BACK DOOR	\$	By	1,147.80	✓
1 GLASS, BACK WINDOW FIX	\$	Sherrin	761.40	✓
1 MOULDING, BACK WINDOW, OUTSIDE LH NO.2	\$	By	30.90	✓
1 SPOILER SUB-ASSY, REAR	\$	By	1,575.40	X
1 LAMP ASSY, CENTER STOP	\$	By	192.30	X
1 LAMP ASSY, REAR, RH	\$	CM	293.60	✓
1 PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	\$	By	54.60	✓
1 PLATE, BACK DOOR NAME, NO.1	\$	By	54.60	✓
1 ORNAMENT SUB-ASSY, BACK DOOR	\$	By	47.90	✓
1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$	CM	913.60	✓
1 BOARD ASSY, BACK DOOR TRIM	\$		259.20	?
1 WEATHERSTRIP, BACK DOOR	\$		372.30	?
1 ANTENNA, ELECTRICAL KEY	\$		72.00	?
1 PAN, REAR FLOOR	\$	X	583.40	?
1 BOARD, REAR FLOOR, NO.1	\$		519.00	?
1 PANEL ASSY, DECK TRIM SIDE, LH	\$		355.90	?
1 PANEL ASSY, DECK TRIM SIDE, RH	\$		355.90	?
1 BOX, DECK FLOOR, REAR	\$		105.80	?

**Trans-cab Auto Services Pte Ltd****AAD2112-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD9970A**

1 BOX, DECK FLOOR, RH	\$	313.60	?
1 BOX, DECK FLOOR, LH	\$	1 <sub>in</sub> 313.00	X
1 COVER, FLOOR UNDER, NO.1 LH	\$	1 <sub>in</sub> 175.10	X
1 COVER, FLOOR UNDER, NO.2 RH	\$	241.90	?
1 COVER, REAR FLOOR CTR	\$	229.90	?
1 COVER, DECK TRIM, REAR	\$	126.70	?
1 PANEL SUB-ASSY, BODY LOWER BACK	\$	1 <sub>in</sub> 651.00	✓
1 STAY ASSY, BACK DOOR, LH	\$	242.50	?
1 STAY ASSY, BACK DOOR, RH	\$	242.50	?
1 HINGE ASSY, BACK DOOR, LH	\$	1 <sub>in</sub> 61.00	X
1 HINGE ASSY, BACK DOOR, RH	\$	1 <sub>in</sub> 61.00	X
1 PANEL SUB-ASSY, QUARTER, RH	\$	1 <sub>in</sub> 871.50	X
1 LINER, REAR WHEEL HOUSE, RH	\$	1 <sub>in</sub> 139.80	X
<b>TOTAL</b>	<b>\$</b>	<b>13,523.70</b>	
<b>25%</b>	<b>\$</b>	<b>3,380.93</b>	
	<b>\$</b>	<b>10,142.78</b>	

**Special Nett**

1SET PARKING AID	\$	1 <sub>in</sub> 700.00	220 <sub>in</sub>
1SET REAR BUMPER CLIP	\$	1 <sub>in</sub> 95.00	30 <sub>in</sub>
2 WINDSCREEN SEALANT	\$	1 <sub>in</sub> 150.00	80 <sub>in</sub>
1 WINDSCREEN MOULDING	\$	1 <sub>in</sub> 200.00	✓
1 WINDSCREEN INNER SPONGE SEAL	\$	1 <sub>in</sub> 130.00	30 <sub>in</sub>
1 REAR BUMPER PROTECTOR	\$	1 <sub>in</sub> 180.00	X
1SET REAR BUMPER RETAINER CLIP	\$	1 <sub>in</sub> 85.00	X
1 REAR SPOILER CLIP	\$	1 <sub>in</sub> 70.00	X
1 END PANEL TRIM CLIP	\$	1 <sub>in</sub> 65.00	?
1 REAR TAILGATE STICKER "Trans-Cab"	\$	1 <sub>in</sub> 80.00	30 <sub>in</sub>
1 REAR TAILGATE STICKER "6555-3333"	\$	1 <sub>in</sub> 80.00	30 <sub>in</sub>
1SET BUMPER CLIP FRT	\$	1 <sub>in</sub> 95.00	X
1 REAR NUMBER PLATE WITH MOULDING	\$	1 <sub>in</sub> 200.00	45 <sub>in</sub>
<b>TOTAL</b>	<b>\$</b>	<b>2,130.00</b>	

**TOTAL PARTS \$ 12,272.78****LABOUR**

**Trans-cab Auto Services Pte Ltd**

AAD2112-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

**SHD9970A**

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	300.00	1801
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	801
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,200.00	7001
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	180.00	601
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	480.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	480.00	X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	?
To check steering geometry and computer wheel alignment	\$	220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	601
Towing Fees	\$	( Bill ) 150.00	?
Putty And Spray Painting Of The Affected Portion.	\$	2,200.00	8801

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD9970A****AAD2112-**

To reinstall rear bumper parking sensor.	\$	170.00	500
To Check Electrical Lighting Concerned.	\$	170.00	200
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	220.00	X
To replace, refix and top up coolant for radiator	\$	170.00	X
To lift-up / out engine with gear box and refit.	\$	440.00	X
To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.	\$	380.00	X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	380.00	X
<b>TOTAL</b>	<b>\$</b>	<b>10,290.00</b>	
<b>Over All Total</b>	<b>\$</b>	<b>22,562.78</b>	

**(PART-BY-PART) Repair Days****25 DAYS****6 days**

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: