

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/TMI21012710/KVCN2**Date:** 27/12/2021**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MR000851		
Claimant Vehicle No :	SHD5339A	Insured Vehicle No :	SKE2357B		
Date of Loss:	10/12/2021	Nature of Claim:	TP	Claim No:	M2105733

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD5339A	Engine No:	M9R8839C003398
Make & Model:	RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A)	Chassis No:	VF1ABL15AUC283342
Reg. Date:	31/08/2016 (Man. Year: 2015)	Odometer:	823113 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Sailun 7 mm	Rear Left Side:	Sailun 7 mm
Front Right Side:	Sailun 7 mm	Rear Right Side:	Sailun 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,312.77	1,516.20	6,796.57	81.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,580.00	815.00	6,765.00	89.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,892.77	2,331.20	13,561.57	85.33
Approved Total (Overridden) (S\$)		1,850.00		
(S\$)	15,892.77	1,850.00	14,042.77	88.36
+ GST 7.00/7.00% (S\$)	1,112.49	129.50	982.99	88.36
Nett Amount (S\$)	17,005.26	1,979.50	15,025.76	88.36

INSPECTION

Date of Assignment:	16/12/2021	
Date Inspected:	14/12/2021	Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Dec 2021)

Parts: 143 RENAULT LATITUDE 2.0 DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHD5339A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*BUMPER COVER REAR	Buckled	561.70 FL	-	*561.70 FL
2	1		*BUMPER LOWER REAR	Dented/Cut	411.90 FL	-	*411.90 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	98.10 FL	-	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	82.10 FL	-	*- FL
5	1		*BUMPER REFLECTOR LH	Cracked	16.60 FL	-	*16.60 FL
6	1		*BUMPER RETAINER RH REAR	Serviceable	59.80 FL	-	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	80.80 FL	-	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	-	*- FL
9	1		*BUMPER BEAM REAR	Bent	547.80 FL	-	*547.80 FL
10	1		*OUTER PANEL REAR (END PANEL)	Repair	745.80 FL	-	*- FL
11	1		*OUTER PANEL REAR (END PANEL) TRIM	Serviceable	404.56 FL	-	*- FL
12	1		*TAILLAMP LH	Serviceable	401.40 FL	-	*- FL
13	1		*TAILLAMP RH	Serviceable	401.40 FL	-	*- FL
14	1		*BOOT REAR	Repair	1,677.20 FL	-	*- FL
15	1		*BOOT REFLECTOR LAMP LH	Serviceable	277.70 FL	-	*- FL
16	1		*BOOT BADGE RENAULT	Not Necessary	82.40 FL	-	*- FL
17	1		*BOOT BADGE	Not Necessary	95.80 FL	-	*- FL
18	1		*BOOT HINGE LH	Repair	254.20 FL	-	*- FL
19	1		*BOOT HINGE RH	Repair	254.20 FL	-	*- FL
20	1		*BOOT STRUT LH	Serviceable	145.10 FL	-	*- FL
21	1		*BOOT STRUT RH	Serviceable	145.10 FL	-	*- FL
22	1		*BOOT LOCK	Repair	246.60 FL	-	*- FL
23	1		*BOOT LOCK CATCH	Repair	41.70 FL	-	*- FL
24	1		*BOOT FINISHER	Serviceable	344.70 FL	-	*- FL
25	1		*SET PARKING AID	Serviceable	700.00 FS	-	*- FS
26	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	-	*66.00 FS
27	1		*FENDER CLIP	Not Necessary	60.00 FS	-	*- FS
28	1		*SET BUMPER BRACKET CTR CLIP	Not Necessary	33.00 FS	-	*- FS
29	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	-	*- FS
30	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	-	*- FS
31	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	-	*- FS
32	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	-	*- FS
33	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	-	*66.00 FS
34	1		*REAR BOOT STICKER TRANS-CAB	Not Necessary	80.00 FS	-	*- FS
35	1		*REAR BOOT STICKER 6555-3333	Not Necessary	80.00 FS	-	*- FS
36	2		*WINDSCREEN SEALANT	Not Necessary	150.00 FS	-	*- FS
37	1		*WINDSCREEN MOULDING	Not Necessary	200.00 FS	-	*- FS
38	1		*WINDSCREEN INNER SPONGE SEAL	Not Necessary	130.00 FS	-	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,055.86	1,670.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	743.09	153.80
Total Parts (\$\$)	8,312.77	1,516.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	440.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	3,000.00	300.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
7	TO DROP REAR EXHAUST BOX,RENEW THE SAME,REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
9	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
11	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	15.00
Gross Labour Cost (\$)			7,580.00	815.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >