

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHD5339A

AAD2112- 055

Not Notified
11/12/21 @ 1850h

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

14 DEC 2021**SHD5339A**

VF1ABL15AUC283342

RENAULT

LATITUDE

10/12/21

Tolo.

31/08/2016

PART

- 1 BUMPER COVER REAR
- 1 BUMPER LOWER REAR
- 1 BUMPER BRACKET CTR REAR
- 1 BUMPER BRACKET SIDE RH REAR
- 1 BUMPER REFLECTOR LH
- 1 BUMPER RETAINER RH REAR
- 1 BUMPER BRACKET SIDE LH REAR
- 1 BUMPER RETAINER LH REAR
- 1 BUMPER BEAM REAR
- 1 OUTER PANEL REAR (End Panel)
- 1 OUTER PANEL REAR (End Panel)TRIM
- 1 TAILLAMP LH
- 1 TAILLAMP RH
- 1 BOOT REAR
- 1 BOOT REFLECTOR LAMP LH
- 1 BOOT BADGE 'RENAULT'
- 1 BOOT BADGE
- 1 BOOT HINGE LH
- 1 BOOT HINGE RH
- 1 BOOT STRUT LH
- 1 BOOT STRUT RH
- 1 BOOT LOCK
- 1 BOOT LOCK CATCH
- 1 BOOT FINISHER

LIST

\$	<i>Per</i> 561.70	✓
\$	<i>Not/Not</i> 411.90	✓
\$	<i>SL</i> 98.10	X
\$	<i>SL</i> 82.10	X
\$	<i>CM</i> 16.60	✓
\$	<i>SL</i> 59.80	X
\$	<i>SL</i> 80.80	X
\$	<i>SL</i> 54.20	X
\$	<i>SL</i> 547.80	✓
\$	<i>N</i> 745.80	X
\$	<i>SL</i> 404.56	X
\$	<i>SL</i> 401.40	} X
\$	<i>SL</i> 401.40	
\$	<i>N</i> 1,677.20	
\$	<i>SL</i> 277.70	
\$	<i>N</i> 82.40	
\$	<i>N</i> 95.80	
\$	<i>N</i> 254.20	
\$	<i>N</i> 254.20	
\$	<i>SL</i> 145.10	
\$	<i>SL</i> 145.10	
\$	<i>N</i> 246.60	}
\$	<i>N</i> 41.70	
\$	<i>SL</i> 344.70	
\$	7,430.86	
10% \$	743.09	
\$	6,687.77	

Trans-cab Auto Services Pte Ltd

AAD2112-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5339A

Special Nett

1SET PARKING AID	\$	700.00	X
1SET REAR BUMPER CLIP	\$	66.00	✓
1 FENDER CLIP	\$	60.00	X
1SET BUMPER BRACKET CTR CLIP	\$	33.00	X
1SET BUMPER BRACKET SIDE CLIP RH RR	\$	10.00	X
1SET BUMPER RETAINER RH CLIP RR	\$	20.00	X
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	10.00	X
1SET BUMPER RETAINER CLIP LH RR	\$	20.00	X
1SET BUMPER LOWER REAR CLIP	\$	66.00	✓
1 REAR BOOT STICKER 'Trans-cab'	\$	80.00	X
1 REAR BOOT STICKER '6555-3333'	\$	80.00	X
2 WINDSCREEN SEALANT	\$	150.00	X
1 WINDSCREEN MOULDING	\$	200.00	X
1 WINDSCREEN INNER SPONGE SEAL	\$	130.00	X
TOTAL	\$	1,625.00	
TOTAL PARTS	\$	8,312.77	

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	4401
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	3001
To Rust-Proofing Of The Affected Areas.	\$	170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	X
To repair and realign rear exhaust pipe.	\$	170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	X

Trans-cab Auto Services Pte Ltd

AAD2112-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5339A

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ 170.00 X

To transfer of rear windscreen fittings and conduct water seepage test.

\$ 170.00 X

To check steering geometry and computer wheel alignment

\$ 220.00 X

To Check Electrical Lighting Concerned.

\$ 170.00 15/

TOTAL \$ 7,580.00**Over All Total \$ 22,580.55****(LUMP SUM)****Repair Days****20 DAYS****2 days****LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer**Signature:****Date:**