

Vin's

Vin's Motor Pte Ltd

160 Sin Ming Drive

#03-03 Sin Ming Autocity

Singapore 575722

Tel : 6456 2121 Fax : 6459 9795

Registration No. 199906067G

Estimated Cost of Repair

Attention To : China Taiping Insurance
(Singapore) Pte Ltd
3 Anson Road
#15-00 Springleaf Tower
Singapore 079909

Claim Details

Case Ref. : Subject to first approval by Insurance Company

Date : 14-12-2021

Accident Date : 13-12-2021

Signature:

Date:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and subject to first approval by Insurance Company

Vehicle Details

Make & Model : Toyota VIOS 1.5 G (AUTO)

Chassis No : MR2B23F3101183644

Registration No : SMN8742L

Third Party Vehicle Details

Registration No : YN9698H

S/N	Description	Qty	Amount (\$\$)
1	FRONT BONNET X <i>nan</i>	1.00	\$751.79
2	FRONT BONNET RH HINGE X <i>nan</i>	1.00	\$53.10
3	FRONT BONNET LH HINGE X <i>nan</i>	1.00	\$53.10
4	FRONT RH HEADLAMP = <i>BR</i>	1.00	\$737.00 ✓
5	FRONT LH HEADLAMP = <i>BR</i>	1.00	\$737.00 ✓
6	FRONT GRILLE BASE	1.00	\$242.40 ✓
7	FRONT GRILLE RH OUTER CHROME = <i>nan</i>	1.00	\$77.80 ✓
8	FRONT GRILLE LH OUTER CHROME = <i>nan</i>	1.00	\$75.20 ✓
9	FRONT GRILLE EMBLEM / <i>nan</i>	1.00	\$66.20 ✓
10	FRONT BUMPER / <i>BR</i>	1.00	\$795.70 486
11	FRONT BUMPER CENTRE GRILLE = <i>BR</i>	1.00	\$93.30 ✓
12	FRONT BUMPER LOWER GRILLE = <i>nan</i>	1.00	\$229.70 ✓
13	FRONT BUMPER RH DAY LIGHT X = <i>BR</i>	1.00	\$653.60 350.5
14	FRONT BUMPER LH DAY LIGHT X = <i>BR</i>	1.00	\$653.60 350.5
15	FRONT BUMPER RH FOG LAMP X	1.00	\$214.20
16	FRONT BUMPER LH FOG LAMP X	1.00	\$214.20
17	FRONT BUMPER RH FOG LAMP COVER X } <i>nan</i>	1.00	\$84.70
18	FRONT BUMPER LH FOG LAMP COVER X	1.00	\$84.70
19	FRONT BUMPER RH SIDE RETAINER X	1.00	\$94.70
20	FRONT BUMPER LH SIDE RETAINER X	1.00	\$94.70
21	FRONT BUMPER REINFORCEMENT X	1.00	\$339.30
22	FRONT BUMPER CLIPS @ \$3.00 - <i>nan</i>	10.00	\$30.00 ✓
23	REAR BOOTLID / <i>nan</i>	1.00	\$685.20 ✓
24	REAR BOOTLID EMBLEM / <i>nan</i>	1.00	\$52.15 ✓
25	REAR BOOTLID "VIOS" EMBLEM / <i>nan</i>	1.00	\$48.25 ✓
26	REAR BOOTLID "G" EMBLEM / <i>nan</i>	1.00	\$34.00 ✓
27	REAR BOOTLID RH REFLECTOR = <i>nan</i>	1.00	\$386.53 ✓
28	REAR BOOTLID LH REFLECTOR = <i>nan</i>	1.00	\$386.53 ✓
29	REAR BOOTLID INNER LOCK / <i>nan</i>	1.00	\$360.42 248.3
30	REAR BOOTLID INNER TRIMBOARD / <i>nan</i>	1.00	\$349.50 221.4

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

31	REAR BOOTLID RUBBER / <i>Tri</i>	1.00	\$160.40 ✓
32	REAR BOOTLID RH NO. PLATE LIGHT ✓ <i>CRA</i>	1.00	\$62.20 ✓
33	REAR BOOTLID LH NO. PLATE LIGHT <i>X NN</i>	1.00	\$62.20
34	REAR RH TAILLAMP <i>= CRA</i>	1.00	\$355.20 ✓
35	REAR LH TAILLAMP	1.00	\$355.20 ✓
36	REAR BUMPER / <i>ee</i>	1.00	\$452.30 ✓
37	REAR BUMPER RH SIDE RETAINER <i>= See</i>	1.00	\$135.90 <i>72.7</i>
38	REAR BUMPER LH SIDE RETAINER	1.00	\$135.90 <i>72.7</i>
39	REAR BUMPER REINFORCEMENT <i>X BT</i>	1.00	\$316.00 ✓
40	REAR BUMPER CLIPS @ \$3.00 <i>- MC</i>	10.00	\$30.00 ✓
41	REAR END PANEL / <i>guc</i>	1.00	\$620.00 ✓
42	REAR END PANEL TOP TRIM / <i>ee</i>	1.00	\$232.00 ✓
43	REAR BUMPER ANTENNA SENSOR / <i>BR</i>	1.00	\$117.10 ✓
44	REAR BUMPER BUZZIE SENSOR <i>X NN</i>	1.00	\$144.90
45	REAR SPARE TYRE PANEL TOP COVER ✓ <i>CUT</i>	1.00	\$390.20 <i>206.9</i>
46	REAR RH FENDER <i>X</i> <i>Repair</i>	1.00	\$872.10
47	REAR LH FENDER <i>X</i>	1.00	\$872.10
48	REAR RH FENDER INNER TRIMBOARD <i>X = See</i>	1.00	\$355.70 ✓
49	REAR LH FENDER INNER TRIMBOARD <i>X = See</i>	1.00	\$355.70 ✓
50	REAR RH FENDER INNER TRIMBOARD CLIPS @ \$3.00 <i>X / MC</i>	20.00	\$60.00 ✓
51	REAR LH MUDFLAG <i>X NN</i>	1.00	\$65.70

Discount: -25%

\$14,829.37 *9362.06*
(\$3,707.34)

52	REAR BUMPER PARKING SENSOR / <i>DM</i>	1.00	\$11,122.03 <i>7021.55</i>
53	FRONT NO. PLATE / <i>BT</i>	1.00	\$280.00 <i>200</i>
54	REAR NO. PLATE / <i>GA</i>	1.00	\$40.00 ✓
55	REAR WINDSCREEN GUM <i>X NN</i>	1.00	\$40.00 ✓
56	TO DIAGNOSE ELECTRICAL COMPONENTS	1.00	\$60.00
57	TO REMOVE AND REFIX ROOF LINING AND SEAT CUSHION	1.00	\$280.00 <i>30</i>
58	TO REMOVE AND REFIX PETROL TANK <i>X</i>	1.00	\$280.00 <i>60120</i>
59	TO REMOVE AND REFIX REAR WINDSCREEN <i>X NN</i>	1.00	\$120.00
60	TO REPAIR DAMAGES	1.00	\$180.00
61	TO SPRAY PAINTING	1.00	\$1,400.00 <i>1200</i>
			\$1,600.00 <i>1500</i>

Subtotal w/o GST:

\$15,402.03 *3130*

10447.05

*8 Days.
p/p. before part photos.
Quoted 15/12/21.*

Issued by Raymond Teo

This is a computer-generated document. No signature is required.