

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKA 9800 M**

**DAMAGED PARTS & PRICES**

| S/N                          | PARTS DESCRIPTION                                                          | QTY | S/NETT             | REMARKS        |
|------------------------------|----------------------------------------------------------------------------|-----|--------------------|----------------|
| 1                            | FRONT BUMPER                                                               | 1   | \$ 2,233.00        | de✓            |
| 2                            | FRONT BUMPER FIXING PARTS                                                  | 1   | \$ 358.00          | X              |
| 3                            | FRONT BUMPER SECURING STRIP ?                                              | 2   | \$ 71.00           | de✓            |
| 4                            | FRONT BUMPER LOWER GRILLE - CENTER                                         | 1   | \$ 196.00          | X              |
| 5                            | FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE ?                              | 1   | \$ 262.00          | de✓            |
| 6                            | FRONT BUMPER AIR GUIDE - LH / RH                                           | 2   | \$ 88.00           | X RH LH me✓    |
| 7                            | FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE                                | 1   | \$ 262.00          | X              |
| 8                            | FRONT BUMPER AIR GRILLE - LH / RH                                          | 2   | \$ 270.00          | RH X LH me✓    |
| 9                            | FRONT BUMPER AIR GRILLE TRIM - LH / RH                                     | 2   | \$ 96.00           | X              |
| 10                           | FRONT RADIATOR GRILLE                                                      | 1   | \$ 1,580.00        | X              |
| 11                           | FRONT BUMPER FOAM FILLER PIECE                                             | 1   | \$ 189.00          | X              |
| 12                           | FRONT BUMPER CARRIER                                                       | 1   | \$ 845.00          | X              |
| 13                           | FRONT BUMPER GUIDE SECTION - LH / RH <del>LH / RH</del> <del>RH / LH</del> | 2   | \$ 72.00           | LH de✓, RH de✓ |
| 14                           | FRONT BUMPER TOP COVER                                                     | 1   | \$ 127.00          | X              |
| 15                           | CAUTION STICKER                                                            | 1   | \$ 14.00           | X              |
| 16                           | A/C STICKER ?                                                              | 1   | \$ 8.00            | X              |
| 17                           | FRONT LOCK CARRIER BRACKET                                                 | 1   | \$ 137.00          | X              |
| 18                           | FRONT BUMPER SUPPORT - LH / RH                                             | 2   | \$ 58.00           | X              |
| 19                           | RIVET                                                                      | 4   | \$ 4.00            | me✓            |
| 20                           | FRONT BUMPER PARKING AID SENSOR - OUTER                                    | 2   | TBC                | X un           |
| <b>SUB TOTAL SPARE PARTS</b> |                                                                            | :   | <b>\$ 6,870.00</b> |                |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKA 9800 M**

|                             |                                         |     | DAMAGED PARTS & PRICES |         |
|-----------------------------|-----------------------------------------|-----|------------------------|---------|
| S/N                         | PARTS DESCRIPTION                       | QTY | S/NETT                 | REMARKS |
| 21                          | FRONT PARKING AID SEAL RING             | 4   | \$ 9.00                | X       |
| 22                          | FRONT BUMPER WIRING SET                 | 1   | \$ 577.00              | X       |
| 23                          | FRONT FENDER - LH / RH                  | 2   | \$ 2,184.00            | bt ✓    |
| 24                          | FRONT FENDER ATTACHMENT PARTS           | 1   | \$ 202.00              | X       |
| 25                          | FRONT FENDER CLOSING ELEMENT - LH / RH  | 2   | \$ 144.00              | new ✓   |
| 26                          | FRONT FENDER BRACKET - LH / RH          | 2   | \$ 70.00               | X       |
| 27                          | RIVET                                   | 12  | \$ 40.00               | new ✓   |
| 28                          | FRONT FENDER BRACE - LH / RH            | 2   | \$ 236.00              | bt ✓    |
| 29                          | FRONT WHEEL HOUSING LINER - LH / RH     | 2   | \$ 477.00              | X       |
| 30                          | FRONT WHEEL SPOILER - LH / RH           | 2   | \$ 146.00              | X       |
| 31                          | FRONT WHEEL SPOILER TRIM - LH / RH      | 2   | \$ 71.00               | X       |
| 32                          | FRONT FENDER TOP COVER - LH / RH        | 2   | \$ 62.00               | new ✓   |
| 33                          | FRONT HEADLIGHT TOP COVER - LH / RH     | 2   | \$ 88.00               | new ✓   |
| 34                          | FRONT HEADLIGHT                         | 2   | \$ 15,370.00           | X       |
| 35                          | FRONT HEADLIGHT LIFT CYLINDER - LH / RH | 2   | \$ 420.00              | X       |
| 36                          | FRONT HEADLIGHT LIFT CYLINDER BRACKET   | 2   | \$ 12.00               | X       |
| 37                          | A/C CORRUGATED PIPE                     | 1   | TBC                    | X       |
| 38                          | A/C REFRIGERANT PIPE                    | 4   | \$ 1,278.00            | X       |
| 39                          | FRONT NO. PLATE                         | S/N | \$ 60.00               | X       |
| 40                          | SUNDRIES                                |     | \$ 300.00              | ?       |
| <b>TOTAL SPARE PARTS</b>    |                                         | :   | <b>\$ 28,616.00</b>    |         |
| <b>TOTAL LABOUR CHARGES</b> |                                         | :   | <b>\$ 7,452.00</b>     |         |
| <b>GRAND TOTAL</b>          |                                         | :   | <b>\$ 36,068.00</b>    |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.