

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 19960/198R GST Reg. No. 19-960/198-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	F	Ref:	CS/AGI21012719/Eqf3n2	
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	С	Date:	14/02/2022	
			C	Code:	AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMT 9252X	Veh. Inspected		PC 9456D	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10012824/CD	Excess (\$)		0.00	
	Assign From	IVY RATILLA	Assign Date		16/12/2021	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA COASTER	c.c		4009	
	Engine No.	HIDDEN	Year of Reg.		2020	
	Chassis No.	JTGFD838106000135	Colour		WHITE	
	Odometer	125088 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	FAIR				
3.						
		Size	Make		Balance	
	R/H Front Tyre	205/75 R17.5	BRIDGESTONE		4 mm	
	L/H Front Tyre	205/75 R17.5	BRIDGESTONE		4 mm	
	R/H Rear Tyre	205/75 R17.5	BRIDGESTONE		4 mm	
	L/H Rear Tyre	205/75 R17.5	BRIDGESTONE		4 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.					
	DAMAGES SEE DETAILS.					
5.	5. General Information					
	Accident Date	07/12/2021	Inspection Date		16/12/2021	
	Survey held at 11 TUAS BAY CLOSE #06-03 WEST STAR					
	Repairer					
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: