

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Mohd Rizal, Nur Mariah Huibrechts

Date: 16 Dec 2021

Preliminary Advice

Vehicle No	: SJG2020Z	Accident Date	: 21/10/2021
Make	: MERCEDES-BENZ A180	Policy No.	: 2070144125
Assignment Date	: 16/12/2021	Excess	: S\$0.00
Date of Inspection	: 15/12/2021	Est. Duration of Repair	: 28
Inspection At	: CYCLE & CARRIAGE INDUSTRIES PL		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	80,747.31
Revised Amount	:S\$	55,405.09
Check Items (Estimated)	:S\$	20,163.73
Total	:S\$	75,568.82

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	135,000.00
COE / PARF Rebate	:S\$	61,346.00
Salvage Value	:S\$	
Margin for Repair	:S\$	73,654.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments : Repairer able to undertake the repair within the Nett Value.

Pending for investigation

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .