

5562010Z

SUPPLEMENTARY

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

## **ESTIMATE FOR**

AIG Asia Pacific Insurance Pte. Ltd MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 64191000

Vehicle & Document Information

54030 WIP No

/ 13/10/2020 Reg No/Reg Date

22/12/2021/-44551---Date In/Mileage W1K1771842J2095682 Chassis No

28291480352860 Engine No

Make/Model MB/A 180

028 859 Mojave Silv/ 041 101 ARTICO Blac Colour/Trim

Date/Time Printed CSE Operator Account No Terms 395 / Yik Chan Hoe 03/03/2023/ 14:53 WA000007 Credit Amount Unit Price Disc% Qty Description of Goods / Services 205.28 184.75 1.00 10,00 FLOOR MAI 3 1.26 10.00 2.27 2.00 HOLE PLUG HE STEERING COLUMN PAST 1466.47 -629.41 10.00 1.00 4 4.00 3.08 10.00 11.09 \ HEXALOBULAR BOLT Tust 34.78 ℃ 10.00 1.00 38.64 SOCKET Daw 12.13 10.00 10.92 -STOWAGE CMPRT. CENT. CONS 1.00 1323.16 -1470.18 10.00 1.00 LINING, REAR FLOOR bornt. 26.58 1.00 29.53 10.00 BRACKET Da 10.10 3.00 3.74 10.00 HEXAGON NUT Da 25.07 27.86 10.00 40A Har RELAY SLOT L 10.00 89.62 -99.58 INTERIOR LAMP Daw 1200 6.61 3.00 2.45 10.00 HEXAGON NUT WITH FLANGE 93.74 -10.00 104.16 1.00 ANTENNA Down 282.13 1.00 313.48 10.00 Din TEMPERATURE SENSOR 1.57 1.41 -1.00 10.00 HEXAGON HEAD BOLT HAC X 7.38 10.00 33.21 5.00 HEX. HEAD BOLT W. FLANGE 940.63 L 1.00 1045.14 10.00 CROSSMEMBER BEHIND DASHBOARD X 1672.66 10.00 1.00 1858.51 FRONT PASSENGER AIRBAG CON X 22.39 1.00 24.88 10.00 COVER, SWIVEL BEARING 1 5.94 L 6.60 10.00 1.00 PLUG SOCKET Da 14.59 L 1.00 16.21 10.00 SCREW HAL 10.00 10.91 L 2.00 6.06 LOCK CLIP HAL X 36.97 ~ 10.27 10.00 4.00 Day HEXALOBULAR BOLT 10.00 6.34 4.00 1.76 X FILLISTER HEAD SCREW HE 2.65 2.95 10.00 1.00 SOCKET Du 4.00 6.75 10.00 24.30 SCREW HL 28.58 L 31.76 10.00 SOCKET Down 1.00 Yik Chan Hoe Cycle & Carriage Industries Pte Ltd DID: 6771 4353 HP; 9186 5190 Fax; 6872 1272 dkk Email: chanhoe.yik@eyelecarriage.comsc Confirmed & accepted by 6,367.87 Nett 6367.87 509.43 8% GST on 6.877.30 Total Payable Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. stimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worm or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6298 1818 Fax: 6779 5383 www.mercedes-benz.com.sg