

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL INV No. AC2108819

64 CECIL STREET INV Date 23/12/2021

#05-02 IOB BUILDING Reference CS3/GRB21012724/Evf3e2 SINGAPORE 049711

NGAPORE 049/11 Code GRB

PROFESSIONAL SERVICE FEE

Vehicle No. FBS 9489R

Insured Veh. SLP 8894H

Claim No. MFL2021D0005203

Policy No. D21MFL0000447

Accident Date 29/11/2021

Inspection Date 16/12/2021

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	120.00
- First Inspection 16.12.2021 04.00pm	
Merimen Fee	11.00
Subtotal	131.00
GST (7%)	9.17
Grand Total	140.17

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

KHM