



Exceptional Journeys

Surveyor : STEVE LKK  
 Claim : AIG OD  
 DOA : 15.12.2021  
 Emailed : 25.01.2022, 3.30pm  
 Date Survey : 16.12.2021

VEHICLE NO : SMZ 7734 D  
 MODEL : KIA CERATO 1.6 A GT  
 WIP : 44064

Material	:	\$	<u>2,408.80</u>
Labour	:	\$	<u>3,060.00</u>
Sub-Total	:	\$	<u>5,468.80</u>
	:	\$	<u>-</u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>5,468.80</u>
GST 7%	:	\$	<u>382.82</u>
Grand Total	:	\$	<u>5,851.62</u>
Finalise By/Date	:	<u>LOI / 25/01/2022</u>	

REVERT BACK WITHIN 7 DAYS,  
 OTHERWISE WILL PROCEED WITH INVOICING

SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 0 WORKING DAYS + 0 Days ( 0 ) Weekends  
 + 0 Days ( 0 ) Public Holiday  
 TOTAL DAYS REPAIR TOOK = 0

TP claim \_\_\_\_\_

Claim GIA / LTA fee \_\_\_\_\_

Claim Loss of  Use /  Rental

Claim Medical Fee / Others \_\_\_\_\_

Third Party Report - \_\_\_\_\_



CYCLE & CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**  
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

**THIS IS NOT AN OFFICIAL TAX INVOICE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 17/12/2021	Cust No/Name	/POH LIONG THIAM FRANCIS
	Reg No/Reg Date	SMZ7734D / 18/05/2021
	Date In/Mileage	16/12/2021/ 9367
	Chassis/Package	KNAF5416MM5102997 /#
	Engine No	G4FGLH713092
	Make/Model	KIA/CERATO 1.6 A GT LINE H370
	Colour/Trim	ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	10/01/2022/ 14:52	BLK	260 / AiTing	44064

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE REAR BUMPER, REAR BOOT, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME				600.00
E PNT98000 RESPRAY ON REAR BUMPER, REAR BOOT, AND ALL OTHER AFFECTED AREAS TO THE SAME				700.00
E PNT88000 REMOVE & INSTALL REAR PARKING ASSIST TO FACILITATE REPAIR				80.00
E PNT88000 TRANSFER REAR BOOT ATTACHMENTS TO NEW PANEL				120.00
M SUNDRY APPLY SEALANT ON AFFECTED AREAS				40.00
M SUNDRY PERFORM RUST PREVENTION ON AFFECTED AREAS				40.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE				120.00
M SUNDRY SUPPLY C & C EMBLEM				40.00
M SUNDRY SUNDRIES				20.00
E PNT88000 REPLACE REAR END PANEL → Supp.				800.00
E PNT88000 REMOVE & REINSTALL REAR COMPARTMENTS TO FACILITATE REPAIR				? 120.00
E PNT98000 RESPRAY REAR END PANEL → Supp.				350.00
X PANEL ASSY-TRUNK LID	1.00	✓ 1297.00	20.00	1037.60
X PANEL ASSY-BACK	1.00	? 324.00	20.00	259.20
X EMBLEM-CERATO	1.00	✓ 28.00	20.00	22.40
X EMBLEM-GT LINE	1.00	✓ 45.00	20.00	36.00


This is not an official tax invoice.  
 This is a computer generated document, no signature is required.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

**THIS IS NOT AN OFFICIAL TAX INVOICE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000  17/12/2021	Cust No/Name	/POH LIONG THIAM FRANCIS
	Reg No/Reg Date	SMZ7734D / 18/05/2021
	Date In/Mileage	16/12/2021/ 9367
	Chassis/Package	KNAF5416MM5102997 /#
	Engine No	G4FGLH713092
	Make/Model	KIA/CERATO 1.6 A GT LINE H370
	Colour/Trim	ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	10/01/2022/ 14:52	BLK	260 / AiTing	44064

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X LOGO ASSY-KIA SUB	1.00	32.00	20.00	25.60
X COVER-RR BUMPER	1.00	651.00	20.00	520.80
X COVER-RR BUMPER LWR	1.00	241.00	20.00	192.80
X BEAM-RR BUMPER	1.00	318.00	20.00	254.40
X STAY-RR BUMPER RH	1.00	65.00	20.00	52.00
X CLIP → <i>Supp</i>	10.00	1.00	20.00	8.00
Z TEXT				
AIG OD CLAIM DOA : 15.12.21 SURVEYOR STEVE - LKK 16.12.21 POLICY NO : 7210049283 REPAIR 4D+2D=6D				

Pro Forma

*Guarantee Your Warranty, Maintain with Cycle & Carriage!*

Parts	2,408.80		Nett	5,468.80
Labour	2,920.00	7% GST on	5468.80	382.82
Standard Menu	0.00			
Specialist Job	0.00		Total Payable	5,851.62
Diagnostics Job	0.00			
Sundry/Others	140.00			
Total(w/o GST)	5,468.80			

This is not an official tax invoice.  
 This is a computer generated document, no signature is required.



Exceptional Journeys

INSURANCE CO. : AIG

Supplementary Parts For Registration No.: SMZ 7734 D

	<u>Materials</u>	<u>Cost (\$)</u>
1	Clips (x10)	10.00 / nec
	Total Materials	10.00
	Less 20% discount	2.00
	Total after discount	8.00

	<u>Labour</u>	<u>Cost (\$)</u>
1	Replace rear end panel	800.00 /
2	Respray rear end panel	350.00 /
	Total labour	1,150.00
	Total amount	1,158.00
	7% GST	81.06
	<b>Grand total</b>	<b>\$ 1,239.06</b>

Thank You.  
Yours faithfully

  
LOI AI TING  
SENIOR OFFICER - ADMIN  
KIA SERVICE CENTRE  
DID : 6568 4556 / 6568 4501  
FAX : 6567 5258 / 6565 1240





# e-Report [Pilot Ver : 1.064]\_20211209



KNAF5416MM5102997 CERATO/FORTE(BD)/2021/G 1.6 MPI GAMMA



## e-Report

## e-Report Case Statistics

eReport Case View

Vehicle Diagnosis Number: 2112280141

List

Prev Page

Date	12/28/2021	Distributor	A22VA	Dealer Code	00001
ServerDate	12/28/2021	Model	CERATO/FORTE(BD)	Engine Type	G 1.6 MPI GAMMA
GDS Version	Source : Content :	Selected Symptom		VIN	KNAF5416MM5102997

Vehicle Information	Unchecked	Warranty History	Unchecked
---------------------	-----------	------------------	-----------

odometer - Information	odometer	Unit	VCI
	9368	km	VCI2_WFD

Total Count: 1

Diagnosis - DTC Codes						
Type	System	Code	Description	FreezeFrame Status	VCI	
Fault Code Searching	Engine		No DTC present at this time		VCI2_WFD	
Fault Code Searching	Transmission		No DTC present at this time		VCI2_WFD	
Fault Code Searching	Brake		No DTC present at this time		VCI2_WFD	
Fault Code Searching	Steering		No DTC present at this time		VCI2_WFD	
Fault Code Searching	Air bag		No DTC present at this time		VCI2_WFD	
Fault Code Searching	Air Conditioner		No DTC present at this time		VCI2_WFD	
Fault Code Searching	Rear View Monitor		Communication Fail / Check whether system is installed or not. Check the keys and DLC		VCI2_WFD	
Fault Code Searching	Cluster Module		No DTC present at this time		VCI2_WFD	
Fault Code Searching	Integrated Body Control Unit B (IM)		No DTC present at this time		VCI2_WFD	
Fault Code Searching	Integrated Body Control Unit I (IMO)		Communication Fail / Check whether system is installed or not. Check the keys and DLC		VCI2_WFD	
Fault Code Searching	Integrated Body Control Unit S (MS)		No DTC present at this time		VCI2_WFD	
Fault Code Searching	Power Seat		No DTC present at this time		VCI2_WFD	
Fault Code Searching	Wireless Power Charger		No DTC present at this time		VCI2_WFD	
Fault Code Searching	Integrated Control Control Unit		No DTC present at this time		VCI2_WFD	

Total Count: 14

S/W Ver.

NEK-00-0009

VCI Ver.

02.63

Res Ver.

NEK-00-0009

OS Ver.

Android 11