



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**  
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/POH LIONG THIAM FRANCIS
	Reg No/Reg Date	SMZ7734D / 18/05/202
	Date In/Mileage	/ 0
	Chassis No	KNAF5416MM5102997
	Engine No	G4FGLH713092
	Make/Model	KIA/CERATO 1.6 A GT LINE H370
	Colour/Trim	ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
LAX00000	Credit	16/12/2021/ 12:53		282 / Kevin Leong	44064	
Description of Goods / Services						
			Qty	Unit Price	Disc%	Amount
E PNT88000		REPLACE REAR BUMPER, BOOT, END PANEL & AFFECTED AREA REPAIR ON FLOOR PANEL				2000.00
E PNT98000		PAINT WORK ON REAR BUMPER, BOOT, END PANEL & FLOOR PANEL				1400.00
E PNT88000		REMOVE & INSTALL REAR PARKING ASSIST				120.00
E PNT88000		TO TRANSFER REAR BOOT ATTACHMENTS TO NEW PANEL				120.00
E PNT88000		TO REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR				120.00
M SUNDRY		TO APPLY SEALANT ON AFFECTED AREA				80.00
M SUNDRY		PERFORM RUST PREVENTION				40.00
A 54900099		CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00
A 10028901		TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				120.00
M SUNDRY		TO SUPPLY C & C EMBLEM				40.00
M SUNDRY		SUNDRIES				40.00
M PANEL ASSY-TRUNK LID						
M PANEL ASSY-BACK			1.00	1297.00	20.00	1037.60
M EMBLEM-CERATO			1.00	324.00	20.00	259.20
M EMBLEM-GT LINE			1.00	28.00	20.00	22.40
M LOGO ASSY-KIA SUB			1.00	45.00	20.00	36.00
M COVER-RR BUMPER			1.00	32.00	20.00	25.60
M COVER-RR BUMPER LWR			1.00	651.00	20.00	520.80
M COVER-RR BUMPER FOG LAMP,RH			1.00	241.00	20.00	192.80
M LAMP ASSY-SIDE T/SIGNAL,RH			1.00	88.00	20.00	70.40
M EXTN WIRING ASSY-BWS			1.00	181.00	20.00	144.80
			1.00	207.00	20.00	165.60

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**  
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

**ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/POH LIONG THIAM FRANCIS
	Reg No/Reg Date	SMZ7734D / 18/05/202
	Date In/Mileage	/ 0
	Chassis No	KNAF5416MM5102997
	Engine No	G4FGLH713092
	Make/Model	KIA/CERATO 1.6 A GT LINE H370
	Colour/Trim	ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	16/12/2021/ 12:53		282 / Kevin Leong	44064		
Description of Goods / Services							
				Qty	Unit Price	Disc%	Amount
M	BRACKET-RR BEAM UPR MTG,LH			1.00	9.00	20.00	7.20
M	BRACKET-RR BEAM UPR MTG,RH			1.00	9.00	20.00	7.20
M	BRACKET-RR BEAM LWR,CTR			1.00	6.00	20.00	4.80
M	BRACKET-RR BEAM LWR MTG			1.00	6.00	20.00	4.80
M	BEAM-RR BUMPER			1.00	318.00	20.00	254.40
M	ANTENNA ASSY-SMARTKEY			1.00	46.00	20.00	36.80
M	STAY-RR BUMPER LH			1.00	65.00	20.00	52.00
M	STAY-RR BUMPER RH			1.00	65.00	20.00	52.00
M	BRACKET ASSY-RR BPR SIDE UPR,L			1.00	25.00	20.00	20.00
M	BRACKET-ASSY RR BPR SIDE UPR,R			1.00	31.00	20.00	24.80
M	ULTRASONIC SENSOR ASSY-BWS			1.00	163.00	20.00	130.40
M	ULTRASONIC SENSOR ASSY-BWS			1.00	163.00	20.00	130.40
M	ULTRASONIC SENSOR ASSY-BWS			1.00	163.00	20.00	130.40
M	W/STRIP-TRUNK LID OPNG			1.00	100.00	20.00	80.00
M	TRIM ASSY-RR TRANSVERSE			1.00	41.00	20.00	32.80
M	MAT ASSY-LUGGAGE COVERING			1.00	211.00	20.00	168.80

Estimate

Confirm &amp; accepted by

	Nett	7,722.00
7% GST on	7722.00	540.54
<b>Total Payable</b>		<b>8,262.54</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.