

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: India International Insurance Pte Ltd 64 Cecil Street #04-00 IOB Building Singapore 049711	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
---	---

Attn: Derrick Tan Ming Chye

Date: 17 Dec 2021

Preliminary Advice

Vehicle No	: SKS5437K	Accident Date	: 28/11/2021
Make	: MITSUBISHI OUTLANDER	Policy No.	: D20MFL0000326_01
Assignment Date	: 16/12/2021	Excess	: S\$0.00
Date of Inspection	: 16/12/2021	Est. Duration of Repair	: 4
Inspection At	: COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL) 205 BRADDELL ROAD SINGAPORE 579701		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,982.50
Revised Amount	:S\$	3,542.30
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,542.30

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	50,000.00
COE / PARF Rebate	:S\$	35,626.00

Salvage Value	:S\$
Margin for Repair	:S\$ 14,374.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : The vehicle repair on Lump Sum basis.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.