

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Estimate

Vehicle No: SLD9395M
 Make and model: Mazda 6
 Chassis : JM6GJ1072G0239365

Qty Spare partsList price

2016

1	RH front door	\$	975.20	975.20	DDV
1	RH front door weatherstrip	\$		143.10	NDX
1	RH front door outer handle with sensor	\$		212.60	NDX
1set	RH rear door inner trim board clips	\$		70.00	NNX
1	RH front door frame black tape	\$		✓ 32.20	NECV
1	RH rear door	\$	958.60	958.60	DDV
1	RH rear door weatherstrip	\$		143.10	NDX
1	RH rear door lock	\$	180.00	222.90	JMV
1	RH rear door lock catch	\$		27.50	NDX
1	RH rear door inner trim board	\$	595.00	2,025.90	BRV
1set	RH rear door inner trim board clips	\$	30.00	70.00	NECV
1	RH rear door glass regulator gear	\$		✓ 149.90	BTV
1	RH rear door glass regulator gear motor	\$		166.70	NDX
1	RH rear door upper hinge	\$		✓ 44.80	BT
1	RH rear door lower hinge	\$		✓ 44.80	BT
1	RH rear door outer handle	\$		78.80	CUTXR
1	RH rear door outer moulding	\$		80.40	NSX
1	RH rear door frame black tape	\$		✓ 32.20	NECV
1	Rear windscreen glass rubber moulding	\$		117.10	NDX
1	RH rear fender	\$		✓ 1,120.50	DDV
1	RH rear fender splash shield	\$		✓ 56.80	BRV
1set	RH rear fender splash shield clips	\$	30.00	50.00	NECV
1	RH rear fender quarter garnish	\$		✓ 54.20	BRV
1	RH rear fender inner trim board	\$		342.10	NDX
1	RH side rocker panel lower garnish	\$		✓ 532.10	DDV
1	Rear bumper	\$	1055.20	1,129.50	BRV
1set	Rear bumper clips	\$	30.00	70.00	NECV
1	Rear bumper RH side retainer	\$		✓ 45.30	NECV
1	Rear bumper LH side retainer	\$		✓ 45.30	NECV
1	RH rear sport rim (original)	\$	200.00	1,291.30	CUTXR
1	RH rear lower arm	\$	233.60	247.70	DDV
1	RH rear upper arm	\$	188.40	241.70	DDV
1	RH rear knuckle arm	\$	291.50	724.80	DDV
1	RH rear wheel bearing	\$	291.50	480.80	JMV
1	RH rear shock absorber	\$	200.80	322.20	JMV
1	RH rear trailing arm	\$		✓ 320.20	DDV
1	RH taillamp assy	\$		1,292.30	NDX

~~Local repair~~ 800

\$ 7,744.50 13,962.60
 -20% \$ 1,548.90 2,792.52
 \$ 6,195.60 11,170.08

Qty Spare parts

- 1 Rear windscreen glass sealant
- 1 Rear windscreen glass inner seal
- 1 RH rear fender joint sealant
- 1 RH rear tyre
- 1 Brake fluid

Special Nett price

\$ 30.00	70.00 NECV
\$ 30.00	50.00 NECV
\$ 30.00	70.00 NECV
\$	350.00 NDX
\$	55.00 NNX
<u>90.00</u>	

Labour and painting

Labour charges to remove, check, replace and reinstall damages bodyparts.
 To panel beating, cut / weld and re-align all affected panels

\$ 800.00 1,400.00 ✓

Spray painting on affected panels

\$ 1,000.00 ~~1,300.00~~ ✓

Check wiring and lighting system

\$ 60.00 } NNX

Apply rust coating chemical on affected panels

\$ 120.00 } NNX

Remove and replace RH front door inner components to assist repair

\$ 120.00 NNX

Remove and replace RH rear door inner components to assist repair

\$ 80.00 120.00 ✓

Remove, reinstall and replace rear inner trims, garnish, roof lining, seats, carpet and boards to assist repair

\$ 380.00 NNX

Remove and reinstall rear bumper reverse sensors to assist repair

\$ 60.00 100.00 ✓

Conduct and adjust wheel alignment system

\$ 60.00 120.00 ✓

Remove and replace rear undercarriage parts to assist repair

\$ 200.00 350.00 ✓

Reset and diagnose control unit after repair

\$ 250.00 NNX

7,200.00
 Total: \$ 16,085.08

Survey 16/12/2021
 Resurvey 17/12/2021
 TGLim Lim
 1400hrs 1350hrs
 Lump sum repair
 Repair days 6

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LS 6750/2
 TGLim Lim
 26/12/2021

Parts 6,195.60
 SN 90.00
 Labour 2,200.00
8485.60
 @20% 1,697.12
6788.48