

Re: SLV2734U AIG OD

Denise Tay (LKKAuto) <denisetay@lkkauto.com>

Mon 3/1/2022 10:32 AM

To: Jenny Lim <jenny.lim@laihuat.com.sg>

Cc: SUR <sur@lkkauto.com>

Hi Jenny,

excess at \$1000

Best Regards,

Denise Tay | Case Handler**LKK Auto Consultants Pte Ltd**Phone: [6256-3561](tel:6256-3561) | email: denisetay@lkkauto.com | fax: [6256-4315](tel:6256-4315)

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto)**Sent:** Wednesday, 29 December 2021 3:41 pm**To:** Jenny Lim <jenny.lim@laihuat.com.sg>**Cc:** SUR <sur@lkkauto.com>**Subject:** SLV2734U AIG OD

Dear Sir/Madam,

As instructed by our client, please proceed to repair the insured vehicle **SLV2734U** (Excess \$TBA/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserves their rights not to pay if there is no valid approval obtained before repair.**Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after repair**

Best Regards,

Denise Tay | Case Handler**LKK Auto Consultants Pte Ltd**Phone: [6256-3561](tel:6256-3561) | email: denisetay@lkkauto.com | fax: [6256-4315](tel:6256-4315)

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)