



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL

INV No. AC2108244

64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV Date 29/11/2021
Reference CS3/GRB21011895/R1tf3e2
Code GRB

PROFESSIONAL SERVICE FEE

Vehicle No. SMA 9534H Bill cancel refer to new invoice No. AC2108920 29/12/2021 \$261.00
Insured Veh. SMK 2525C
Claim No. MFL2021D0005121
Policy No. D21MFL0000447
Accident Date 23/11/2021
Inspection Date 24/11/2021

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	120.00
- First Inspection 24.11.2021 11.36am	
Merimen Fee	11.00
Subtotal	131.00
GST (7%)	9.17
Grand Total	140.17

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL

INV No. AC2108920

64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV Date 29/12/2021
Reference CS3/GRB21011895/R1tf3e2-
1
Code GRB

PROFESSIONAL SERVICE FEE

Vehicle No. SMA 9534H
Insured Veh. SMK 2525C
Claim No. MFL2021D0005121
Policy No. D21MFL0000447
Accident Date 23/11/2021
Inspection Date 24/11/2021

Description	Total
Survey Inspection	250.00
Digital Photographs	
Transportation	
Merimen Fee	11.00
Note: Pls discard Inv.AC2108244 dated 29/11/2021 \$140.17	
Subtotal	261.00
GST (7%)	18.27
Grand Total	279.27

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM