

ASSURE AUTO ASSIST PTE LTD

23 Tuas Avenue 18 Singapore 638902

Tel: 6385 1171

BUS. REG. NO. 201919143Z

15th Dec 2021

Our Ref: SMA9534H

Your Ref: SMK2525C

India International Insurance Pte Ltd

Motor Claims Department

64 Cecil Street

#04-05 IOB Building

Singapore 049711

Dear Sirs,

ACCIDENT INVOLVING SMA9534H AND SMK2525C ALONG THOMSON ROAD ON 23.11.2021.

We are the representative for Law Leong Tat, whose vehicle registration number **SMA9534H** was damaged in the above accident.

We are instructed to claim for damages against your insured in connection with the above-captioned road traffic accident driven by your insured.

We are instructed that the accident was caused by your insured's negligence and/or management of motor vehicle registration **SMK2525C**. As a result of the accident, our client's vehicle was damaged and our client had been put to loss and expense, particulars of which are as follows:-

Cost of repairs	\$ 4,922.00 (inclusive of 7% GST)
Loss of use for 04 days @\$120.00/day	\$ 480.00
Survey report	\$ 538.00
LTA search fee	\$ 7.45
	<u>\$ 5,947.45</u>

Enclosed are the supporting documents for your perusal:-

GIA

Repair bill

Kindly let us have your payment of **\$5,947.45** in our workshop's name within the next 14 days.

Please do not hesitate to contact Ms Irene at 6385 1171 or email motor@iaconsultingsg.com should you have any queries on your matter. We thank you for your kind attention and appreciate your quick remittance.

Yours faithfully,

Encl.


LETTER OF AUTHORITY

We/I, Low Leong Tat ("the third party claimant") of UEN/NRIC No. S8434724 H, owner of vehicle Reg.No SMA 9534 H hereby authorize M/s Assure Auto Assist Pte Ltd ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use and/or survey fee ("claim") for my vehicle no. SMA 9534 H that was damaged pursuant to the accident which occurred on 23/11/2021 along Thomson Road involving vehicle no/s SMK 2525C ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this _____ of _____ 20____



Signed by the third party claimant



> Back to OneMotoring



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 23 Nov 2021 / 14:02:23

Receipt Date/Time : 23 Nov 2021 / 14:02:23

Tax Invoice/Receipt

Receipt No. : ITNET-00000-211123-002010

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SMK2525C As at 23 Nov 2021/12:00:00 Insurance Co: INDIA INT'L INS PTE LTD				
1	Insurance Enquiry - SMK2525C Enquiry Fee 20211123140104396658	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
20211123140112213		Direct Debit: eNETS Debit (Internet Banking)		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

ASSURE AUTO ASSIST PTE LTD

23 Tuas Avenue 18 Singapore 638902

Tel: 6385 1171

BUS. REG. NO. 201919143Z GST.REG.NO.201919143Z

TAX INVOICE


To: Law Leong Tat

Invoice No. : AA20146
Date : 10.12.2021
Vehicle No. : SMA9534H

No.	Description	Qty	Unit Price	Amount
1	REPAIR COST		\$ 4,600.00	\$ 4,600.00
Sub-Total				\$ 4,600.00
GST 7%				\$ 322.00
Total				\$ 4,922.00

Payment by cheque should be crossed and made payable to 'Assure Auto Assist Pte Ltd'

Issued By:


.....
Authorised Signature

Our reference: 21-8342

Date: 5/12/2021

INVOICE NO. 8342

Law Leong Tat

c/o Assure Auto Assist Pte Ltd
23 Tuas Avenue 18
Singapore 638902

Registration No. **SMA9534H**

We enclose our fee note for your kind attention, which remains payable irrespective of the outcome of this case.

S/No.	Description of Services Provided	Qty	Amount
1	Being vehicle damage assessment report, inspection, photographs, transport and miscellaneous.	1	\$ 538.00
Total amount			<u>\$ 538.00</u>

Please kindly cross all cheques made payable to "Impact Analysis Consultant".

We thank you in anticipation for your prompt payment.



L. L. Tan (Ms)

Principal Consultant

Subsidiaries of Impact Analysis Consultant:

• Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd
• IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd
www.iaconsultingsg.com

Our reference: 21-8342

Date: 5/12/2021

c/o Assure Auto Assist Pte Ltd
23 Tuas Avenue 18
Singapore 638902

Dear Sirs

**RE: Road Traffic Accident on 23/11/2021
Law Leong Tat**

In accordance with your instructions received in this office on **24/11/2021**, we made arrangements to examine the vehicle on **24/11/2021** at above-mentioned address. The following data was recorded:


Vehicle details

Make	Hyundai	Registration	SMA9534H
Model	Elantra	Chassis	KMHD841CMJU684373
Colour	Black	Gearbox	Auto
Odometer	74715km	Paintwork	Good
Steering	In order	Brakes	In order
Condition	Good		

Tyre Depths

Front left	195/65R15	85% Yokohama
Front right	195/65R15	85% Yokohama
Rear left	195/65R15	85% Yokohama
Rear right	195/65R15	85% Yokohama

Impact Direction & Area of Damage:



Status	REPAIRABLE
Magnitude	Medium
Legal status	Unroadworthy

Following our examination of the accident damage, we have calculated repair times and method, which are detailed on page 2 & 3. We would recommend a sum of **\$4,600.00** and **6** working days for repair, which is sufficiently lower than the pre accident value to render the vehicle an economically and physically reliable proposition.

Subsidiaries of Impact Analysis Consultant:

• Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd
• IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd
www.iaconsultingsg.com

Our reference 21-8342
Date 5/12/2021
Page 2

Section A: Damaged Parts Assessment

Part's Description	Qty	Condition As inspected	Repairer's Estimate	Our Adjustment
List Items:				
Boot lid	1	buckled.warped.bent	1890.00	1890.00
Boot lid hinges @\$98.50	2	reset	197.00	0.00
Boot lid top lock	1	bent-in	215.80	215.80
Boot lid emblem Elantra	1	necessary	45.00	45.00
Boot lid logo	1	necessary	41.20	41.20
Boot lid inner trim	1	reuse	228.50	0.00
Boot lid reflector @\$215.00	2	intact.refix	430.00	0.00
Boot lid weatherstrip	1	ripped.nec	199.40	199.40
Rear bumper	1	deformed.cracked	589.40	589.40
Rear bumper side retainer @\$36.90	2	reuse	73.80	0.00
Rear bumper reinforcement	1	bent	395.40	395.40
Rear bumper reflector @\$99.50	2	lh broken rh reuse	199.00	99.50
Rear bumper lower lid	1	holder broken	422.00	422.00
Tail lamp @\$401.00	2	intact.refix	802.00	0.00
Rear end panel	1	repair	485.12	0.00
Rear end panel top garnish	1	deformed	177.00	177.00
Rear fender inner trim @\$265.00	2	serviceable	530.00	0.00
Sub- Total costs			6920.62	4074.70
Percentage discount : 20%			1384.12	814.94
Sub-Total costs for parts			5536.50	3259.76

Special Nett Items:

Reverse sensor	set	malfunction	250.00	250.00
Rear bumper clips	set	necessary	50.00	50.00
Rear end panel sealant	1	necessary	40.00	40.00
Rear end panel top garnish clips	set	necessary	15.00	15.00
Sub-Total costs for parts			355.00	355.00

Parts Repair

*	*	0.00	0.00
Sub- Total costs		0.00	0.00
Total costs for parts		5891.50	3614.76

Subsidiaries of Impact Analysis Consultant:

• Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd
• IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd
www.iaconsulting.sg.com

Our reference 21-8342

Date 5/12/2021

Page 3

Section B: Labour Cost Calculation

	Hourly rate	19	Total
To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mentioned on the 'Parts Repair' column inclusive of replacement parts.	\$ 45.00	15	\$ 675.00
Putty & Spray painting to adjacent panels. Job allowance. Paint / material. (4 panels)	Sub-contract work.		\$ 800.00
Apply rust proofing on the adjacent panels.	Sub-contract work.		\$ 50.00
Remove and replace rear bumper reverse sensor & conduct distance safety setting.	\$ 45.00	1.7	\$ 76.50
Conduct water leak test for rear portion associated repair works	\$ 45.00	1	\$ 45.00
Transfer of existing boot lid to new boot lid and refit the same	\$ 45.00	2	\$ 90.00
Wiring and bulb checking	\$ 45.00	0.8	\$ 36.00
Total labour cost			\$ 1,772.50

Manhour rate and the number of manhours required for each repairing task are formulated based on 'individual workshop' operating cost and in-house@ IA Research Guidelines respectively.

Our reference 21-8342

Date 5/12/2021

Section C: Summary Table of Total Repair Cost

Description		Cost	
Damaged Parts Assessment (See section A)		\$3,614.76	
Further discount	20%	\$722.95	
Recommended cost of parts replacement		\$2,891.81	(1)
Labour Cost Calculation (See section B)		\$1,772.50	(2)
Total Repair Cost (Round off to hundred)		\$4,600.00	(1) + (2)

We would recommend a sum of \$4,600.00 and 6 working days for repair.
No further items will be approved without our expressed written agreement. Any significant additional items will be subject to a supplementary report.


Mechanical Engineer, Accident Expert Witness, Licensed Appraiser (Automobile)
B.Eng. (Hons, NUS)
Diploma.Mechanical Engineering
NTC-2 Automovite Technology
Sr.MIES, Institution of Engineers, Singapore (#20100091)
MATAI, Maryland Association of Traffic Accident Investigators
IAARS, International Association of Accident Reconstruction Specialists
PMC of Singapore Business Advisors & Consultants Council
ACTA certified Trainer, Singapore
Enterprise Singapore - Recognised Certification for Management Consultants
IMI Professional Certificate In Vehicle Accident Damage Assessment (UK)

Subsidiaries of Impact Analysis Consultant:

- Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd
 - IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd
- www.iaconsultingsg.com

