

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel: 62898126 Fax : 62870590

Email: Jin@jinauto.com.sg

Company Reg No:200704370C GST Reg No :200704370C

roc. lie

20/12/2021

M/S INDIA INTERNATIONAL INSURANCE

DEAR SIR/MADAM

ESTIMATE REPAIR COST FOR VOLVO XC90 T5 - SMX498S

DOA : 11/12/2021

S/N	QTY	DESCRIPTION			
1	1 PC	REAR BUMPER COVER	R	\$	3345.30 X
2	1 PC	REAR BUMPER LOWER SPOILER	de	\$	1192.30 ✓
3	1 PC	REVERSE SENSOR	su	\$	232.80 X
4	1 PC	REAR BUMPER REINFORCEMENT	R	\$	1750.60 X
5	10 PCS	REAR BUMPER CLIPS	her	\$	60 80.00 ✓
6	1 PC	REAR BUMPER RH RED REFLECTOR	one	\$	106.80 ✓
7	1 PC	REAR BUMPER RH TOW COVER	R	\$	70.80 X
8	1 PC	REAR BUMPER LOWER GARNISH	de	\$	878.80 ✓
				\$	7657.40
				Disc - 10%	\$ -765.74
				\$	6891.66
9		LABOUR CHARGE		\$	580.00 320
10		SPRAY PAINTING		\$	780.00 400
11		WIRING		\$	50.00 20
				\$	8301.66
				Total	\$ 8301.66

LKR Auto Consultants, hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not allowed
deu
1/5 = 2200/
3 days

2-2237-90
102
2014-11
740
2754.1