



Not Notified
 11 Sep @ 3400/r
 Repair After Paint
 5 days



Chen Jianchun
 Blk 249 #09-85 Kim Keat Link
 Singapore 310249

File No : SH/2021/109/12/012/TP
 Date : 23-December-2021

Estimated cost of repair for vehicle no : SLP2009L Toyota Altis

Accident involving vehicle no: SLP2009L & SLA37Y on 15.12.2021

Description	Quantity	Cost Price
Rear boot	1	\$ Bu 725.00 —
Rear boot emblem	1	\$ M 61.90 —
Rear boot chrome moulding	1	\$ S 352.80 X
Rear boot badge "corolla"	1	\$ M 67.80 —
Rear boot badge "Altis"	1	\$ M 61.90 —
Rear boot inner lock 281	1	\$ M 352.00 —
Rear boot weatherstrip	1	97.30 \$ M 194.60 50 bin
RH Rear boot inner tail lamp	1	\$ S 270.10 X
LH Rear boot inner tail lamp	1	\$ S 270.10 X
RH Rear boot hinge	1	\$ R 70.70 X
LH Rear boot hinge	1	\$ R 70.70 X
Rear bumper	1	\$ Bu 480.50 —
Rear bumper clips (1 set)	1	\$ M 28.00 —
Rear bumper reinforcement	1	\$ R 386.00 —
RH Rear bumper retainer	1	\$ D 91.70 —
LH Rear bumper retainer	1	\$ D 91.70 —
RH Rear bumper bracket	1	\$ R 93.70 X
LH Rear bumper bracket	1	\$ R 93.70 X
Rear end panel 562.10	1	\$ R 645.30 —
Rear end panel top ganrish	1	\$ M 197.10 —
Rear end panel top ganrish clips (1 set)	1	\$ M 35.00 —
RH outer tail lamp	1	\$ CM 379.65 —
LH outer tail lamp	1	\$ S 379.65 X
	258	\$ 5,399.60
	Less 20%	\$ 1,079.92
		\$ 4,319.68
Rear number plate	1	S. Nett \$ P 45.00 X
Rear parking sensors (1 set)	1	S. Nett \$ Short 260.00 200 bin

To remove rear damaged parts, to jack out rear end panel and rear floor panel and cut out body panel, to reweld, reshape and repair rear end panel, rear floor panel, rear body panel, RH and LH rear fender, to straighten out rear chassis member, to replace damaged parts and adjust rear body and tailgate alignment

\$ 750.00 600

To spray paint affected rear and inner damaged portion inclusive of preparatory works and material

\$ 1,100.00 800

To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality

\$ 25.00 20

To apply anti-corrosion Tuff-Kote

\$ 100.00 60

\$ 6,599.68

T/Party: AIG Asia Pacific Insurance Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: