



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SGX48D

INDIA INTERNATIONAL INSURANCE P/L

ATTN: MOTOR CLAIM DEPARTMENT
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711
63476100

Vehicle & Document Information

WIP No **53575**
Reg No/Reg Date **SGX48D / 18/08/2011**
Date In/Mileage **0**
Chassis No **WDD2120472A472255**
Engine No **27186030269788**
Make/Model **MB/E 250 CGI SEDAN (W212)**
Colour/Trim **021 197 Obsidian Bl/ 042 Leather Black/C**

| Account No | Terms | Date/Time Printed | CSE | Operator |
|------------|--------|-------------------|-----|------------------|
| WI000576 | Credit | 24/11/2021/ 15:04 | K0 | 301 / Kerlyn Ong |

| Description of Goods / Services | Qty | Unit Price | Disc% | Amount |
|---------------------------------|-----|------------|-------|--------|
|---------------------------------|-----|------------|-------|--------|

| | | | | |
|--|------|---------|-------|-------------|
| THIS IS NOT AN OFFICIAL TAX INVOICE <i>Handwritten: Paul, Hp 90010068, 27/12/21, before paid</i> | | | | |
| Z REQUEST Customer Request M BINSUN POLICY NO/ACC DATE : 7210074046 // 24/11/2021 DRIVE IN//TP VEHICLE NO. : 24/11/2021 // SLT332U - DATE IN/DATE SURVEY: BY/AUTHORIZED ON : | | | | |
| A BPILAB DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH. | | | | 960 1920.00 |
| A BPIRES RESPRAY REAR BUMPER | | | | 600 980.00 |
| A BPILAB USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT | | | 0.10 | 380.00 |
| A BPILAB DISASSEMBLE AND ADJUST HEAD REST & REFINISH. NETT | | | | 240.00 |
| M REAR BUMPER | 1.00 | 1640.41 | 00.00 | 1640.41 |
| M REAR BUMPER LOWER TRIM | 1.00 | 566.58 | 00.00 | 566.58 |
| M LH/ REAR BUMPER CHROME MOULDING | 1.00 | 137.18 | 00.00 | 137.18 |
| M RH/ REAR BUMPER CHROME MOULDING | 1.00 | 137.18 | 00.00 | 137.18 |
| M CTR/ REAR BUMPER CHROME MOULDING | 1.00 | 184.71 | 00.00 | 184.71 |
| M SENDER UNIT | 2.00 | 366.00 | 00.00 | 732.00 |
| M PARKTRONIC SENSOR SPACER RING | 2.00 | 10.46 | 00.00 | 20.92 |
| M LH/ REAR BUMPER BOTTOM BRACKET | 1.00 | 23.18 | 00.00 | 23.18 |
| M RH/ REAR BUMPER BOTTOM BRACKET | 1.00 | 23.18 | 00.00 | 23.18 |
| M LH/ REAR BUMPER SIDE STABILITY | 1.00 | 42.66 | 00.00 | 42.66 |
| M RH/ REAR BUMPER SIDE STABILITY | 1.00 | 42.66 | 00.00 | 42.66 |
| M REAR CROSS MEMBER | 1.00 | 911.01 | 00.00 | 911.01 |

AKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Date:
Signature:
Acknowledged by Repairer
is subject to final approval from Insurance Company
Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Confirmed & accepted by
No illegal modification(s) is on a "Without Prejudice" basis
Third party survey is on a "Without Prejudice" basis
Parts prices are subject to confirmation
To display damaged part(s) during resurvey
To resurvey before/after spray painting
The Repairer of the following:
Authorized signatory and company stamp

Kerlyn Ong Kai Li

DID : 6771 4420 HP : 9186 5113

Email : kerlyn.ong@cyclecarriage.com.sg

Cycle & Carriage Industries Pte Ltd

Customer Service Centre - Pandan Loop

Nett **7,961.67**
7% GST on **7961.67** **557.32**
Total Payable 8,518.99

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg

