



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SGX48D

INDIA INTERNATIONAL INSURANCE P/L

ATTN: MOTOR CLAIM DEPARTMENT
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711
63476100

Vehicle & Document Information

WIP No 53575
Reg No/Reg Date SGX48D / 18/08/2011
Date In/Mileage / 0
Chassis No WDD2120472A472255
Engine No 27186030269788
Make/Model MB/E 250 CGI SEDAN (W212)
Colour/Trim 021 197 Obsidian B1/ 042 Leather Black/C

Account No	Terms	Date/Time Printed	CSE	Operator
W1000576	Credit	24/11/2021/ 15:04	K0	301 / Kerlyn Ong
Description of Goods / Services				
Qty	Unit Price	Disc%	Amount	

Z REQUEST

Customer Request
M BPN SUN

POLICY NO/ACC DATE : 7210074046 // 24/11/2021
DRIVE IN//TP VEHICLE NO. : 24/11/2021 // SLT332U -
DATE IN/DATE SURVEY:
BY/AUTHORIZED ON :

A BPILAB

DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.

A BPIRES

RESpray REAR BUMPER

A BPILAB

USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO
IDENTIFICATION STANDARD. NETT

A BPILAB

DISASSEMBLE AND ADJUST HEAD REST & REFINISH. NETT

M REAR BUMPER

REAR BUMPER LOWER TRIM

M LH/ REAR BUMPER CHROME MOULDING

RH/ REAR BUMPER CHROME MOULDING

M CTR/ REAR BUMPER CHROME MOULDING

SENDER UNIT

M PARKTRONIC SENSOR SPACER RING

LH/ REAR BUMPER BOTTOM BRACKET

M RH/ REAR BUMPER BOTTOM BRACKET

LH/ REAR BUMPER SIDE STABILITY

M RH/ REAR BUMPER SIDE STABILITY

REAR CROSS MEMBER

KK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1.00	1640.41	00.00	1640.41
1.00	566.58	00.00	566.58
1.00	137.18	00.00	137.18
1.00	137.18	00.00	137.18
1.00	184.71	00.00	184.71
2.00	366.00	00.00	732.00
2.00	10.46	00.00	20.92
1.00	23.18	00.00	23.18
1.00	23.18	00.00	23.18
1.00	42.66	00.00	42.66
1.00	42.66	00.00	42.66
1.00	911.01	00.00	911.01

Kerlyn Ong Kai Li

DID : 6771 4420 HP : 9186 5113

Email: kerlyn.ong@cyclecarriage.com.sg

Cycle & Carriage Industries Pte Ltd

Customer Service Centre - Pandan Loop

Nett 7,961.67
7% GST on 7961.67 557.32

Total Payable 8,518.99

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388