



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SGX48D

INDIA INTERNATIONAL INSURANCE P/L

ATTN: MOTOR CLAIM DEPARTMENT
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711
63476100

Vehicle & Document Information

WIP No **53575**
Reg No/Reg Date **SGX48D / 18/08/2011**
Date In/Mileage **27/12/2021/ 151463**
Chassis No **WDD2120472A472255**
Engine No **27186030269788**
Make/Model **MB/E 250 CGI SEDAN (W212)**
Colour/Trim **021 197 Obsidian Bl/ 042 Leather Black/C**

Account No	Terms	Date/Time Printed	CSE	Operator
WI000576	Credit	30/12/2021/ 11:05	K0	301 / Kerlyn Ong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST				
Customer Request				
M BPNSUN				
POLICY NO/ACC DATE : 7210074046 // 24/11/2021				
DRIVE IN//TP VEHICLE NO. : 24/11/2021 // SLT332U - III				
DATE IN/DATE SURVEY: 27/12/2021 1040 // LKK - RASUL				
DIRECT SETTLEMENT : 10/12/2021 // III - Sherini Pillai				
A BPILAB				960.00
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.				
A BPIRES				600.00
RESPRAY REAR BUMPER				
A BPILAB			0.10	380.00
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT				
A BPILAB				240.00
DISASSEMBLE AND ADJUST HEAD REST & REFINISH. NETT				
A BPILAB				960.00
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.				
A BPIRES				600.00
RESPRAY BOOT LID				
X REAR BUMPER	1.00	1640.41	00.00	1640.41
X REAR BUMPER LOWER TRIM	1.00	566.58	00.00	566.58
X LH/ REAR BUMPER CHROME MOULDING	1.00	137.18	00.00	137.18
X RH/ REAR BUMPER CHROME MOULDING	1.00	137.18	00.00	137.18
X CTR/ REAR BUMPER CHROME MOULDING	1.00	184.71	00.00	184.71
X REAR CROSS MEMBER	1.00	911.01	00.00	911.01
X BOOT LID	1.00	2972.90	00.00	2972.90
X BOOT LID MOULDING	1.00	122.20	00.00	122.20
X GROMMET	3.00	2.64	00.00	7.92
X RIVETED NUT	4.00	4.34	00.00	17.36
X MERCEDES STAR	1.00	49.73	00.00	49.73
X E250 TYPE DESIGNATION	1.00	85.29	00.00	85.29
X STOP	2.00	11.34	00.00	22.68

Confirmed & accepted by

Finalization

7% GST on **Nett 10,595.15**
741.66

Authorized signatory and company stamp

Total Payable 11,336.81

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SGX48D

INDIA INTERNATIONAL INSURANCE P/L

ATTN: MOTOR CLAIM DEPARTMENT
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711
63476100

Vehicle & Document Information

WIP No	53575
Reg No/Reg Date	SGX48D / 18/08/2011
Date In/Mileage	27/12/2021/ 151463
Chassis No	WDD2120472A472255
Engine No	27186030269788
Make/Model	MB/E 250 CGI SEDAN (W212)
Colour/Trim	021 197 Obsidian Bl/ 042 Leather Black/C

Account No	Terms	Date/Time Printed	CSE	Operator
WI000576	Credit	30/12/2021/ 11:04	K0	301 / Kerlyn Ong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
A BPILAB				960.00
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.				
A BPIRES				600.00
RESpray BOOT LID				
X BOOT LID	1.00	2972.90	00.00	2972.90
X BOOT LID MOULDING	1.00	122.20	00.00	122.20
X GROMMET	3.00	2.64	00.00	7.92
X RIVETED NUT	4.00	4.34	00.00	17.36
X MERCEDES STAR	1.00	49.73	00.00	49.73
X E250 TYPE DESIGNATION	1.00	85.29	00.00	85.29
X STOP	2.00	11.34	00.00	22.68

SUPPLEMENTARY

Confirmed & accepted by

7% GST on **Nett 4,838.08** **338.67**

Authorized signatory and company stamp

Total Payable 5,176.75

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg