

Not Authored
11/12/2021

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5697R

AAD2112- 073 -

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

15 DEC 2021

SHD5697R

JTDKB3FUX03074491

TOYOTA

PRIUS

13/12/2021

AIG.

26/10/2018

	PART
1	COVER, REAR BUMPER
1	REINFORCEMENT SUB-ASSY, REAR BUMPER
1	COVER, REAR BUMPER, LOWER
1	GUARD, REAR BUMPER, CENTER
1	SEAL, REAR BUMPER SIDE, LH
1	RETAINER, REAR BUMPER SIDE, LH
1	RETAINER, REAR BUMPER SIDE, RH
1	FILLER, REAR BUMPER EXTENSION, LH
1	FILLER, REAR BUMPER EXTENSION, RH
1	PANEL SUB-ASSY, BACK DOOR
1	PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2
1	PLATE, BACK DOOR NAME, NO.1
1	ORNAMENT SUB-ASSY, BACK DOOR
1	LOCK ASSY, BACK DOOR, W/COURTESY LAMP SWITCH
1	STAY ASSY, BACK DOOR, LH
1	STAY ASSY, BACK DOOR, RH
1	HINGE ASSY, BACK DOOR, LH
1	HINGE ASSY, BACK DOOR, RH
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
1	BOARD ASSY, BACK DOOR TRIM
1	WEATHERSTRIP, BACK DOOR
1	COVER, FLOOR UNDER, NO.1 LH
1	COVER, FLOOR UNDER, NO.2 RH
1	COVER, REAR FLOOR CTR
1	PANEL SUB-ASSY, BODY LOWER BACK
1	COVER, FRONT BUMPER
1	REINFORCEMENT SUB-ASSY, FRONT BUMPER
1	ABSORBER, FRONT BUMPER ENERGY

	LIST
\$	442.60 ✓
\$	332.70 ✓
\$	15.40 ✓
\$	576.30 ✓
\$	88.50 X
\$	116.50 X
\$	117.70 X
\$	123.70 X
\$	123.70 ✓
\$	1,147.80 X
\$	54.60 ✓
\$	54.60 ✓
\$	47.90 ✓
\$	467.00 X
\$	242.50 X
\$	242.50 X
\$	61.00 X
\$	61.00 X
\$	925.60 ✓
\$	259.20 X
\$	372.30 X
\$	175.10 X
\$	241.90 X
\$	229.90 X
\$	650.30 X
\$	516.00 ✓
\$	716.60 X
\$	79.60 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2112-

SHD5697R

- 1 BRACKET, FRONT BUMPER SIDE, LH
- 1 BRACKET, FRONT BUMPER SIDE, RH
- 1 HOOD SUB-ASSY
- 1 HINGE ASSY, HOOD, LH
- 1 HINGE ASSY, HOOD, RH
- 1 GRILLE SUB-ASSY, RADIATOR
- 1 GRILLE, RADIATOR, LOWER NO.1
- 1 EMBLEM ASSY, RADIATOR GRILLE

\$	59.30	X
\$	59.30	X
\$	983.10	✓
\$	58.90	X
\$	58.90	X
\$	346.00	✓
\$	170.10	X
\$	90.80	✓
TOTAL	\$ 10,308.90	
25%	\$ 2,577.23	
	\$ 7,731.68	

Special Nett

- 1SET PARKING AID
- 1SET REAR BUMPER CLIP
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL
- 1 REAR TAILGATE STICKER "Trans-Cab"
- 1 REAR TAILGATE STICKER "6555-3333"
- 1 REAR BUMPER PROTECTOR
- 1SET REAR BUMPER RETAINER CLIP
- 1 REAR NUMBER PLATE WITH HOLDER
- 1 END PANEL TRIM CLIP
- 1SET BUMPER CLIP FRT
- 1SET FRNT BUMPER RETAINER CLIP

\$	700.00	2205u
\$	95.00	50Pa
\$	150.00	X
\$	200.00	X
\$	130.00	X
\$	80.00	305u
\$	80.00	305u
\$	180.00	505u
\$	85.00	X
\$	140.00	X
\$	65.00	X
\$	95.00	505u
\$	85.00	X
TOTAL	\$ 2,085.00	

TOTAL PARTS \$ 9,816.68**LABOUR**

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.

\$ 300.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5697R**AAD2112-**

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,200.00	600
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	nn 180.00	X
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	h 480.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	da 480.00	X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	h 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	h 380.00	X
To check steering geometry and computer wheel alignment	\$	h 220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	300
Towing Fees	\$	nn 150.00	X
Putty And Spray Painting Of The Affected Portion.	\$	2,200.00	800
To reinstall rear bumper parking sensor.	\$	170.00	500
To Check Electrical Lighting Concerned.	\$	170.00	200
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	nn 380.00	X

Trans-cab Auto Services Pte Ltd**AAD2112-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5697R

To transfer of tire, rim and on wheel balancing.	\$	220.00	X
To replace, refix and top up coolant for radiator	\$	170.00	X
To lift-up / out engine with gear box and refit.	\$	440.00	X
To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.	\$	380.00	X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	380.00	X
TOTAL	\$	10,290.00	
Over All Total	\$	20,106.68	

(PART-BY-PART) Repair Days**25 DAYS****5 days****LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: