

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21012755/KPA3Q2**Date:** 17/10/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0007747
Claimant Vehicle No : SKA488R **Insured Vehicle No :** SNB4226M
 Date of Loss: 15/12/2021 Nature of Claim: TP Claim No: MFL2021D0005616

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKA488R**
 Make & Model: NISSAN X-TRAIL, 2.0 CVT ABS 4WD S/R 7-STR (A) Engine No: MR20836475B
 Reg. Date: 29/04/2016 (Man. Year: 2016) Chassis No: JN1JANT32Z0001659
 Colour: Metallic Silver Odometer: 142231 km
 Engine Capacity: 1997 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60 R18 Rear Tyre Size: 225/60 R18
 Front Left Side: Kumho 7 mm Rear Left Side: Kinforest 3 mm
 Front Right Side: Kumho 7 mm Rear Right Side: Kinforest 3 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-------------------|-------------------|-------------------|---------------|
| Parts | 2,085.12 | 1,461.53 | 623.59 | 29.91 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,980.00 | 665.00 | 1,315.00 | 66.41 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 4,065.12 | 2,126.53 | 1,938.59 | 47.69 |
| Approved Total (Overridden) (S\$) | | 1,700.00 | | |
| Nett Amount (S\$) | 4,065.12 | 1,700.00 | 2,365.12 | 58.18 |
| + Loss of Use (4.0 x S\$70.00/day) (S\$) | | 280.00 | | |
| + Doc/Search Fee (S\$) | | 7.45 | | |
| Nett Liability (S\$) | | 1,987.45 | | |

INSPECTION

Date of Assignment: 16/12/2021
 Date Inspected: 17/12/2021 Inspected At: Caris Autoworks Pte Ltd - SIN MING (HQ)
 160 SIN MING DR #05-03 SIN MING AUTOCITY
 Singapore 575722
 Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Feb 2022)

Parts: M1-SUV NISSAN X-TRAIL 2.0 CVT ABS 4WD S/R 7-STR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKA488R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|----------------------------------|---------------|------------|------------|
| 1 | 1 | | *BUMPER (REAR) | Buckled / Cut | 793.10 FL | *693.10 FL |
| 2 | 1 | | *BUMPER REINFORCEMENT (REAR) | Bent | 696.20 FL | *533.80 FL |
| 3 | 4 | | *BUMPER RETAINER (REAR) | Serviceable | 220.40 FL | *- FL |
| 4 | 1 | | *BUMPER STAY (REAR RIGHT) | Distorted | 250.60 FL | *174.80 FL |
| 5 | 1 | | *BUMPER DOOR LOCK STRIKER (REAR) | Repair | 78.10 FL | *- FL |
| 6 | 1 | | *SET PARKING SENSOR (REAR) | Cracked | 250.56 FS | *200.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|-----------------|-----------------|
| Sub Total (\$\$) | 2,288.96 | 1,601.70 |
| - List Item Discount on L Items 10.00/10.00% (\$\$) | 203.84 | 140.17 |
| Total Parts (\$\$) | 2,085.12 | 1,461.53 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|----------------------------|----------|-----------------|---------------|
| Labour Items | | | | |
| 1 | PANEL KNOCKING | New | 1,000.00 | 200.00 |
| 2 | SPRAYPAINTING | New | 800.00 | 400.00 |
| 3 | BODY CLIPS & SCREWS | New | 100.00 | 50.00 |
| 4 | WIRE CHECKING & DIAGNOSTIC | New | 80.00 | 15.00 |
| Gross Labour Cost (\$\$) | | | 1,980.00 | 665.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >