

CARIS AUTOWORKS PTE LTD
160 SIN MING DRIVE
#05-03 SIN MING AUTOCITY
SINGAPORE 575722
(COMPANY REGISTRATION NO: 200923135D)
TEL: 62589831
FAX: 62585349

*Not Authorized
6/10/07 @ 1700h
Penny After Rain
3 days*

ESTIMATE REPAIR COST FOR NISSAN (X-TRAIL 2.0) REG NO : SKA 488 R

S\$

1 PC	BUMPER (REAR)	693.10	Bumper	793.10	✓
1 PC	BUMPER REINFORCMENT (REAR)	533.80	Br	696.20	✓
4 PCS	BUMPER RETAINER (REAR)(PER PC \$55.10)		Pin	220.40	X
1 PC	BUMPER STAY (REAR RIGHT)	174.80	Dis	250.60	✓
1 PC	BUMPER DOOR LOCK STRIKER (REAR)		rc	78.10	X
1 SET	PARKING SENSOR (REAR)		cmf	278.40	2005m

TOTAL 2316.80
LESS 10% 231.68
TOTAL 2085.12

LABOUR & MISC CHARGES

PANEL KNOCKING	1000.00	2001
SPRAY PAINTING	800.00	4001
BODY CLIPS & SCREWS	100.00	501
WIRE CHECKING & DIAGNOSTIC	80.00	151

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer 1
Signature:
Date:

TOTAL 4065.12