



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
INDIA INTERNATIONAL INSURANCE SINGA 64 CECIL STREET #04-05 IOU BUILDING SINGAPORE 049711	Cust No/Name KCV15414/Mr Leow Yu Lung(Liao Yulong) Reg No/Reg Date SMS2915T / 20/02/2020 Date In/Mileage 15/12/2021/ 24911 Chassis No GF7W0601711 Engine No 4J11BD7811 Make/Model MIT/19MY OUTLANDER 2.0 ELEG (995) Colour/Trim P02 / BK
Contact No	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000036	Credit	15/12/2021/ 10:27	DS	303 / Renemer	23672
Description of Goods / Services	Qty	Unit Price	Disc%	Amount	
Z NOTES ACCIDENT ON 14/12/2021 ALONG PUNGGOL CENTRAL ROAD OWNER CLAIMING THIRD PARTY REQUIRED REPLACEMENT CAR TP#: GBG1949X TP INS: INDIA INT'L INS				✓ 250.00	✓
S MIPNT88088 DIAGNOSTIC/SCANNING				80 100.00	✓
S MIPNT88088 TO CHECK ALL LIGHTING/WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS				X 640.00	
S MIPNT88088 TO REMOVE & RE-INSTALL ALL CARPETS/TRIMMING TO FACILITATE REPAIR ON REAR ACCIDENT AFFECTED AREAS				X 200.00	
S MIPNT88088 TO APPLY SEALANT KIT ON NEW & REPAIR PANELS	1280			640 1920.00	
S MIPNT88088 TO REPLACE REAR BUMPER, CLIPS, BRACKETS, EXTENSION BUMPER, REFLECTOR LAMP, ANTENNA, BUZZER, ETC -TO REPAIR REAR END PANEL STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS	1100			550 1650.00	
S MIPNT98088 SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS				280.00	
S MIPNT88088 REVERSE SENSOR (ITEMS & INSTALLATION INLCUDED)				✓ 150.00	
S MIPNT88088 REAR BUMPER PLATE PROTECTOR (OWNER PURCHASED)					
M JJ6410D738 FACE, RR BUMPER	1.00	✓ 799.00	10.00	719.10	
M JJMR200300 CLIP, BUMPER	10.00	40 4.00	10.00	36.00	
M JJ6410D336 LH SIDE BRACKET, RR B	1.00	12.00	10.00	10.80	
M JJ6410D337 RH SIDE BRACKET, RR B	1.00	12.00	10.00	10.80	
M JJ6415A090HA EXTENSION, RR BUMPER	1.00	✓ 360.00	10.00	324.00	
M JJ8336A153 LH REFLECTOR, TAIL LA	1.00	100.00	10.00	90.00	
M JJ8336A154 RH REFLECTOR, TAIL LA	1.00	100.00	10.00	90.00	
M JJ8637B115 ANTENNA, KEYLESS OPER	1.00	96.00	10.00	86.40	

Confirm & accepted by

1199

2950

4149

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE



CYCLE & CARRIAGE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
INDIA INTERNATIONAL INSURANCE SINGA 64 CECIL STREET #04-05 IOU BUILDING SINGAPORE 049711	Cust No/Name KCV15414/Mr Leow Yu Lung(Liao Yulong) Reg No/Reg Date SMS2915T / 20/02/2020 Date In/Mileage 15/12/2021/ 24911 Chassis No GF7W0601711 Engine No 4J11BD7811 Make/Model MIT/19MY OUTLANDER 2.0 ELEG (995) Colour/Trim P02 / BK
Contact No	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000036	Credit	15/12/2021/ 10:27	DS	303 / Renemer	23672

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M JJ8637A176 BUZZER,KEYLESS OPERA X NN	1.00	91.00	10.00	81.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications, allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4 Days.

before paint photos.

Quo @ ian - 8288 0282

20/12/21

Confirm & accepted by

Parts	1,449.00
Labour	0.00
Standard Menu	0.00
Specialist Job	5,190.00
Others(Lub,etc)	0.00
Sundry	0.00
Total(w/o GST)	6,639.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.