



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2207021

3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV Date 14/12/2022  
Reference CC6/CTI21012757/Tpa3q2  
Code CTI

### PROFESSIONAL SERVICE FEE

Vehicle No. SJM 301U  
Insured Veh. PC 6568J  
Claim No. SNM21D207311/C02  
Policy No. DMB1SNW00005722100  
Accident Date 15/12/2021  
Inspection Date 15/12/2021

| Description                    | Total         |
|--------------------------------|---------------|
| Third Party Express Settlement | 400.00        |
| <b>Subtotal</b>                | <b>400.00</b> |
| <b>GST (7%)</b>                | <b>28.00</b>  |
| <b>Grand Total</b>             | <b>428.00</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                              |                 |                                                              |  |
|----------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------|-----------------|--------------------------------------------------------------|--|
| CHINA TAIPING INSURANCE (S) PTE LTD<br>3 ANSON ROAD #16-00<br>SPRINGLEAF TOWERSINGAPORE 079909                                         |                                                                                              |                 | Ref: CC6/CTI21012757/Tpa3q2<br>Date: 14/12/2022<br>Code: CTI |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                              |                 |                                                              |  |
| Insured Veh.                                                                                                                           | PC 6568J                                                                                     | Veh. Inspected  | SJM 301U                                                     |  |
| Policy No.                                                                                                                             | DMB1SNW00005722100                                                                           | Coverage (\$)   | 0.00                                                         |  |
| Claim No.                                                                                                                              | SNM21D207311/C02                                                                             | Excess (\$)     | 0.00                                                         |  |
| Assign From                                                                                                                            |                                                                                              | Assign Date     | 15/12/2021                                                   |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                              |                 |                                                              |  |
| Make & Model                                                                                                                           | TOYOTA HARRIER G                                                                             | c.c             | 1998                                                         |  |
| Engine No.                                                                                                                             | HIDDEN                                                                                       | Year of Reg.    | 2018                                                         |  |
| Chassis No.                                                                                                                            | JTEKB3GH00J002398                                                                            | Colour          | BLACK                                                        |  |
| Odometer                                                                                                                               | 73694 KM                                                                                     | Steering        | IN ORDER                                                     |  |
| Brakes                                                                                                                                 | IN ORDER                                                                                     | Modification    | SPORTS RIM                                                   |  |
| General                                                                                                                                | GOOD                                                                                         |                 |                                                              |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                              |                 |                                                              |  |
|                                                                                                                                        | Size                                                                                         | Make            | Balance                                                      |  |
| R/H Front Tyre                                                                                                                         | 235/55 R18                                                                                   | MICHELIN        | 6 mm                                                         |  |
| L/H Front Tyre                                                                                                                         | 235/55 R18                                                                                   | MICHELIN        | 6 mm                                                         |  |
| R/H Rear Tyre                                                                                                                          | 235/55 R18                                                                                   | MICHELIN        | 6 mm                                                         |  |
| L/H Rear Tyre                                                                                                                          | 235/55 R18                                                                                   | MICHELIN        | 6 mm                                                         |  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                              |                 |                                                              |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.<br><br>DAMAGES SEE DETAILS.                                                    |                                                                                              |                 |                                                              |  |
| <b>5. General Information</b>                                                                                                          |                                                                                              |                 |                                                              |  |
| Accident Date                                                                                                                          | 15/12/2021                                                                                   | Inspection Date | 15/12/2021                                                   |  |
| Survey held at                                                                                                                         | RYDER AUTO PTE LTD<br>2 KAKI BUKIT AVE 2<br>#02-19/22 KAKI BUKIT AUTOHUB<br>SINGAPORE 417921 |                 |                                                              |  |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                              |                 |                                                              |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                              |                 |                                                              |  |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                                              |                 |                                                              |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                                              |                 | 4 Working Days                                               |  |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJM 301U

| Qty | Description of Parts                              | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---------------------------------------------------|-----------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b>                |           |                           |                   |
| 1   | FRONT BUMPER                                      | DEFORMED  | 1,186.00                  | 811.20            |
| 1   | FRONT BUMPER N/S SPONGE                           | CRACKED   | 40.30                     | 40.30             |
| 1   | FRONT BUMPER N/S RETAINER                         | DEFORMED  | 109.00                    | 109.00            |
| 1   | FRONT N/S FENDER                                  | BENT      | 1,446.30                  | 1,446.30          |
| 1   | FRONT N/S DAY TIME RUNNING LIGHT                  | CRACKED   | 922.30                    | 907.60            |
| 1   | FRONT N/S FENDER WHEEL GUARD                      | TORN      | 523.40                    | 523.40            |
| 1   | FRONT N/S HEAD LAMP                               | CUT       | 6,714.50                  | 6,714.50          |
| 1   | FRONT N/S AIR DUCT (ADDITIONAL)                   | DEFORMED  | 451.20                    | 251.00            |
| 1   | FRONT N/S AIR DUCT RETAINER (ADDITIONAL)          | BENT      | 92.50                     | 92.50             |
| 1   | FRONT N/S HEAD LAMP BRACKET (ADDITIONAL)          | BENT      | 131.20                    | 131.20            |
| 1   | FRONT BONNET CHROME (ADDITIONAL)                  | CRACKED   | 667.50                    | 567.50            |
|     | LESS 25% DISCOUNT                                 |           | -3,071.05                 | -2,898.63         |
|     |                                                   |           | 9,213.15                  | 8,695.87          |
|     | <b><u>SPECIAL NETT ITEMS</u></b>                  |           |                           |                   |
| 10  | FRONT BUMPER CLIPS (SN)                           | NECESSARY | 50.00                     | 30.00             |
| 6   | FRONT N/S FENDER WHEEL GUARD CLIPS (SN)           | NECESSARY | 30.00                     | 20.00             |
|     |                                                   |           | 80.00                     | 50.00             |
|     | <b><u>LABOUR</u></b>                              |           |                           |                   |
|     | TO DISMANTLE DAMAGED PARTS ,STRAIGHTEN & WELDING. |           | 800.00                    | 450.00            |
|     | TO SPRAY PAINTING.                                |           | 700.00                    | 600.00            |
|     | TO CHECK FOR FAULT CODE AND RESETTING.            |           | 280.00                    | 180.00            |
|     | TO CHECK WIRING .                                 |           | 80.00                     | 30.00             |
|     | TO RESEAL ANTI RUST .                             |           | 100.00                    | 30.00             |
|     |                                                   |           | 1,960.00                  | 1,290.00          |
|     | <b>GRAND TOTAL</b>                                |           | <b>11,253.15</b>          | <b>10,035.87</b>  |

Report Ref No. CC6/CTI21012757/Tpa3q2



|                             |  |  |           |
|-----------------------------|--|--|-----------|
| RECOMMENDED COST OF REPAIRS |  |  | 10,035.87 |
|-----------------------------|--|--|-----------|

Report Ref No. CC6/CTI21012757/Tpa3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJM 301U

INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJM 301U

RE-INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SJM 301U

### RE-INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

