


CS/CTI21012758/Uty3

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SLX 494P
 at Workshop m/s: Tardur
 of _____
 Insured: XE 5750J
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: \$70k.
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 14 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No 0.50
 CA / REV / REP. / 24 HRS

Vehicle: IN / OUT
 Date: _____ Person Contacted: LTA B4115

Date / Time Action / Instruction 207 10/11
N0445 2885

Veh No: SLX 494P Yr Regn: 29/3/18
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA /
 Make: KIA Carens c.c. 1681
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 3/2077 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KNAMU815VJ7203631
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or 4 Wheel
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205/55R16
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Dunlop

Front 6 mm Rear 6 mm
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 13/12/21 D.O.I. 15/10/24
 Survey held at _____

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
0.5 Body & 1.5 Rear, 1.5 Body
 The U/C / Chassis frame / Body Structure affected due to collision.

3/1/22 2/5 \$15,000 in form n2 tar.
 red: 12854.50;46%

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 14

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____) S + RS _____ SI☐ : Interview (\$ _____) Photos☐ : Tech. Invs (\$ _____) Others☐ : Weekend (\$ _____)

Report Format :

Lump Sum / I.B.I.: (\$ _____)

TOTAL

not Authorised
Mk



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

CTP Insured's Veh No : XE5790J

Date of Accident : 13 December 2021

4/5 \$15,000
14 days

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Take up the other repair
15/12/21

Messrs BIS Motoring Pte Ltd

Date : 15 December 2021

Estimate To Repair SLX4941P - KIA CARENS 1.7 DCT DIESEL 5DR FWD

Chassis No : D4FDJH550864

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	rear bumper	\$ 452.00
02	8 ps	rear bumper clip @ \$5.00	\$ 40.00
03	1 pc	rear bumper lower	\$ 190.00
04	1 pc	n/s rear bumper reflector	\$ 104.00
05	1 pc	n/s rear bumper side retainer	\$ 23.00
06	1 pc	rear bumper parking sensor	\$ 147.00
07	1 pc	rear bumper diffuser	\$ 162.00
08	1 pc	rear bumper beam	\$ 331.00
09	3 ps	rear bumper bracket - lower @ \$10.00	\$ 30.00
10	1 pc	n/s taillamp	\$ 321.00
11	1 pc	tailgate lid	\$ 1,219.00
12	1 pc	n/s tailgate reflector	\$ 193.00
13	1 pc	tailgate carens lettering	\$ 32.00
14	1 pc	tailgate CRDI lettering	\$ 26.00
15	1 pc	n/s rear fender	\$ 1,349.00
16	1 pc	n/s rear fender sticker	\$ 12.00
17	1 pc	rear axle	\$ 1,161.00
18	1 pc	n/s rear rim	\$ 546.00
19	1 pc	n/s rear door	\$ 978.00
20	1 pc	n/s front door	\$ 1,098.00
21	1 pc	n/s front fender inner cowl	\$ 68.00
22	1 pc	n/s front knuckle arm	\$ 311.00
23	1 pc	n/s front lower arm	\$ 387.00
24	1 pc	n/s front wheel bearing	\$ 214.00
25	1 pc	n/s front lower arm ball joint	\$ 85.00
26	1 pc	n/s front absorber	\$ 302.00
27	1 pc	n/s front drive shaft	\$ 838.00
28	1 pc	n/s front anti roll bar linkage	\$ 85.00
29	1 pc	n/s front rim	\$ 546.00
30	1 pc	o/s side mirror	\$ 589.00
31	1 pc	o/s front door	\$ 1,098.00
32	1 pc	o/s front door outer handle	\$ 176.00
33	1 pc	o/s front door outer handle extension	\$ 24.00
34	1 pc	o/s front door key lock	\$ 85.00
35	1 pc	o/s front door outer chrome moulding	\$ 43.00

1218

1160

1020



陳林摩呀私人有限公司
TAN LIM MOTOR PTE LTD

CTP Insured's Veh No : XE5790J

Date of Accident : 13 December 2021

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Messrs BIS Motoring Pte Ltd

Date : 15 December 2021

Estimate To Repair SLX4941P - KIA CARENS 1.7 DCT DIESEL 5DR FWD

Chassis No : D4FDJH550864

S/No	Quantity	Description	Amount	
<u>LIST ITEMS</u>				
36	1 pc	o/s front door lock JM	\$ 239.00	✓
37	1 pc	o/s front door hinge - top SUC	\$ 30.00	X
38	1 pc	o/s front door hinge - bottom SUC	\$ 30.00	X
39	1 pc	o/s front door checker SUC	\$ 45.00	X
40	1 pc	o/s front door weatherstrip neu	\$ 95.00	✓
41	1 pc	o/s front door inner trim board 24/30mm	\$ 873.00	✓
42	1 pc	o/s front door glass 320	\$ 174.00	✓
43	1 pc	o/s front door glass weatherstrip Bntf	\$ 106.00	✓
44	1 pc	o/s front door glass power window motor Bntf	\$ 280.00	✓
45	1 pc	o/s front door glass power window regulator JM	\$ 207.00	✓
46	1 pc	o/s front door frame sticker - front neu	\$ 15.00	✓
47	1 pc	o/s front door frame sticker - top neu	\$ 15.00	✓
48	1 pc	o/s front door frame sticker - rear neu	\$ 15.00	✓
49	1 pc	o/s front door frame weatherstrip 11	\$ 126.00	X
50	1 pc	o/s front door key plate 11	\$ 24.00	X
51	1 pc	o/s rear door 115 975	\$ 978.00	✓
52	1 pc	o/s rear door outer handle C17	\$ 48.00	✓
53	1 pc	o/s rear door outer chrome moulding Bntf	\$ 53.00	✓
54	1 pc	o/s rear door lock JM	\$ 207.00	✓
55	1 pc	o/s rear door weatherstrip neu	\$ 104.00	✓
56	1 pc	o/s rear door inner trim board 24/30mm	\$ 697.00	✓
57	1 pc	o/s rear door glass power window motor JM	\$ 161.00	✓
58	1 pc	o/s rear door glass power window regulator Bntf	\$ 180.00	✓
59	1 pc	o/s rear door glass 320	\$ 217.00	✓
60	1 pc	o/s rear door glass weatherstrip 11	\$ 107.00	X
61	1 pc	o/s rear door frame sticker - front neu	\$ 15.00	✓
62	1 pc	o/s rear door frame sticker - top neu	\$ 15.00	✓
63	1 pc	o/s rear door frame sticker - rear neu	\$ 15.00	✓
64	1 pc	o/s rear door hinge - top Bntf	\$ 25.00	✓
65	1 pc	o/s rear door hinge - bottom Bntf	\$ 25.00	✓
66	1 pc	o/s rear door checker Bntf	\$ 31.00	✓
67	1 pc	o/s rear door frame weatherstrip 11	\$ 124.00	X
68	1 pc	o/s rear door key plate 11	\$ 29.00	X
69	1 pc	o/s rear rim C17	\$ 546.00	✓
70	1 pc	o/s rear absorber Bntf	\$ 200.00	✓

12583



陳林摩打有限公司
TAN LIM MOTOR PTE LTD

CTP Insured's Veh No : XE5790J

Date of Accident : 13 December 2021

1 Defu Lane 6 Singapore 539365

Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Messrs BIS Motoring Pte Ltd

Date : 15 December 2021

Estimate To Repair SLX4941P - KIA CARENS 1.7 DCT DIESEL 5DR FWD

Chassis No : D4FDJH550864

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
71	1 pc	o/s rear wheel bearing with hub <i>Damaged</i>	\$ 325.00 ✓
72	1 pc	o/s rear fender <i>Body</i>	\$ 1,349.00 ✓
73	1 pc	o/s rear fender inner cowling <i>11</i>	\$ 202.00 ✓
74	8 ps	o/s rear fender inner cowling clip @ \$5.00 <i>rec</i>	\$ 40.00 ✓
75	1 pc	o/s rear fender mudflap - front <i>re</i>	\$ 15.00 ✓
76	1 pc	o/s rear fender sticker <i>rec</i>	\$ 15.00 ✓
77	1 pc	o/s B pillar <i>Body</i>	\$ 1,864.00 ✓
78	1 pc	o/s rocket panel <i>Body 1600</i>	\$ 1,729.00 X
			\$ 24,855.00
Less 10 %			\$ 2,485.50
			\$ 22,369.50
<u>SPECIAL NETT ITEMS</u>			
79	1 pc	tailgate C&C emblem <i>rec</i>	\$ 55.00 40
80	1 pc	n/s rear tyre <i>sun</i>	\$ 250.00 X
81	1 pc	n/s front tyre <i>11</i>	\$ 250.00 X
82	1 pc	o/s rear tyre <i>11</i>	\$ 250.00 X
83	1 pc	o/s rear 1/4 glass primer <i>rec</i>	\$ 80.00 40
84	1 pc	o/s rear 1/4 glass sealant <i>rec</i>	\$ 80.00 40
			\$ 965.00
<u>LABOUR & MISC. CHARGES</u>			
01		To reinstall of rear bumper parking sensor.	\$ 80.00 50
02		To remove upholstery	\$ 150.00 80
03		To remove and refit n/s 1/4 glass	\$ 100.00 80
04		To transfer of door fittings and perform water seepage test.	\$ 160.00 120
05		To rust-proofing of the affected areas.	\$ 300.00 120
06		To check electrical lighting concerned.	\$ 100.00 30
07		To transfer of tyre, rim and on wheel balancing.	\$ 150.00 X
08		To check steering geometry and computer wheel alignment.	\$ 80.00 ✓
09		To drop rear axle and suspension assy, remove and renewal of necessary parts, to conduct final checking and testing.	\$ 200.00 ✓
10		To drop front suspension undercarriage parts, remove and renewal of the necessary parts, to perform final checking and testing.	\$ 200.00 120
11		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,600.00 1400



陳林摩嘜私人有限公司
TAN LIM MOTOR PTE LTD

CTP Insured's Veh No : XE5790J

Date of Accident : 13 December 2021

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Messrs BIS Motoring Pte Ltd

Date : 15 December 2021

Estimate To Repair SLX4941P - KIA CARENS 1.7 DCT DIESEL 5DR FWD

Chassis No : D4FDJH550864

S/No	Quantity	Description	Amount
12		LABOUR & MISC. CHARGES	
		Putty and spray painting of the affected portion.	\$ 1,400.00
			\$ 4,520.00
		Total	\$ 27,854.50

1380

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2- 16897
10%
P. 15207.3
S. N-120
L-3660
16897.3
4789