

ASSIGNMENT

Veh No:

SLP 4048K

Yr Regn:

06, 17

Bus / Van / Lorry / Taxi / Prime Mover /

A314-32-C6Z5



Lian Her Motors

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
Tel : 64817221

Fax : 64816131

L H Car Rental Pte Ltd
Blk 5038 #01-405
Ang Mo Kio Industrial Pk 2
Singapore 569541

Vehicle No : SLP 4048 K
Make : Toyota Wish
Year : 2017

NOT Authorized
11 Day @ 3250/h
Delivery After Repair
5 days

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Front o/s fender		
1 pc	Front o/s fender innershield		
1 pc	Front o/s door assy		
1 pc	Front o/s door weatherstrip		
1 pc	Front o/s door frame black sticker		
1 pc	Rear o/s door assy		
1 pc	Rear o/s door weatherstrip		
1 pc	Rear o/s door frame black sticker		
1 pc	O/S rocker panel garnish		
1 pc	Front o/s shock absorber		
1 pc	Front o/s lower arm		
1 pc	Front o/s knuckle arm		
1 pc	Front o/s knuckle arm bearing		
1 pc	Front o/s hub		

Ry	\$455.10	✓
Sn	\$186.10	X
rd/way	\$1,287.50	✓
Sn	\$255.10	X
nn	\$85.20	✓
R	\$1,250.60	X
Sn	\$255.10	X
nn	\$85.20	X
Sn	\$550.70	X
Sn	\$387.10	X
Sn	\$405.10	X
Ry	\$425.20	2
nn	\$175.10	2
Ry	\$417.60	2
	\$6,220.70	
Less 25 %	\$1,555.18	
	\$4,665.52	

S Nett

1 pc	Front o/s tyre rim		
20 pcs	Clip		

nd	\$450.00	2800
nn	\$40.00	X
	\$745.00	

Labour Charges

Remove/renew the above parts. Knock out & straighten n/s door centre pillar etc

\$1,000.00 500

To putty & spray paint on accident affected portion.

\$1,200.00 900

Check/reconnect wiring.

\$55.00 20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

balance c/f \$7,665.52

Acknowledged by Repairer

Signature:

Date:

Aspire 3

DDR4

600 11ac

A314-32-C6Z5

1000Mbps

Gigabit Ethernet

Alibi 210127811K.

048 K

balance b/f \$7,665.52

Labour Charges

To spray anti rust on accident affected portion.	\$180.00	601
Remove/refit front & rear o/s door glass, mechanism, inner lock, trim board to new door.	\$240.00	601
Remove/renew front o/s undercarriages.	\$350.00	901
Check and relign wheel alignment.	\$60.00	✓
Total	<u>\$8,495.52</u>	