


## LETTER OF AUTHORITY



ACCIDENT ON 15/11/2021 AT 08:35 HRS INVOLVING  
VEHICLES NOS. SKH 5535 T and SLQ 2153 Y  
AT/ALONG South Bridge Rd

I, Koh Boon Hock LLP of NRIC No. TXXXXX145L, owner of vehicle  
Reg.No SKH 5535 T insured by NTUC under policy  
no. 5099750898-03 do hereby authorize M/S Freesion Autodrive as my  
representative to claim, write, negotiate, act & settle for me to claim for damages, loss of  
use and medical fees (if applicable) from the owner/driver or the insurer of vehicle no.  
SLQ 2153 Y arising from the above mentioned accident.

I also authorize that the agreed settlement sum be made in favour of my representative  
M/S Freesion Autodrive

and the said payment be forwarded to them as full and final discharge of my claim.

Dated this  day of

Signature :  

Name : Koh Boon Hock LLP

Address : 119 A RIVERSIDE DR  
: #10-304  
: 541119

NRIC No. : T16LL1145L

Contact No. : 91162968

# LS CAR RENTAL

25 Kaki Bukit Road 4 #03-33 Synergy@KB Singapore 417800  
Tel: 9637 3533 Email: lscar.rental@gmail.com

RENTAL AGREEMENT NO.: 9075

TO BE PAID BY HIRER				DATE & TIME IN 22.11.2021 3.21pm				TOTAL DAYS 5	
Alson Lim Chun Wei				DATE & TIME OUT 17.11.2021 5.50pm.				5	
				VEHICLE MAKE & MODEL Honda Vezel					
				CLASS					
				VEHICLE UNIT NO.					
HIRER				VEHICLE REGISTRATION NO SLH 711919E					
METHOD OF PAYMENT		CREDIT APPROVAL / DATE / AMOUNT		KM IN 1 4 6 5 8 5		MINIMUM @			
				KM OUT 1 4 6 0 1 5		DAYS @		5 x \$160	
AUTHORISED OPERATOR				KM DRIVEN		EXTRA HRS @			
HOME ADDRESS Blk 19A Riverak Drive #10-304				KM ALLOWED		WEEKS @			
Singapore 54119				KM CHARGED		KM @			
COMPANY									
COMPANY ADDRESS				MINIMUM RENTAL PERIOD		SUB TOTAL			
LOCAL CONTACT 91162968				RATES DO NOT INCLUDE PETROL BY TANK <input type="checkbox"/> BY KILOMETRES <input type="checkbox"/>		SUB TOTAL			
NRIC / PASSPORT NO S9470083C		COUNTRY OF ISSUE		DATE OF ISSUE 23 Jan 2014		IN E 1/8 1/4 3/8 1/2 5/8 3/4 7/8 F		REFUELLING CHARGE	
DRIVING LICENCE NO S9470083C		ISSUED BY		EXPIRY DATE		OUT E 1/8 1/4 3/8 1/2 5/8 3/4 7/8 F		SERVICE CHARGE	
PLACE OF BIRTH Malaysia		DATE OF BIRTH 26 Apr 1994		DELIVERY		COLLECTION		LDW (PER DAY)	
DUE DATE				DECLINES LDW				ACCEPTS LDW	
				LOSS DAMAGE WAIVER (LDW) Hirer is responsible for the first \$250.00 excess for the collision to first party (i.e. LS Car) vehicle (including windscreen). And also first \$250.00 excess for collision / damage to third party's vehicle for each and every accident / damage.				\$	
INDICATE : D - DENTS S - SCRATCHES A - ACCIDENT FRONT LEFT TOP REAR RIGHT				DECLINES PAI		ACCEPTS PAI		PAI (PER DAY)	
				PERSONAL ACCIDENT INSURANCE (PAI) By INITIALS, Hirer declines or accepts PAI. If "Accepts" Hirer accepts coverage at rate shown and acknowledges to have read the SYNOPSIS of coverage limits furnished by owner at rental.				MISCELLANEOUS	
								SUNDRIES	
								OIL REPAIRS	
The vehicle is rented subject to all the terms and conditions on this page and on the reverse whether printed or handwritten. Note that the Vehicle is for use in Singapore only, unless otherwise authorised by the Owner in writing and unless a valid permit is obtained.				SUB TOTAL		\$ 800			
				PREPARED BY					
				DEPOSIT COLLECTED BY		AMOUNT DUE			
				DEPOSIT		LESS DEPOSIT (IF ANY)			
REMARKS				COMPUTED BY		NET DUE			
				REFUND COLLECTED BY		AMOUNT REFUND			

SKH5535T.

# L S CAR RENTAL

Block 67 Sin Ming Road #01-59 Sector A Singapore 575675  
Tel: 64531967, 64525043 Fax: 64573091

No. 1949

## OFFICAL RECEIPT

Date: 22-11-2021

Received from Alson Lim Chun Wei

the sum of Dollars Eight Hundred Only —

being payment for RA: 9075. SLH7199E - Honda Vezel. Rental from

17/11/2021 - 22/11/2021 \$160 x 5 = \$800/-

\$ 800 / ~~xx~~  
Cash/Cheque No.



Authorised Signature





Land Transport Authority  
10 Sin Ming Drive  
Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 16 Nov 2021 / 09:41:56

Receipt Date/Time : 16 Nov 2021 / 09:41:40

**Tax Invoice/Receipt**

Receipt No. : ITNET-00000-211116-000680

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SLQ2153Y As at 15 Nov 2021/08:35:00 Insurance Co: INDIA INT'L INS PTE LTD Insurance Co: MSIG INSURANCE (SINGAPORE) PTE LTD				
1	Insurance Enquiry - SLQ2153Y Enquiry Fee 20211116094030190157	7.00	0.49	7.49
<b>Sub-Total</b>		7.00	0.49	7.49
<b>Total Before Rounding</b>		7.00	0.49	7.49
<b>Rounding Difference</b>				0.04
<b>Total Amount Payable</b>				7.45
Paid By				
	421808XXXXXX8547	eNETS Credit Card		7.45
<b>Total</b>				7.45
<b>Cash Change</b>				0.00
<b>Tendered Amount</b>				7.45
<b>Excess Refundable Amount</b>				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

# FREESION AUTODRIVE

25 KAKI BUKIT ROAD 4 SYNERGY @KB #03-33 SINGAPORE 417800

TEL: 6702 3533 FAX: 6702 3577

BUS. REGN. NO. 53260330C

## INVOICE

To: Koh Boon Hock LLP

Invoice No. : FA17526  
Date : 06.12.2021  
Vehicle No. : SKH5535T

No.	Description	Qty	Unit Price	Amount
1	Repair Cost		\$ 6,000.00	\$ 6,000.00
Total:				\$ 6,000.00

Payment by cheque should be crossed and made payable to 'Freesion Autodrive'

Issued By:



.....  
Authorised Signature

Our reference: 21-8316  
Date: 28/11/2021

**INVOICE NO. 8316**

**Koh Boon Hock LLP**  
c/o Freesion Autodrive  
25 Kaki Bukit Road 4  
Synergy @ KB #03-33  
Singapore 417800

Registration No. **SKH5535T**

We enclose our fee note for your kind attention, which remains payable irrespective of the outcome of this case.

S/No.	Description of Services Provided	Qty	Amount
1	Being vehicle damage assessment report, inspection, photographs, transport and miscellaneous.	1	\$648.00
Total amount			<u><u>\$648.00</u></u>

Please kindly cross all cheques made payable to "Impact Analysis Consultant".

We thank you in anticipation for your prompt payment.



**L. L. Tan (Ms)**  
Principal Consultant

*Subsidiaries of Impact Analysis Consultant:*

• Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd  
• IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd  
[www.iaconsultingsg.com](http://www.iaconsultingsg.com)

Our reference: 21-8316

Date: 28/11/2021

c/o Freesion Autodrive  
25 Kaki Bukit Road 4  
Synergy @ KB #03-33  
Singapore 417800

Dear Sirs

**RE: Road Traffic Accident on 15/11/2021  
Koh Boon Hock LLP**

In accordance with your instructions received in this office on **15/11/2021**, we made arrangements to examine the vehicle on **15/11/2021** at above-mentioned address. The following data was recorded:


#### Vehicle details

Make	Honda	Registration	SKH5535T
Model	Civic	Chassis	JHMFD26408S201378
Colour	Gold	Gearbox	Auto
Odometer	341437km	Paintwork	Good
Steering	In order	Brakes	In order
Condition	Good		

#### Tyre Depths

Front left	225/45R17	85% Toyo
Front right	225/45R17	85% Toyo
Rear left	225/45R17	85% Toyo
Rear right	225/45R17	85% Toyo

#### Impact Direction & Area of Damage:



Status	REPAIRABLE
Magnitude	Medium
Legal status	Unroadworthy

Following our examination of the accident damage, we have calculated repair times and method, which are detailed on page 2 & 3. We would recommend a sum of **\$6,000.00** and **7** working days for repair, which is sufficiently lower than the pre accident value to render the vehicle an economically and physically reliable proposition.

#### Subsidiaries of Impact Analysis Consultant:

- Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd
  - IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd
- www.iaconsultingsg.com



Our reference 21-8316  
Date 28/11/2021  
Page 2

### Section A: Damaged Parts Assessment

Part's Description	Qty	Condition As inspected	Repairer's Estimate	Our Adjustment
<b>List Items:</b>				
Rear bumper	1	torn.deformed	645.50	645.50
Rear bumper side retainer lh	1	broken.nec	22.80	22.80
Rear fender lh	1	bent.deep-cut	895.40	895.40
Rear windscreen glass moulding	1	necessary	112.80	112.80
Rear door lh	1	bent.warped	865.40	865.40
Rear door inner lock lh	1	damaged	205.40	205.40
Rear door outer protector lh	1	damaged	124.80	124.80
Rear door outer handle cover lh	1	scratched	96.80	96.80
Rear door weatherstrip	1	ripped.nec	175.80	175.80
Rocker panel lh	1	repair.	552.00	0.00
Tail lamp lh	1	refix	225.90	0.00
Rear wheel bearing lh	1	necessary	166.00	166.00
Rear wheel bearing hub lh	1	necessary	198.70	198.70
Rear shock absorber lh	1	rebuilt	301.00	0.00
<b>Sub- Total costs</b>			<b>4588.30</b>	<b>3509.40</b>
Percentage discount : 20%			917.66	701.88
<b>Sub-Total costs for parts</b>			<b>3670.64</b>	<b>2807.52</b>

#### Special Nett Items:

Rocker panel side skirt lh	1	bent.deep-cut	628.80	628.80
Rear tyre rim lh	1	cut	559.80	559.80
Rear windscreen sealant	1	necessary	50.00	50.00
Rear bumper clips	set	necessary	45.00	20.00
Rear fender sealant	1	necessary	40.00	40.00
Reverse sensor	1	serviceable.refix	250.00	0.00
<b>Sub-Total costs for parts</b>			<b>1573.60</b>	<b>1298.60</b>

#### Parts Repair

*	*	*	0.00	0.00
<b>Sub- Total costs</b>			<b>0.00</b>	<b>0.00</b>
<b>Total costs for parts</b>			<b>5244.24</b>	<b>4106.12</b>

Subsidiaries of Impact Analysis Consultant:

• Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd  
• IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd  
www.iaconsulting.sg.com



Our reference 21-8316

Date 28/11/2021

Page 3

### Section B: Labour Cost Calculation

	Hourly rate	Manhr. Req.	Total
To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mentioned on the 'Parts Repair' column inclusive of replacement parts.	\$ 45.00	23	\$ 1,035.00
Putty & Spray painting to adjacent panels. Job allowance. Paint / material. ( 5 panels)	Sub-contract work.		\$ 1,100.00
Apply rust proofing on the adjacent panels.	Sub-contract work.		\$ 80.00
Wiring and bulb checking	\$ 45.00	0.8	\$ 36.00
Remove and refix rear windscreen glass. (2-man job)	\$ 45.00	3.5	\$ 157.50
Conduct water leak test for rear portion associated repair works	\$ 45.00	1	\$ 45.00
Remove and replace rear undercarriage work lh	\$ 45.00	4	\$ 180.00
Transfer of existing rear door mechanism to new door lh	\$ 45.00	2	\$ 90.00
Remove and refix rear bumper reverse sensor & conduct distance safety setting.	\$ 45.00	1.7	\$ 76.50
<b>Total labour cost</b>			<b>\$ 2,800.00</b>

Manhour rate and the number of manhours required for each repairing task are formulated based on 'individual workshop' operating cost and in-house@ IA Research Guidelines respectively.

Our reference 21-8316

Date 28/11/2021

### Section C: Summary Table of Total Repair Cost

Description		Cost	
<b>Damaged Parts Assessment (See section A)</b>		<b>\$4,106.12</b>	
Further discount	20%	\$821.22	
Recommended cost of parts replacement		<b>\$3,284.90</b>	(1)
<b>Labour Cost Calculation (See section B)</b>		<b>\$2,800.00</b>	(2)
<b>Total Repair Cost (Round off to hundred)</b>		<b>\$6,000.00</b>	(1) + (2)

We would recommend a sum of \$6,000.00 and 7 working days for repair.  
No further items will be approved without our expressed written agreement. Any significant additional items will be subject to a supplementary report.

*Mechanical Engineer, Accident Expert Witness, Licensed Appraiser (Automobile)*  
B.Eng. (Hons, NUS)  
Diploma. Mechanical Engineering  
NTC-2 Automovite Technology  
Sr.MIES, Institution of Engineers, Singapore (#20100091)  
MATAI, Maryland Association of Traffic Accident Investigators  
IAARS, International Association of Accident Reconstruction Specialists  
PMC of Singapore Business Advisors & Consultants Council  
ACTA certified Trainer, Singapore  
SPRING- Recognised Certification for Management Consultants

#### Subsidiaries of Impact Analysis Consultant:

• Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd  
• IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd  
www.iaconsultingsg.com



