

QUOTATION

Customer :

NO. : **39699**

- Rev. 1

AIG ASIA PACIFIC INSURANCE PTE LTD
 CHARTIS BUILDING
 78 SHENTON WAY
 #07-16
 SINGAPORE 079120
 ATTN: MOTOR CLAIMS DEPT

DATE : 11/12/2021
 CLAIM NO. : 11836
 POLICY NO. : MC/00833787

FROM : RAYMOND

VEHICLE NO. : FBN1159Y
 MAKE/MODEL : YAM / NMAX155 ABS

(Page 1 of 5)

S/N	Description	Action	Qty	Unit Price	Amount
1	AXLE FRONT WHEEL P/N: 59126 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$14.00 Disc %: 10.00	12.60
2	BEARING 6300 LLU (NTN) P/N: 72057 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$16.00 Disc %: 10.00	28.80
3	BELLY PAN P/N: 58094 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$35.00 Disc %: 10.00	31.50
4	BOARD FOOTREST LH P/N: 59588 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$55.00 Disc %: 10.00	49.50
5	BOARD FOOTREST RH P/N: 59589 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$55.00 Disc %: 10.00	49.50
6	BOLT MUDGUARD - (REPORTED BY MECHANIC)	REPLACE	4.00	\$11.50 Disc %: 10.00	41.40
7	BOX FILTER AIR OUTER FRONT P/N: 58164 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$10.50 Disc %: 10.00	9.45
8	BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT P/N: 27220 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$200.00 Disc %: 10.00	180.00
9	CAMERA (V_SYS) M6 (WIFI VERSION) P/N: 56377 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$362.00 Disc %: 10.00	325.80

*39699 *



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
10	CLIP NUT SPRING P/N: 59586 - (REPORTED BY MECHANIC)	REPLACE	10.00	\$1.50 Disc %: 10.00	13.50
11	COLLAR RIM FRONT P/N: 66705 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$20.00 Disc %: 10.00	18.00
12	COVER BAR HANDLE LOWER P/N: 64731 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$16.00 Disc %: 10.00	14.40
13	COVER FRONT UPPER (WHITE) P/N: 59585 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$38.00 Disc %: 10.00	34.20
14	COVER LEG SHIELD P/N: 60933 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$16.00 Disc %: 10.00	14.40
15	COVER SIDE LH (GREY) P/N: 60877 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$38.00 Disc %: 10.00	34.20
16	COVER SIDE LOWER LH (WHITE) P/N: 58097 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$22.00 Disc %: 10.00	19.80
17	COVER SIDE LOWER RH (WHITE) P/N: 58117 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$22.00 Disc %: 10.00	19.80
18	COWLING FRONT LH (WHITE) P/N: 58179 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$35.00 Disc %: 10.00	31.50
19	COWLING FRONT RH (WHITE) P/N: 59594 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$35.00 Disc %: 10.00	31.50
20	DAMPER PLATE P/N: 64847 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$3.00 Disc %: 10.00	2.70
21	EMBLEM P/N: 56570 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$9.00 Disc %: 10.00	8.10
22	EMBLEM (YAMAHA) LOGO P/N: 57069 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$15.00 Disc %: 10.00	27.00
23	FENDER INNER P/N: 59583 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$30.00 Disc %: 10.00	27.00
24	FORK FRONT ASSY P/N: 59590 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$763.00 Disc %: 10.00	686.70
25	GROMMET P/N: 59593 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$6.00 Disc %: 10.00	5.40

*39699 *

bizSAFE₃

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
26	HEADLAMP ASSY P/N: 58174 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$308.00 Disc %: 10.00	277.20
27	HORN P/N: 58186 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$30.00 Disc %: 10.00	27.00
28	LAMP SIGNAL FRONT LH P/N: 59587 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$35.00 Disc %: 10.00	31.50
29	LAMP SIGNAL FRONT RH P/N: 59592 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$35.00 Disc %: 10.00	31.50
30	LEG SHIELD ASSY P/N: 60917 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$34.00 Disc %: 10.00	30.60
31	LEVER BRAKE LH P/N: 58145 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$18.00 Disc %: 10.00	16.20
32	MIRROR LH P/N: 58099 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$37.00 Disc %: 10.00	33.30
33	MUDGUARD FRONT (WHITE) P/N: 58087 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$48.00 Disc %: 10.00	43.20
34	NUT (WINDSCREEN) P/N: 46834 - (REPORTED BY MECHANIC)	REPLACE	4.00	\$2.50 Disc %: 10.00	9.00
35	NUT SPRING P/N: 53709 - (REPORTED BY MECHANIC)	REPLACE	10.00	\$3.50 Disc %: 10.00	31.50
36	PANEL 1 (GREY) LH P/N: 59584 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$22.00 Disc %: 10.00	19.80
37	PANEL 2 (GREY) RH P/N: 58081 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$22.00 Disc %: 10.00	19.80
38	PANEL CONSOLE 1 P/N: 65284 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$37.00 Disc %: 10.00	33.30
39	PANEL METER P/N: 60927 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$16.00 Disc %: 10.00	14.40
40	PLATE DISC BRAKE FRONT P/N: 58182 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$80.00 Disc %: 10.00	72.00
41	REPAIR ON BODY ALIGNMENT FRONT - (REPORTED BY MECHANIC)	Repair	1.00	\$350.00	350.00

*39699 *

bizSAFE₃

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
42	RIM SPORT FRONT(SILVER) P/N: 58148 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$250.00 Disc %: 10.00	225.00
43	RIVET P/N: 56583 - (REPORTED BY MECHANIC)	REPLACE	17.00	\$3.00 Disc %: 10.00	45.90
44	SEAL OIL FRONT RIM 20X35X7 P/N: 61482 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$4.50 Disc %: 10.00	8.10
45	SPRAY LACQUER ON COVER CENTRE LH - ON COVER CENTRE LH, COWLING FRONT LH, COWLING FRONT RH AND MUDGUARD FRONT	Spray	1.00	\$250.00	250.00
46	STAY FRONT HEADLAMP P/N: 60938 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$93.00 Disc %: 10.00	83.70
47	STICKER (CERTIS CISCO) WINDSHIELD NEW MODEL P/N: 61182 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$58.00	58.00
48	STICKER (CISCO) COVER CENTRE LH P/N: 58614 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$40.00	40.00
49	STICKER (CISCO) COWLING FRONT LH P/N: 58616 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$40.00	40.00
50	STICKER (CISCO) COWLING FRONT RH P/N: 58617 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$40.00	40.00
51	STICKER (CISCO) MUDGUARD FRONT P/N: 58618 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$40.00	40.00
52	STICKER LABEL WARNING P/N: 54157 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$10.00	10.00
53	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$10.00	10.00
54	TRANSPORT CHARGES P/N: 07169	Supply/Install	1.00	\$35.00	35.00
55	WINDSHIELD P/N: 58073 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$58.00 Disc %: 10.00	52.20
56	COVER FRONT LOWER (WHITE) P/N: 58106	Replace	1.00	\$22.00 Disc %: 10.00	19.80
57	Labour P/N: 06766	Supply/Install	8.00	\$45.00	360.00

*39699 *

bizSAFE₃

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
		SUB TOTAL			\$4,074.75
		GST @ 7 %			\$285.23
		GRAND TOTAL (SGD)			\$4,359.98

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*39699 *

bizSAFE₃

