	Ref No :	7 3	05497835	ENGINEERING ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969			
Date	:		18/12/21				
FINALIZATION FORM				59 Loyang Drive Singapore 559 Fax: 8548 8158			
To :			LKK	Fax:			
Attn : THEVAN				_	Tun.		
Vehicle Reg No. : SH946:			3X			13/12/2021	
The surv	ey and es	timates of th	ne repairs of the above-ment	oned vehicle are	e as follows:-		
Z Th	ie repair jo	ob shall bill	to:	NTUC		SLQ3520P	
2. Th	The finalized amount shall be:						
(a)) Spare	Parts afte	List discount				
(b)) Labo	ur Charges					
			y-Part Repair Cost				
(c.) Lump Total	sum Repai for Lumpsu	r (if applicable) um repair cost after Less: Repair cost	A second		\$4,250.00	
4. We	e shall tre orking da	at the abo	d for repairs: ve amount as Correct and istance.	Confirmed if the	confirm the es		
Signature : CHIANG Tel : 62148314			Signature: Name: Theyan Date: 20 2 2				
		65468150		_			
Or Unic	ial Use O	inly					
	Item		Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks	
1. Renta	l Rate P/[Day		YES			
2. Loss of Income Paid			-	N			
3. Survey Fees			•				
LTA Search Fee Medical Fees (on behalf of driver, if applicable)			\$7.49/\$2.00				
6 Overru	ın						
Remarks:							

,

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO

13.12.2021

SH 9463X REG. 22.10.2019

MAKE	MEG. EZ.ZO.Z.			
MODEL	IONIO G3			

MAKE				CHIANG/NTUC			
MODEL	IONIQ G3		Туре	Unit Price	Amount		
Qty	Parts Description/ Lab	our	· ipc	D			
	1 REAR BUMPER	ING		l t		n/hT	
1	1 REAR BUMPER CENTRE MOULD				\$\$394.80	n'/pt	
	1 REAR BUMPER REINFORCEMENT			\$138.10		17 17 1	
	2 REAR BUMPER STAY LH /RH 1 REAR BUMPER LOWER CENTRE N	NOULDING			DT \$155.00	2/14t	
	1 REAR CENTRE UNDER COVER				\$225.00		
1	10 REAR BUMPER CLIPS			\$2.20		1 `	
	1 BOOTLID COVER				\$2,480.40,	1 ' '	
	1 BOOTLID LOCK UPPER				\$224.00		
	1BOOTLID H EMBLEM				\$38.00		
	1 BOOTLID EMBLEM IONID				\$31.80	1 -	
	1 BOOTLID EMBLEM HYBRID				\$24.30	14	
	1 REAR END PANEL				\$532.00	> XESSIV /	
	1 REAR PANEL GARNISH				\$346.80	1. 137	
	1 BUMPER FOG LAMP				\$201.00		
	1 BUMPER NUMBER LAMP LH/RH			\$85.30		5 XZUC	
	1 BUMPER HOOK COVER				\$94.60	1	
	1 REAR REFLECTOR LH /RH			\$41.45	\$82.90		
	1REAR ANTENNA – SMART KEY					J. 751C	
:	1 REAR ANTENNA - SWART RET				\$55.80	nec	
2	REAR BUMPER BRACKET LH /RH				\$6,306.35		
		20.00%			\$1,261.27		
	DISCOLL	NTED TOTAL			\$5,045.08	./	
	Discoo	MILDIOIAL				nec	
					\$50.00,		
1	REAR BUMPER MAT				\$40.00	nec	
1 1	BOOTLID COMFORT APP STICKER	TICKED		\$30.00	\$60.00	neo	
2 8	BOOTLID COMFORT /TEL NUMBER S	STICKER		40 0.00	\$55.00	CVa	
1 F	REAR NUMBER PALTE W/HOLDER	LKK Auto Co	oncultante t	ence notify	\$180.09	Pat 1	
1/R	EAR REVERSE SENSOR	the Repairer	r of the follo	wing:	\$351.50	1 ./	
7		 To resurvey be 	efore/after spr	ay painting	\$331.30	- T	
		To display dan					
	hour Charge	Parts prices at Third party sur		ithout Prejudice" basis		17	
	Labour Charge		ification(s) is	llowed	\$900.00	1	
	Panel Beating		y item(s) mus	be resurveyed <u>and</u> m Insurance Company	\$600.00		
Sp	Spray Painting Charge		1.0	in insurance company	\$180.00	120	
	Remove/Refix rear wscreen and lowe		y Repairer		\$60.00	70	
Ch	eck wiring and lighting	Signature:			\$60.00	20	
Tut	ff Kote	Date:			\$60.00		
Remove/Refix reverse sensor				}	\$1,860.00		
	To allal as a TOTA			\$1,000.00	1		
	MEVAN ELMAGIO. (or	+		ļ		4	
	4 82235769 ESTIMA			\$7,256.58	4		
	19/12/21 17/5						
1	Thevan elphatisticor 4. 82235769 ESTIMA 1. 12/21 17/5 1. 18 after repair plusto 3 clays mp						
	3 clays wp '						