



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2203735

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 16/06/2022
Reference CC6/CTI21012771/Apa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SMZ 5516E
Insured Veh. SMJ 2801K
Claim No. SNM21D207365C02
Policy No. DMPCSNW00079662102
Accident Date 16/12/2021
Inspection Date 17/12/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21012771/Apa3q2 Date: 16/06/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMJ 2801K	Veh. Inspected	SMZ 5516E	
Policy No.	DMPCSNW00079662102	Coverage (\$)	0.00	
Claim No.	SNM21D207365C02	Excess (\$)	0.00	
Assign From		Assign Date	17/12/2021	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ E250C	c.c	1796	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	WDD2120472A351716	Colour	BRONZE	
Odometer	133782 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/45 R17	GOODYEAR	6 mm	
L/H Front Tyre	245/45 R17	GOODYEAR	6 mm	
R/H Rear Tyre	245/45 R17	GOODYEAR	6 mm	
L/H Rear Tyre	245/45 R17	GOODYEAR	6 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	16/12/2021	Inspection Date	17/12/2021	
Survey held at	RYDER AUTO PTE LTD 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMZ 5516E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	2,445.20	1,462.00
1	REAR BUMPER TOP GARNISH CHROME	NECESSARY	235.60	235.60
2	REAR BUMPER O/S & N/S TOP GARNISH CHROME	NECESSARY	456.80	456.80
1	REAR BUMPER LOWER DIFFUSER	DEFORMED	650.50	480.00
1	REAR BUMPER ENFORCEMENT	DENTED	845.60	765.00
2	REAR BUMPER O/S & N/S RETAINER	NOT NECESSARY	386.60	-
1	REAR BUMPER CENTRE RETAINER	NOT NECESSARY	210.60	-
2	REAR BUMPER O/S & N/S CENTRE BUMPER BRACKET	N/S CRACKED	160.00	45.00
2	REAR EXHAUST MUFFLER MOUNTING	NOT NECESSARY	245.60	-
2	FRONT O/S & N/S HEAD REST	ACTIVATED	2,865.60	1,830.00
	LESS 10% DISCOUNT		-850.21	-527.44
			7,651.89	4,746.96
<u>SPECIAL NETT ITEMS</u>				
10	REAR BUMPER CLIPS (SN)	NECESSARY	100.00	30.00
2	REAR REVERSE SENSOR (SN)	DAMAGED (1 PCS ONLY)	845.20	250.00
1	REAR EXHAUST TIP CHROME (SN)	DENTED	500.00	280.00
			1,445.20	560.00
<u>LABOUR</u>				
	TO DISMANTLE DAMAGED PARTS ,STRAIGHTEN & WELDING.		500.00	250.00
	TO SPRAY PAINTING.		400.00	250.00
	TO POLISH REAR EXHAUST .	NOT NECESSARY	150.00	-
	TO RESET FRONT O/S & N/S HEADREST.	NOT NECESSARY	600.00	300.00
	TO REMOVE AND REPLACE REAR REVERSE SENSOR .		120.00	60.00
	TO CHECK FOR FAULT CODE AND RESETTING.	NOT NECESSARY	150.00	-
	TO CHECK WIRING.		60.00	30.00
	TO RE-SEAL ANTI-RUST.	NOT NECESSARY	50.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIT REAR EXHUAUST .	NOT NECESSARY	180.00	-
			2,210.00	890.00
GRAND TOTAL			11,307.09	6,196.96
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,900.00

Report Ref No. CC6/CTI21012771/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMZ 5516E

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMZ 5516E

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMZ 5516E

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMZ 5516E

RE-INSPECTION

