

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

WDD212047A35716

ESTIMATE OF REPAIR

Veh# SMZ5516E

TP Chim
Xiao Tony

Model:

MERC 250

ident Date 16/12/2021

(16/12/2010-30/4/2030)

ocation : PIE TUAS BEORE STEVEN ROAD EXIT

3P: SMJ2801K (CHINA TAIPIG)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1pc	Rear bumper <i>Deland</i>	2,445.20	1462	
2	10pcs	Rear bumper clips <i>new</i>		100.00	30
3	1pc	Rear bumper top garnish chrome <i>3444.42</i>	235.60		
4	2pcs	Rear bumper o/s & n/s top garnish chrome <i>3444.42</i>	456.80		
5	1pc	Rear bumper lower diffuser <i>Deland</i>	650.50	480	
6	2pcs	Rear reverse sensor <i>Deland 1 piece</i>		845.20	250
7	1pc	Rear bumper enforcement <i>Deland</i>	845.60	765	
8	2pcs	Rear bumper o/s & n/s retainer <i>new</i>	386.60	x	
9	1pc	Rear bumper centre retainer <i>new</i>	210.60	x	
10	2pcs	Rear bumper o/s & n/s centre bumper bracket <i>N/s only</i>	160.00	45	
		Sub-Total:	5390.90	945.20	0.00
			10%	0%	10%
		After Less %:	4851.81	945.20	0.00
		Labour			
1		To dismantle damaged parts, straighten & welding.		500.00	250
2		To spray painting.		400.00	250
3		To polish rear exhaust.		150.00	x
4		To reset front o/s & n/s headrest		600.00	300
5		To remove and replace rear reverse sensor		120.00	60
6		To check for fault code and resetting		150.00	x
7		To check wiring.		60.00	30
8		To re-seal anti-rust.		50.00	x
		Sub-Total:		2,030.00	
		Total:		7,827.01	
		After Less 20%:		6,261.61	

llan

Supplementary: 280
Supplementary: 1647
total: 6196.96
H/S: 4.9K.
Admin 850
H/S 17/12/21
04 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company


Acknowledged by Repairer

Signature:

Date:



8778 1999
24 hr accident call



2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

SUPPLEMENTARY ESTIMATE OF REPAIR

Veh# SMZ5516E Model: MERC 250
ident Date 16/12/2021 (16/12/2010-30/4/2030)
Location : PIE TUAS BEORE STEVEN ROAD EXIT 3P: SMJ2801K (CHINA TAIPING)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1pc	Rear exhaust tip chrome <i>perked</i>		500.00	280
2	2pcs	Rear exhaust muffler mounting <i>new</i>	245.60		
		Sub-Total:	245.60	500.00	0.00
			10%	0%	10%
		After Less %:	221.04	500.00	0.00
		Labour			
1		To remove and refit rear exhaust		180.00	+
		Sub-Total:		180.00	
		Total:		901.04	
		After Less 20%:		720.83	

Chan
Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)

Admin
20/12/21.



AL 8778 1999
24 hr accident call



Supplementary : \$280

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

SUPPLEMENTARY ESTIMATE OF REPAIR 2

Veh# SMZ5516E

Model:

MERC 250

ident Date 16/12/2021

(16/12/2010-30/4/2030)

ocation : PIE TUAS BEORE STEVEN ROAD EXIT

3P:

SMJ2801K (CHINA TAIPING)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	2pcs	Front o/s & n/s head rest <i>Activated</i>	2865.6	<i>1830</i> 0.00	0
		Sub-Total:	2865.60	0.00	0.00
			10%	0%	10%
		After Less %:	2579.04	0.00	0.00
		Total:		2,579.04	
		After Less 20%:		2,063.23	

Chan

Chan San Choon

Director

DipEng, AAL MIM,MSAE(Aust)



8778 1999
24 hr accident call



Supplementary 1: 1647.