

Our Job Ref No 305498012  
Date : 20/12/2021

## ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

### FINALIZATION FORM


To : LKK  
Attn : THEVAN  
: SHA 903U


Fax :

DOA 15/12/2021

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- SNA2678K
2. The finalized amount shall be:
  - (a) Spare Parts after List discount \$430.95
  - (b) Labour Charges \$620.00
  - Total for Part-By-Part Repair Cost** \$1,050.95
  - (c.) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: 20%  
**Final Lumpsum Repair cost** \_\_\_\_\_
3. Estimated normal period for repairs: 2 working days
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature :   
Name : JUMANI  
Tel : 6214 8315  
Fax : 65468156

Signature :   
Name : THEVAN  
Date : 20/12/21

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	7.49 / 2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE

NTUC-CPV)

Date: 15.12.2021

Time: 15:09:08

Page: 1

Jumar!

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010070  
 ADDRESS : CITYCAB PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65551188

JOB NO : 305498012  
 REGN NO : SHA 903U ✓  
 MILEAGE : 0000000000  
 MAKE : TOYOTA  
 MODEL : PRIUS HYBRID(G4A)  
 DATE OF REGN : 14.01.2020  
 DATE/TIME IN : 15.12.2021 15:03  
 ACCIDENT DATE : 15.12.2021

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

0001 04-01-0302-2282-G COVER REAR BUMPER%	1	459.40	25.00	344.55	XV
0002 04-01-0302-2287-G GUARD-REAR BUMPER CENTER	1	552.60	25.00	414.45	/Scr
0003 04-01-0302-2267-G BUMPER PIECE	10	22.00	25.00	16.50	/NEC
0004 04-01-0302-1150-A BUMPER PROTECTOR MAT	1 N	50.00	2.50-	50.00	XNN
0005 04-01-0302-2288-G REINFORCEMENT SUB-ASSY RE	1	318.80	25.00	239.10	1. XSC ✓

SUB-TOTAL : 1,064.60

## JOB NATURE

0000 PB	PANEL BEATING	400.00	350
0001 SP	SPRAYPAINT CHARGE	300.00	250
0002 L	REMOVE/REFIX REVERSE SENSOR	50.00	20 ✓

SUB-TOTAL : 750.00

1814.60

thuanol auto. lvm  
 82235769  
 18/12/21 1630  
 p/p bfr paint photo  
 2 days up ✓

LKK Auto Consultants hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: