



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921
Tel: +65 67412845 Fax No: +65 67412170
Email: zero_gravity@singnet.com.sg
Reg.No.: 52888887X

QUOTATION

No : QT-000269

SOMPO INSURANCE SINGAPORE PTE LTD

50 RAFFLES PLACE

#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623

Attn: Motor Claims Department

TEL : 64616555

FAX : 62213302

Your Ref. : SKG5932K
Vehicle No. : GZ5311A
Make & Model : TOYOTA HIACE
Chassis No. : JTFHT02P500247011
Engine No. : 1KD2835075
Accident Date : 16/12/2021
Policy No. : 2021-V0110874-VCV-R001
Date : 18/12/2021
Page : 1 of 3

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price S\$	Amount S\$
1	LAMP (L/H/R) <i>New</i>	1.0	PCS 328.90	X 328.90
2	LAMP (R/H/R) <i>Good</i>	1.0	PCS 328.90	✓ 328.90
3	CORNER PANEL (L/H/R) <i>Good</i>	1.0	PCS 134.20	✓ 134.20
4	CORNER PANEL (R/H/R) <i>Good</i>	1.0	PCS 134.20	✓ 134.20
5	REAR END PANEL (INNER) <i>Repair</i>	1.0	PCS 1,147.60	X 1,147.60
6	REAR END PANEL (OUTER) <i>Dented</i>	1.0	PCS 297.80	✓ 297.80
7	FLOOR PANEL (REAR) <i>New</i>	1.0	PCS 710.50	X 710.50
8	REAR FLOOR TRIM <i>Best</i>	1.0	PCS 110.30	✓ 110.30
9	BUMPER SIDE RETAINER (L/H/R) <i>Good</i>	1.0	PCS 24.50	✓ 24.50
10	BUMPER SIDE RETAINER (R/H/R) <i>Good</i>	1.0	PCS 24.50	✓ 24.50
11	FENDER SIDE RETAINER <i>New</i>	2.0	PCS 26.80	X 53.60
12	REAR BUMPER <i>Debond</i>	1.0	PCS 431.20	✓ 431.20
13	BUMPER CLIP <i>New</i>	6.0	PCS 11.90	30 71.40
14	BUMPER BRACKET <i>2 pieces Best</i>	4.0	PCS 42.50	36 170.00
15	REAR BOOT <i>Dented</i>	1.0	PCS 1,755.30	✓ 1,755.30
16	REAR BOOT GARNISH <i>New</i>	1.0	PCS 131.20	X 131.20
17	REAR BOOT OUTER HANDLE <i>New</i>	1.0	PCS 105.90	X 105.90
18	REAR BOOT INNER LOCK <i>Dented</i>	1.0	PCS 288.60	✓ 288.60
19	LOCK GARNISH <i>Not New</i>	1.0	PCS 64.70	X 64.70
20	REAR BOOT LOCK STRIKER <i>New</i>	1.0	PCS 102.30	X 102.30
21	CENTER LOCKING MOTOR (BOOT) <i>New</i>	1.0	PCS 408.10	X 408.10
22	REAR BOOT WEATHERSTRIP <i>lt</i>	1.0	PCS 426.30	✓ 426.30
23	REAR BOOT INNER TRIM BOARD <i>Good</i>	1.0	PCS 583.40	X 583.40
24	REAR BOOT INNER TRIM BOARD CLIPS <i>Good</i>	16.0	PCS 3.90	X 62.40
25	DOOR ANTI SPLASH PLASTIC SEAL (BOOT) <i>New</i>	1.0	PCS 56.10	X 56.10
26	LOGO <i>New</i>	1.0	PCS 78.80	✓ 78.80
27	STICKER "TOYOTA" <i>New</i>	1.0	PCS 34.30	✓ 34.30



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921
 Tel: +65 67412845 Fax No: +65 67412170
 Email: zero_gravity@singnet.com.sg
 Reg.No.: 52888887X

QUOTATION

No : QT-000269

SOMPO INSURANCE SINGAPORE PTE LTD

50 RAFFLES PLACE

#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623

Attn: Motor Claims Department

TEL : 64616555 FAX : 62213302

Your Ref. : SKG5932K
 Vehicle No. : GZ5311A
 Make & Model : TOYOTA HIACE
 Chasis No. : JTFHT02P500247011
 Engine No. : 1KD2835075
 Accident Date : 16/12/2021
 Policy No. : 2021-V0110874-VCV-R001
 Date : 18/12/2021
 Page : 2 of 3

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price S\$	Amount S\$
28	STICKER "HIACE" <i>Nec</i>	1.0	PCS 26.30	✓ 26.30
29	SPARE TYRE BRACKET <i>Best NN</i>	1.0	PCS 310.40	X 310.40
30	LOCK REGULATOR (SPARE TYRE) <i>Not Nec</i>	1.0	PCS 288.50	X 288.50
31	REAR BOOT CATCH <i>NE</i>	2.0	PCS 44.00	+ 88.00
32	REAR BOOT STOPPER BUSH (SIDE) <i>NE</i>	2.0	PCS 25.30	+ 50.60
33	Di count 25 %			-2,207.20
34	SubTotal (L)			6,621.60
35	REAR FLOOR BOARD <i>NE</i>	1.0	PCS 450.00	+ 450.00
36	STICKER "70 Km/h" <i>3</i>	1.0	PCS 10.00	✓ 10.00
37	STICKER "8 PAX" <i>3</i>	1.0	PCS 10.00	✓ 10.00
38	REVERSE SENSOR <i>and</i>	1.0	SET 280.00	200 280.00
39	REVERSE CAMERA <i>NE</i>	1.0	PCS 380.00	X 380.00
40	RIM <i>NE</i>	1.0	PCS 180.00	X 180.00
41	TYRE (SPARE) <i>Not</i>	1.0	PCS 220.00	+ 220.00
42	REAR END PANEL SEALANT <i>NE</i>	1.0	BTL 50.00	✓ 50.00
43	SEALANT (WINDSCREEN) <i>NE</i>	1.0	PCS 35.00	✓ 35.00
44	SubTotal (S)			1,615.00
45	PANEL BEAT & REPAIR REAR DAMAGE	1.0	X	800 1,200.00
46	TO PUTTY AND RE-SPRAY AFFECTED PORTION	1.0	X	800 900.00
47	TO PROVIDE UNDER TURFCODE	1.0	X	60 120.00
48	TO CHECK WIRING SYSTEM & ENSURE FUNCTION OF COMPONENT	1.0	X	30 80.00
49	TO CHECK WIRING SYSTEM, FOCUS LIGHTINGS	1.0	X	X 50.00
50	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	1.0	X	120 150.00
51	TO TRANSFER REAR BOOT FITTING	1.0	X	60 120.00
52	TO REMOVE REVERSE SENSOR/CAMERA	1.0	X	2030 100 150.00
53	TO REMOVE AND REFIT COMPONENTS / FACILITATE THE REPAIR	1.0	X	60 150.00
54	SubTotal (LABOUR)			2,920.00



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921
Tel: +65 67412845 Fax No: +65 67412170
Email: zero_gravity@singnet.com.sg
Reg.No.: 52888887X

QUOTATION

No : QT-000269

SOMPO INSURANCE SINGAPORE PTE LTD

50 RAFFLES PLACE

#05-01/06 SINGAPORE LAND TOWER

SINGAPORE 048623

Attn: Motor Claims Department

TEL : 64616555

FAX : 62213302

Your Ref. : SKG5932K
Vehicle No. : GZ5311A
Make & Model : TOYOTA HIACE
Chasis No. : JTFHT02P500247011
Engine No. : 1KD2835075
Accident Date : 16/12/2021
Policy No. : 2021-V0110874-VCV-R001
Date : 18/12/2021
Page : 3 of 3

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price S\$	Amount S\$
------	-------------	-----	-----------------	---------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: \$368.87

h/s: A.3K

05 days

A.3K

SINGAPORE DOLLAR ELEVEN THOUSAND ONE HUNDRED FIFTY SIX AND CENTS SIXTY ONLY

E. & O.E

Total	S\$	11,156.60
Discount	S\$	0.00
Net Total	S\$	11,156.60

Terms: C.O.D.

Customer's Signature/Co. Stamp

ZERO GRAVITY

Any claim for faulty workmanship is limited solely to the rectification free of cost of such work, no claim for loss consequential or otherwise being admissible. Any objections to the validity of these charges must be made seven (7) days from the date of this invoice otherwise it is assumed that this bill is accepted as correct.