

Our Job Ref No 305497830

Date : 16/12/2021

ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508989
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : THEVAN
: SHD4586J

Fax :
DOA 11/12/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- SMX7660T
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$378.60
 - (b) Labour Charges \$820.00
 - Total for Part-By-Part Repair Cost \$1,198.60**
 - (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost
3. Estimated normal period for repairs: 2 working days
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :
Name : JUMANI
Tel : 6214 8315
Fax : 65468156

Signature :
Name : THEVAN
Date : 17/12/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	7.49 / 2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305497830
 REGN NO : SHD4586J ✓
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 16.01.2020
 DATE/TIME IN : 12.12.2021 09:20
 ACCIDENT DATE : 11.12.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	npc
0002 04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52	Xr
0003 04-01-0104-2288-G	BEAM-RR BUMPER	1	394.80	20.00	315.84	XsVC
0004 04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00	/scr
0005 04-01-0104-1150-A	PROTECTOR MAT	1	50.00	2.00-	50.00	XsVC
0006 04-01-0104-2545-G	MOULDING-REAR BUMPER LWR	1	155.00	20.00	124.00	XsVC ✓
SUB-TOTAL :						1,235.96

JOB NATURE

0000 PB	PANEL BEATING	400.00	350
0001 SP	SPRAYPAINT CHARGE	300.00	200 250
0002 L	REMOVE/REFIX REVERSE SENSOR	50.00	20 ✓
0003 20-05	RENEW ADVERTISEMENT STICKER-FENDER	200.00	100
SUB-TOTAL :		950.00	

Thuvarela Auto. low
 82235769
 14/12/21 1630
 PIP ambu pain photo
 2 plays up ✓

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: