

JA AUTOCARE PTE LTD

Blk 24 Sin Ming Road

#03-35

Singapore 570024

Tel : 94513429

*Not Authorized
L1 Pay @
Perman After Pain
6days*

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120

ESTIMATE

Date: 15.12.2021
vehicle number: SLU 1680C
Model MIT LANCER
Chassis/Eng# :
Accident Date : 15.12,21

PARTS

- 01) Boot lid
- 02) Boot lid lock assy
- 03) Boot lid Rubber
- 04) Boot lid Inner Trim Board
- 05) boot lid spoiler *(Crown type)*
- 06) Boot lid centre garnish (Black)
- 07) MIT emblem
- 08) Boot Lid hinges @\$130.00 x2
- 09) Boot lid centre garnish
- 10) Rear Panel
- 11) Rear Bumper
- 12) Rear Bumper Reinforcement
- 13) Rear Bumper Bracket @\$90.00 X2
- 14) Rear Bumper Retainer @\$120.00 X 2
- 15) Rear Bumper Lower Reflector @\$90.00 X 2
- 16) rear bumper clips
- 17) Rear exhaust
- 18) Rear exhaust chrome pipe
- 19) Taillamp assy #650.00 x 2
- 20) Tail Lamp clips

<i>Rm</i>	\$	850.00	✓
	\$ R	450.00	X
<i>Red 101's</i>	\$	220.00	50km
<i>NSP</i>	\$	350.00	X
<i>Mc</i>	\$	280.00	✓
<i>Sm</i>	\$	150.00	X
<i>Am</i>	\$	75.00	✓
	\$ R	260.00	X
<i>Sm</i>	\$	180.00	X
<i>Rm</i>	\$	950.00	✓
<i>Rm</i>	\$	750.00	✓
<i>NSP</i>	\$	450.00	X
<i>ols Rm</i>	\$	180.00	LT
<i>ols CM</i>	\$	240.00	LT
<i>ols SCR</i>	\$	180.00	LT
<i>Mc</i>	\$	60.00	✓
	\$ R	850.00	X
	\$ Sm	250.00	X
<i>ols CM</i>	\$	1,300.00	LT
<i>Mc</i>	\$	60.00	30 ✓
		\$	8,085.00
		\$	(808.50)
		\$	7,276.50

LKK Auto Consultants hence notify Less 10%
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

JA AUTOCARE PTE LTD

Blk 24 Sin Ming Road

#03-35

Singapore 570024

Tel : 94513429

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

ESTIMATE

Date: 15.12.21

vehicle number: SLU 1680C

Model Mit Lancer

Chassis/Eng# :

Accident Date : 15.12.21

S/Nett

21) Reverse Sensor

22) Rear number plate with casing

<i>phon</i>	\$	350.00	<i>2005m</i>
	\$	<i>5m</i> 75.00	<i>X</i>
	\$	425.00	

Labour charges

23) To checking wiring

24) to apply anti rust chemical

25) to dismantle and refix exhaust

26) To knock out dent on affected areas and renew parts

27) To putty & respray painting

	\$	120.00	<i>20l</i>
	\$	100.00	<i>60l</i>
<i>nn</i>	\$	250.00	<i>X</i>
	\$	1,800.00	<i>800l</i>
	\$	1,800.00	<i>90d</i>
	\$	4,070.00	