

JA AUTOCARE PTE LTD

Blk 24 Sin Ming Road

#03-35

Singapore 570024

Tel : 94513429

*Not Authorized
L1 Pnp @ 3650h
Perman After Pain
6 days*

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

ESTIMATE

Date: 15.12.2021

vehicle number: SLU 1680C

Model MIT LANCER

Chassis/Eng# :

Accident Date : 15.12.21

PARTS

01) Boot lid	791	B	\$	850.00	✓
02) Boot lid lock assy			\$	450.00	X
03) Boot lid Rubber		ADIPIS	\$	220.00	50km
04) Boot lid Inner Trim Board		NIP	\$	350.00	X
05) boot lid spoiler	(Crown type)	ME	\$	280.00	✓
06) Boot lid centre garnish (Black)		SL	\$	150.00	X
07) MIT emblem	45	ME	\$	75.00	✓
08) Boot Lid hinges @130.00 x2			\$	260.00	X
09) Boot lid centre garnish		SL	\$	180.00	X
10) Rear Panel	425	B	\$	950.00	✓
11) Rear Bumper	708	B	\$	750.00	✓
12) Rear Bumper Reinforcement		NIP	\$	450.00	X
13) Rear Bumper Bracket @\$90.00 X2	C34.50	OLS B	\$	180.00	✓
14) Rear Bumper Retainer @\$120.00 X 2	C59.80	OLS CM	\$	240.00	✓
15) Rear Bumper Lower Reflector @\$90.00 X 2	C38	OLS BR	\$	180.00	✓
16) rear bumper clips		ME	\$	60.00	✓
17) Rear exhaust			\$	850.00	X
18) Rear exhaust chrome pipe		SL	\$	250.00	X
19) Taillamp assy #650.00 x 2	C332	OLS CM	\$	1,300.00	✓
20) Tail Lamp clips		ME	\$	60.00	30 ✓
				\$	8,085.00
				Less 10%	\$ (808.50)
					\$ 7,276.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

JA AUTOCARE PTE LTD

Blk 24 Sin Ming Road

#03-35

Singapore 570024

Tel : 94513429

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

ESTIMATE

Date: 15.12.21

vehicle number: SLU 1680C

Model Mit Lancer

Chassis/Eng# :

Accident Date : 15.12.21

S/Nett

21) Reverse Sensor

22) Rear number plate with casing

<i>Phon</i>	\$	350.00	<i>2005m</i>
	\$	<i>5m</i> 75.00	<i>X</i>
	\$	425.00	

Labour charges

23) To checking wiring

24) to apply anti rust chemical

25] to dismantle and refix exhaust

26) To knock out denst on affected areasand renew parts

27) To putty & respray painting

	\$	120.00	<i>20l</i>
	\$	100.00	<i>60l</i>
<i>nr</i>	\$	250.00	<i>X</i>
	\$	1,800.00	<i>800l</i>
	\$	1,800.00	<i>900l</i>
	\$	4,070.00	

Sub Total

\$ 11,771.50

for JA AUTOCARE PTE LTD



Pre-Report
 Final Report

Date of Report: _____
 Page No. of Report: _____

ADD Fee:

Report Format: _____
 Equip. Serial No.: _____

Day of Report: _____
 Priority No. of Report: _____

Site Insp - 15
 Interview - 5
 Test - 10
 Workshop - 15