



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: TEO KITTY			Ref: CS/ASM21012779/Tty3m4 Date: 14/06/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHD 3769E	Veh. Inspected	SLG 5031Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	S1M03O2M	Excess (\$)	0.00	
Assign From	TEO KITTY	Assign Date	17/12/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	RENAULT KADJAR 1.5 DCI	c.c	1461	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	VF1RFE00556155228	Colour	ORANGE	
Odometer	56990 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/45 R19	GOODYEAR	6 mm	
L/H Front Tyre	225/45 R19	GOODYEAR	6 mm	
R/H Rear Tyre	225/45 R19	GOODYEAR	6 mm	
L/H Rear Tyre	225/45 R19	GOODYEAR	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	10/12/2021	Inspection Date	05/01/2022	
Survey held at	1 Kaki Bukit Avenue 6 #01-08 Autobay@Kaki Bukit			
Repairer	TSL AUTO GARAGE			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	