

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SLG5031Z Renault Kadjar

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy	1052 \$ 1,423.70 <i>de</i>
2	1	Rear bumper lower pad (grey)	698 \$ 980.50 <i>de</i>
3	2	Rear bumper bracket	\$ 145.40 <i>x</i>
4	2	Rear bumper retainer	\$ 152.80 <i>nee</i>
5	2	Rear bumper reflector	\$ <i>4x nn</i> 386.60 <i>RH cont</i> 193.30
6	1	Rear bumper reinforcement	\$ 395.30 <i>bt</i>
7	1	Rear bumper sponge	\$ 179.90 <i>x nn</i>
8	1	Rear bumper tow cover	\$ 98.90 <i>x nn</i>
9	1	Rear bumper inner beam	\$ 331.30 <i>x nn</i>
10	1	Rear tailgate assy	1963.58 \$ 2,662.80 <i>bt</i>
11	1	Rear tailgate centre logo	\$ 126.80 <i>nee</i>
12	1	Rear tailgate inner trim board	380 \$ 494.60 <i>crn</i>
13	2	Rear tailgate inner trim board inner handle	\$ 185.80 <i>x</i>
14	1	Rear no plate inner garnish	\$ 155.60 <i>x</i>
15	1	Rear tailgate lock switch	\$ 267.70 <i>x</i>
16	2	Rear no plate lamp	\$ 120.00 <i>x</i>
17	1	Rear compartment top board	\$ 301.90 <i>x</i>
18	1 set	Rear top compartment foldable board	\$ 280.50 <i>x</i>
19	1	Rear left fender inner garnish	\$ 383.30 <i>x</i>
20	1	Rear right fender inner garnish	\$ 383.30 <i>x</i>
21	1	Rear tool tray	\$ 255.90 <i>x</i>
22	1	Rear Bose sub-woofer	\$ 1,180.20 <i>x</i>
23	1	Rear left fender side protector	\$ 196.30 <i>de</i>
24	1	Rear right fender side protector	\$ 196.30 <i>de</i>
25	1	Rear tailgate 'RENAULT' emblem	60 \$ 106.40 <i>nee</i>
26	1	Rear tailgate 'KADJAR' emblem	60 \$ 106.20 <i>ne</i>
27	1	Rear tailgate weatherstrip	\$ 188.60 <i>cut</i>
28	1	Rear wiper blade assy	\$ 190.40 <i>x</i>
29	1	Rear wiper motor assy	\$ 495.20 <i>x</i>
30	1	Rear floor panel	\$ 1,635.20 <i>x</i>
31	1	Rear tailgate lock	\$ 252.20 <i>bt</i>
32	1	Rear tailgate left taillamp	\$ 686.60 <i>x nn</i>
33	1	Rear tailgate right taillamp	419.58 \$ 686.60 <i>wt</i>
34	1	Rear left taillamp	\$ 786.30 <i>x nn</i>
35	1	Rear right taillamp	548 \$ 786.30 <i>cut</i>
36	1	Rear end lower panel	786.50 \$ 1,298.60 <i>bt</i>
37	1	Rear end lower panel top garnish	\$ 291.60 <i>de</i>
38	1	Rear exhaust muffler assy	\$ 1,797.10 <i>Ry</i>
39	1	Rear exhaust muffler rubber mounting	\$ 66.00 <i>x nn</i>
40	1	Reverse camera	\$450.00 <i>dis</i>
		Less 10%	280. \$ 2,065.87
			\$ 18,592.83

7949.21

7154.30

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SLG5031Z Renault Kadjar

			Estimated Parts Price	
No	Qty	Parts Description		
<u>Special Nett Items</u>				
1	12	Rear bumper clips	\$	60.00 <i>3 over</i> ✓
2	1	Rear windscreen glass sealant	\$	100.00 <i>6 over</i> ✓
3	10	Rear bumper lower pad clips	\$	50.00 <i>1 over</i> ✓
4	16	Rear tailgate inner trim board clips	\$	60.00 <i>2 over</i> ✓
5	6	Rear no plate inner garnish clips	\$	40.00 <i>X n</i>
6	8	Rear left fender inner garnish clips	\$	40.00 <i>X n</i>
7	8	Rear right fender inner garnish clips	\$	40.00 <i>X n</i>
8	6	Rear left fender side protector clips	\$	40.00 <i>1 over</i>
9	6	Rear right fender side protector clips	\$	40.00 <i>1 over</i> ✓
10	1	Rear floor panel insulator pad	\$	180.00 <i>X n</i>
11	1	Rear floor panel sealant	\$	150.00 <i>X n</i>
12	6	Rear end lower panel top garnish clips	\$	30.00 <i>1 over</i> ✓
13	1	Rear end lower panel sealant	\$	140.00 <i>X n</i>
14	4	Rear bumper reverse sensor <i>* to check price</i>	\$	1,200.00 <i>nw</i> ✓ <i>450</i>
15	1	Rear no plate with garnish	\$	100.00 <i>X n</i>
			\$	<u>2,270.00</u>
Total parts			\$	20,862.83 <i>600</i>

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SLG5031Z Renault Kadjar

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts including floor panel.	\$ 1,600.00 700
2	To putty and spray painting rear portion.	\$ 1,600.00 700
3	To check rear lighting and wiring.	\$ 50.00 30
4	To remove and install rear bootlid lock mechanism.	\$ 80.00 60
5	To remove and install rear exhaust muffler assy.	\$ 120.00 60
6	To repair straighten and align both rear fender assy.	\$ 450.00 X 27
7	To remove and install rear seat, inner garnish and trim to facilitate the repair.	\$ 180.00 60
8	To apply anti rust proofing to rear affected area.	\$ 140.00 30
9	To remove and install rear bumper reverse sensor.	\$ 80.00 30
10	To remove and install rear windscreen glass to facilitate the repair.	\$ 140.00 120.
11	Towing service.	\$ 100.00 X 44
Total labour :		\$ 4,540.00 1790

Total parts : \$ 20,862.83
Total labour : \$ 4,540.00
Total repair cost : \$ 25,402.83

7154.30
600
1790

9544.30

c/s 87600, 6 days #

Taufik 97495749
- WP' 5/1/22 @ 130pm.
6 days
4/5 Resurvey after repair
taufik @ whatsapp.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: