

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SLG5031Z Renault Kadjar

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy	\$ 1,423.70 <i>de</i> ✓
2	1	Rear bumper lower pad (grey)	\$ 980.50 <i>de</i> ✓
3	2	Rear bumper bracket	\$ 145.40 ✕
4	2	Rear bumper retainer	\$ 152.80 <i>nei</i> ✓
5	2	Rear bumper reflector	\$ <i>LHx</i> 386.60 <i>RHcarb</i> ✓
6	1	Rear bumper reinforcement	\$ 395.30 <i>bt</i> ✓
7	1	Rear bumper sponge	\$ 179.90 ✕
8	1	Rear bumper tow cover	\$ 98.90 ✕
9	1	Rear bumper inner beam	\$ 331.30 ✕
10	1	Rear tailgate assy	\$ 2,662.80 <i>bt</i> ✓
11	1	Rear tailgate centre logo	\$ 126.80 <i>nei</i> ✓
12	1	Rear tailgate inner trim board	\$ 494.60 <i>cra</i> ✓
13	2	Rear tailgate inner trim board inner handle	\$ 185.80 ✕
14	1	Rear no plate inner garnish	\$ 155.60 ✕
15	1	Rear tailgate lock switch	\$ 267.70 ✕
16	2	Rear no plate lamp	\$ 120.00 ✕
17	1	Rear compartment top board	\$ 301.90 ✕
18	1 set	Rear top compartment foldable board	\$ 280.50 ✕
19	1	Rear left fender inner garnish	\$ 383.30 ✕
20	1	Rear right fender inner garnish	\$ 383.30 ✕
21	1	Rear tool tray	\$ 255.90 ✕
22	1	Rear Bose sub-woofer	\$ 1,180.20 ✕
23	1	Rear left fender side protector	\$ 196.30 <i>de</i> ✓
24	1	Rear right fender side protector	\$ 196.30 <i>de</i> ✓
25	1	Rear tailgate 'RENAULT' emblem	\$ 106.40 <i>nei</i> ✓
26	1	Rear tailgate 'KADJAR' emblem	\$ 106.20 <i>ne</i> ✓
27	1	Rear tailgate weatherstrip	\$ 188.60 <i>cut</i> ✓
28	1	Rear wiper blade assy	\$ 190.40 ✕
29	1	Rear wiper motor assy	\$ 495.20 ✕
30	1	Rear floor panel	\$ 1,635.20 ✕
31	1	Rear tailgate lock	\$ 252.20 <i>bt</i> ✓
32	1	Rear tailgate left taillamp	\$ 686.60 ✕
33	1	Rear tailgate right taillamp	\$ 686.60 <i>wt</i> ✓
34	1	Rear left taillamp	\$ 786.30 <i>xm</i> ✓
35	1	Rear right taillamp	\$ 786.30 <i>out</i> ✓
36	1	Rear end lower panel	\$ 1,298.60 <i>bt</i> ✓
37	1	Rear end lower panel top garnish	\$ 291.60 <i>de</i> ✓
38	1	Rear exhaust muffler assy	\$ 1,797.10 <i>Ry</i> ✓
39	1	Rear exhaust muffler rubber mounting	\$ 66.00 ✕
40	1	Reverse camera	\$ 20,658.70
		Less 10%	\$ 2,065.87
			\$ 18,592.83

#450.00 *dis*✓
280.

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SLG5031Z Renault Kadjar

			Estimated Parts Price	
No	Qty	Parts Description		
<u>Special Nett Items</u>				
1	12	Rear bumper clips	\$	60.00 3over ✓
2	1	Rear windscreen glass sealant	\$	100.00 6over ✓
3	10	Rear bumper lower pad clips	\$	50.00 10over ✓
4	16	Rear tailgate inner trim board clips	\$	60.00 20over ✓
5	6	Rear no plate inner garnish clips	\$	40.00 X un
6	8	Rear left fender inner garnish clips	\$	40.00 X un
7	8	Rear right fender inner garnish clips	\$	40.00 X un
8	6	Rear left fender side protector clips	\$	40.00 10over
9	6	Rear right fender side protector clips	\$	40.00 10over ✓
10	1	Rear floor panel insulator pad	\$	180.00 X un
11	1	Rear floor panel sealant	\$	150.00 X un
12	6	Rear end lower panel top garnish clips	\$	30.00 10over ✓
13	1	Rear end lower panel sealant	\$	140.00 X
14	4	Rear bumper reverse sensor	\$	1,200.00 n/w ✓
15	1	Rear no plate with garnish	\$	100.00 X
			\$	<u>2,270.00</u>
Total parts			\$	20,862.83

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SLG5031Z Renault Kadjar

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts including floor panel.	\$ 1,600.00 8.00
2	To putty and spray painting rear portion.	\$ 1,600.00 8.00
3	To check rear lighting and wiring.	\$ 50.00 3.0
4	To remove and install rear bootlid lock mechanism.	\$ 80.00 6.0
5	To remove and install rear exhaust muffler assy.	\$ 120.00 6.0
6	To repair straighten and align both rear fender assy.	\$ 450.00 X
7	To remove and install rear seat, inner garnish and trim to facilitate the repair.	\$ 180.00 6.0
8	To apply anti rust proofing to rear affected area.	\$ 140.00 3.0
9	To remove and install rear bumper reverse sensor.	\$ 80.00 3.0
10	To remove and install rear windscreen glass to facilitate the repair.	\$ 140.00 12.0
11	Towing service.	\$ 100.00 X
Total labour :		\$ 4,540.00

Total parts : \$ 20,862.83
Total labour : \$ 4,540.00
Total repair cost : \$ 25,402.83

Taufik 97495749
 - WP' 5/1/22 @ 1300pm.
 6 days
 A/S Resurvey after repair -
 Taufik @ WhatsApp.com.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: